

**2016 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 4533
CSAH 77 over MC RY**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: New Brighton

STATE: Minnesota

Date of Inspection: 11/16/2016

Equipment Used:

Owner: County Highway Agency

Inspected By: Bodelson, Dan

Report Written By: Dan Bodelson
Report Reviewed By: Nicklaus Fischer
Final Report Date: 12/02/2016




Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
STRUCTURE INVENTORY	3
ROUTINE INSPECTION DATA	4
ELEMENTS	8
PICTURES	13
MAINTENANCE	24
STRUCTURAL ASSESSMENT REPORT - ROUTINE	25

Minnesota Structure Inventory Report

Bridge ID: 4533

CSAH 77

over MC RY

Date: 12/02/2016

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City New Brighton			
Township			
Desc. Loc. 0.2 MI E OF JCT CSAH 45			
Sect., Twp., Range 29 - 030N - 23W			
Latitude		Sec	
Deg 45	Min 3	36.49	
Longitude		Sec	
Deg 93	Min 11	43.43	
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		1926	
MN Year Reconstructed		1973	
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 3 - COUNTY			
Date Opened to Traffic			
On-Off System		1 - ON	
Legislative District 50B			
ABC Suitable			

STRUCTURE	
Service On	5 - Highway-pedestrian
Service Under	2 - Railroad
Main Span Type	5 - Prestress or Precast 11 - Channel Span
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	0
Culvert Type	
Barrel Length	ft.
Cantilever ID	

NUMBER OF SPANS			
MAIN:	3	APPR:	0
		TOTAL:	3
Main Span Length	22.0	ft.	
Structure Length	65.9	ft.	
Deck Width (Out-to-Out)	63.5	ft.	
Deck Material 2 - Concrete Precast Panels			
Wear Surf Type 6 - Bituminous			
Wear Surf Install Year			
Wear Course/Fill Depth	0.20	ft.	
Deck Membrane 0 - None			
Deck Rebars 0 - None			
Deck Rebars Install Year			
Structure Area (Out-to-Out)	4185	sq. ft.	
Roadway Area (Curb-to-Curb)	3423	sq. ft.	
Sidewalk Width	Lt 4.50	ft.	Rt 4.50 ft.
Curb Height	Lt 0.75	ft.	Rt 0.75 ft.
Rail Type	Lt 14		Rt 14

ROADWAY			
Bridge Match ID (TIS) 0			
Roadway O/U Key Route On Structure			
Route Sys 04 - CSAH		Number 77	
Roadway Name or Description			
CSAH 77			
Level of Service 1 - MAINLINE			
Roadway Type 2 - 2-way traffic			
Control Section (TH Only)			
Reference Point 001+00.820			
Detour Length	5.0	mi	
Lanes	On 4	Under 0	
	ADT 8366	Year 2008	
HCACT	0	ADTT 0	%
Functional Class 16 - Urban - Minor Arterial			

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	52.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.	51.9	ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	43.0	ft.	
Bridge Roadway Width	52.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	1 - CONC
(Material/Type)	5 - U TYPE ABUT
Pier Foundation	1 - CONC
(Material/Type)	3 - FTG PILE
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	2 - Vehicle & Semi (Type R12-5)
Traffic	0 - Not Required
Horizontal	1 - Object Markers
Vertical	0 - Not Required

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	Y
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	43.6
Routine Inspection Date	11/16/2016
Routine Inspection Frequency	12
Inspector Name	CO Bridge
Status	P - Posted for Load

NBI CONDITION RATINGS	
Deck	5 - Fair Condition
Unsound Deck %	
Superstructure	4 - Poor Condition
Substructure	5 - Fair Condition
Channel	N - Not Applicable
Culvert	N - Not Applicable

NBI APPRAISAL RATINGS	
Structure Evaluation	4
Deck Geometry	4
Underclearances	3
Water Adequacy	N - Not Applicable
Approach Alignment	6 - Equal to present minimum

SAFETY FEATURES	
Bridge Railing	1 - MEETS STANDARDS
GR Transition	0 - SUBSTANDARD
Appr. Guardrail	1 - MEETS STANDARDS
GR Termini	1 - MEETS STANDARDS

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical	N		
Underwater	N		
Pinned Asbly.	N		
Spec. Feat.			

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening		sq. ft.	
Navigation Control N - Not applicable, no waterw			
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code A - NON WATER' Year			

CAPACITY RATINGS			
Design Load	5 - HS 20		
Operating Rating	1 - LF (LF)	HS 42.2	
Inventory Rating	1 - LF (LF)	HS 25.4	
Posting VEH:	26	SEMI: 40	DBL: 40
Rating Date 06/10/2011			

Minnesota Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

Minnesota Structure Inventory Report

Bridge ID: 4533

CSAH 77 over MC RY

Date: 11/08/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
Agency Br. No. Crew District 05 Maint. Area County 062 - Ramsey City New Brighton Township Desc. Loc. 0.2 MI E OF JCT CSAH 45 Sect., Twp., Range 29 - 030N - 23W Latitude 45 ° 3 ' 36.49 '' Longitude 93 ° 11 ' 43.43 '' Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 1926 MN Year Reconstructed 1973 FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 3 - COUNTY Date Opened to Traffic On - Off System 1 - ON Legislative District 50B Potential ABC 2 - N/A	Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 04 - CSAH Number 77 Roadway Name or Description CSAH 77 Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point 001+00.820 Detour Length 5.0 mi. Lanes ON 4 UNDER 0 ADT 8366 YEAR 2008 HCA DT ADTT % Functional Class 16 - Urban - Minor Arterial	Userkey 102 Structurally Deficient Y Functionally Obsolete N Sufficiency Rating 43.6 Routine Inspection Date 11/16/2016 Routine Inspection Frequency 12 Inspector Name Bodelson, Dan Status P - Posted for Load																				
	+ RDWY DIMENSIONS +	+ NBI CONDITION RATINGS +																				
	If Divided NB-EB SB-WB Roadway Width 52.00 ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. 51.9 ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 43.0 ft. Bridge Roadway Width 52.0 ft. Median Width On Bridge ft.	Deck 5 Unsound Deck % Superstructure 4 Substructure 5 Channel N Culvert N																				
+ STRUCTURE +	+ MISC. BRIDGE DATA +	+ NBI APPRAISAL RATINGS +																				
Service On 5 - Highway-pedestrian Service Under 2 - Railroad Main Span Type 5 - Prestress or Precast Main Span Design 11 - Channel Span Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 0 Culvert Type Barrel Length Cantilever ID Number of Spans MAIN: 3 APPR: 0 TOTAL: Main Span Length 22.0 ft. Structure Length 65.9 ft. Deck Width (Out-to-Out) 63.5 ft. Deck Material 2 - Concrete Precast Panels Wear Surf Type 6 - Bituminous Wear Surf Install Year Wear Course/Fill Depth 0.20 ft. Deck Membrane 0 - None Deck Rebars 0 - None Deck Rebars Install Year Structure Area (Out-to-Out) 4185 sq. ft. Roadway Area (Curb-to-Curb) 3423 sq. ft. Sidewalk Width 50A. Lt 4.50 ft. 50B. Rt 4.50 ft. Curb Height Lt 0.75 ft. Rt 0.75 ft. Rail Type Lt 14 Rt 14	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID Abutment Foundation (Material/Type) 1 - CONC 5 - U TYPE ABUT Pier Foundation (Material/Type) 1 - CONC 3 - FTG PILE Historic Status 5 - Not eligible	Structure Evaluation 4 Deck Geometry 4 Underclearances 3 Waterway Adequacy N Approach Alignment 6																				
	+ PAINT +	+ SAFETY FEATURES +																				
	Year Painted Unsound Paint % Painted Area sq. ft. Primer Type Finish Type	Bridge Railing 1 - MEETS STANDARDS GR Transition 0 - SUBSTANDARD Appr. Guardrail 1 - MEETS STANDARDS GR Termini 1 - MEETS STANDARDS																				
	+ BRIDGE SIGNS +	+ IN DEPTH INSP. +																				
	Posted Load 2 - Vehicle & Semi (Type R12-5) Traffic 0 - Not Required Horizontal 1 - Object Markers Vertical 0 - Not Required	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Underwater</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Pinned Asbly.</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	Frac. Critical	N			Underwater	N			Pinned Asbly.	N			Spec. Feat.			
	Y/N	Freq	Date																			
Frac. Critical	N																					
Underwater	N																					
Pinned Asbly.	N																					
Spec. Feat.																						
		+ WATERWAY +																				
		Drainage Area (sq. mi.) Waterway Opening (sf.) Navigation Control N - Not applicable, no Pier Protection Nav. Clr. (ft.) Vert. 0.0 Horiz. 0.0 Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code A - NON Year																				
		+ CAPACITY RATINGS +																				
		Design Load 5 - HS 20 Operating Rating 2 - HS TRUCK 42.2 Inventory Rating 2 - HS TRUCK 25.4 Posting VEH: 26 SEMI: 40 DBL: 40 Rating Date 06/10/2011 Overweight Permit Codes A N - N/A B N - N/A C N - N/A																				

MINNESOTA BRIDGE INSPECTION REPORT

12/02/2016

BRIDGE 4533 CSAH 77 OVER MC RY

ROUTINE INSP. DATE: 11/16/2016

County: Ramsey	Location: 0.2 MI E OF JCT CSAH 45	Length: 65.9 ft.
City: New Brighton	Route: 04 - CSAH 77 Ref. Pt.: 001+00.820	Deck Width: 63.5 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 3423 sq. ft. / %
Section: 29 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 5 - Prestressed Concrete 2 -	Local Agency Bridge Nbr.:	Culvert: N/A
List: Stringer/Multi-beam or Girder		Postings: 26 40 40
NBI Deck: 5 Super: 4 Sub: 5 Chan: N Culv: N		
	Open, Posted, Closed: P - Posted for Load	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 6 Waterway: N		Unofficial Structurally Deficient Y
Required Bridge Signs - Load Posting: 2 - Vehicle & Semi (Type R12-5)	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 1 - Object Markers	Vertical: 0 - Not Required	Unofficial Sufficiency Rating 43.6

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
013	Bituminous Overlay (Concrete Deck)	2	Routine	11/16/2016	4187 SF	0	0	4187	0	0
			Routine	11/19/2015	4187 SF	0	0	4187	0	0

Notes: [2010-2015] There is moderate to major longitudinal and transverse cracking of bituminous overlay.
 [2009-2015] There is deck leakage @ deck joints (transverse cracking) & along pre-cast sections- 6 on each side of centerline (longitudinal cracking).
 Milled an average of 1 1/4" and paved 0.20' in July 2007.
 Difficult to determine the condition of concrete deck due to the bituminous overlay.

205	Reinforced Concrete Column	2	Routine	11/16/2016	10 EA	0	7	3	0	N/A
			Routine	11/19/2015	10 EA	0	7	3	0	N/A

Notes: [2015] The north side of column #3 & #5 at the top has exposed re-bar with corrosion.
 [2013-2015] Minor spalls are present. The north side of #7 column at the top has exposed re-bar with corrosion.
 [2003-2015] Numerous minor horizontal & vertical cracking. Rebar and form tie corrosion is present on columns.

215	Reinforced Concrete Abutment	2	Routine	11/16/2016	128 LF	0	54	74	0	N/A
			Routine	11/19/2015	128 LF	0	54	74	0	N/A

Notes: [2015] There is spall at the NW corner abutment back wall.
 [2014-2015] There is a major 1" delamination on the top of the west abutment between channels 5 & 15.
 [2014-2015] There is a major spall at west abutment below #16 channel.
 [2013-2015] The west abutment contains minor to moderate spalls throughout. There is a major spall at west abutment below #5 channel.
 [2010-2015] The east abutment contains major spalls at channel #5, channels #3 & #16 at construction joints.
 [2008-2015] There are 2 moderate vertical cracks in each abutment with delamination at the construction joints.
 [2003-2015] There are 36 LF of horizontal cracks on east abut. & 35 LF on west abut. 4" below the abutment seat. Scaling at abutment seats. Hairline cracks outside edges of SE & SW corners of bridge seats 1994-2015. Sealed in 1982. Reappeared in 1983. Visible 1983-2015.
 [2013-2014] There is delamination at the NW corner abutment back wall.

220	Reinforced Concrete Footing	2	Routine	11/16/2016	10 EA	0	10	0	0	N/A
			Routine	11/19/2015	10 EA	0	10	0	0	N/A

Notes: [2015] Minor spalls are present with numerous minor horizontal & vertical cracking.

234	Reinforced Concrete Pier Cap	2	Routine	11/16/2016	128 LF	0	54	74	0	N/A
			Routine	11/19/2015	128 LF	0	54	74	0	N/A

Notes: [2014-2015] There is moderate delamination on the north construction joint of the east pier cap.
 [2009-2015] There is moderate vertical cracking at construction joints. There are moderate spalls underneath side of concrete caps. There are 36 LF of horizontal cracking on each pier cap.

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
333	Masonry, Other or Combination Material Railing	2	Routine	11/16/2016	200 LF	0	182	18	N/A	N/A
			Routine	11/19/2015	200 LF	0	182	18	N/A	N/A

Notes: [2015] 18 LF in CS 3 & 182 LF in CS 2.

[2015] 75% of concrete posts have moderate spalls & delamination with corrosion present.

[2015] There is moderate spalls on #9, #11 & #12 posts on the south side.

[2014-2015] There is longitudinal cracking on top of railing the east 1/2 of the north side railing.

[2009-2015] There is longitudinal cracking on top of railing the west 1/2 of the north side railing.

[2006-2015] There is major delamination with section loss south side on the #5 post.

[2004-2015] Concrete parapet needs repair & paint. Galvanizing protection is chalking on metal railing.

[2009-2014] There is moderate delamination of #9, #11 & #12 posts on the south side.

[2004-2014] 50% of concrete posts have moderate spalling & delamination with corrosion present.

Railing is a combination concrete parapet & metal railing.

375	Pre-cast Concrete Channel	2	Routine	11/16/2016	1320 LF	0	138	980	202	N/A
			Routine	11/19/2015	1320 LF	0	138	980	202	N/A

Notes: [2015] Spans 1,2,3,6,7,8,9,10,11,14,15,18,19 & 20 have major spalls with exposed rebar and some significant section loss. Spans 4,5,12,13,16 & 17 have major delamination.

[2014] West span has major delamination on channels #1, #10, #12, & #14.

[2014] Center span has major delamination on channels #2, #6, & #9.

[2014] East span has major delamination on channels #1, #4, #5, #9, #12, & #14.

[2013-2014] West span has major spalls w/ exposed rebar on channels #3, #7, #9, #11, #15, #16, #19, #21. Major effluence on channel #4

[2013-2014] Center span has major spalls w/ exposed rebar on channels #3, #7, #10, #15, #19, #21

[2013-2014] East span has major spalls w/ exposed rebar on channels #3,#8, #10, #11, #19, #21

[2009-2014] Numerous minor shear & flexure cracking exist throughout all pre-cast channel spans. Also contains some leaching through from the deck. 100% in condition state 3.

Span #1

[2013-2014] Channel #1, #10, #14, #15, #18 & #20 have longitudinal cracking w/corrosion 100% length.

#14 & #15 have 8' of delamination with section loss.

Chan. #2 & #3 has exposed re-bar w/section loss 100% length. Also leaching through from the deck.

Chan. #5 has 4' long. crack. w/corr. Chan. #4, #6, #7 & #12 has long. crack. w/corr. 50% length.

Chan. #8 & #9 has long. crack. w/corr. 100% length. Chan. #8 has 4' exposed re-bar w/ sect. loss.

Chan. #8 & #10 have 2' of delamination w/ sect. loss @ pier. Channel #14 & #15 have 4' delamination @ abutment. Chan. #18 has 6' of delam. w/ sect. loss.

Chan. #13 has a 4' longitudinal crack & 6" moderate spall w/corr. @ abutment.

Chan. #16 - 2' & #17 - 1' of long. crack. w/corrosion.

Chan. #11, #18 & #19 have long. cracking 100% length with 50% delam. & section loss.

Span #2

[2011-2014] Chan. #2 & #3 have cracking w/corr. 100% length & delam. w/ exposed re-bar & sect. loss 75% L.

Chan. #1, #4, #5, #16 & #17 have 2' crack. w/corr. @ each pier. Chan. #8 has 4' crack w/corr. @ west pier & 2' crack. w/corr. @ east pier.

Chan. #6, #7, #11, #12 & #13 have long. crack. w/corr. 50% length. #7 has 2' delamination w/section loss.

Chan. #9 & #10 have delam. w/ exposed re-bar & sect. loss 50% L.

Chan. #14 & #15 have cracking 100% length. Chan. #14 & #15 also has exposed re-bar & sect. loss 75% length.

Chan. #18, #19 & #20 cracking w/corr. 100% L. Chan #19 has delam. w/ exposed re-bar & sect. loss 100% length.

Span #3

[2011-2014] Chan. #7, #10, #13, #15, #16, #17 has long. crack. w/corr. 50% length.

Chan. #1, #2 & #3 have long. crack. w/corr. 75% length.

Channel #2,#3,#9,#10 & #11 have 6' of delamination w/ exposed re-bar & section loss @ east abutment.

Chan. #4 & #5 have 50% long. crack. w/corrosion. #4 has 2' delam. @ abut.

Chan. #6 has 1' long. crack. w/corr. @ pier.

Chan. #8, #18, #19 & #20 have long crack. w/corr. 100% length. Channel #19 has 8' of delam. w/ exposed re-bar & sect. loss.

Chan. #14 has a 1' spall & 6' longitudinal crack with corrosion.

387	Reinforced Concrete Wingwall	2	Routine	11/16/2016	4 EA	0	3	1	0	N/A
			Routine	11/19/2015	4 EA	0	3	1	0	N/A

Notes: [2013-2015] Minor spalls present on all concrete wingwalls.

[2008-2015] There is a major spall at the NW corner bridge seat.

[2003-2015] There is minor cracking with evidence of corrosion at the SW & NW corners.

[2005-2015] There also is some cracking all corners at back wall bridge seats.

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
407	Bituminous Approach Roadway	2	Routine	11/16/2016	2 EA	0	2	0	0	N/A
			Routine	11/19/2015	2 EA	0	2	0	0	N/A
Notes: [2010-2015] Moderate cracking with settlement present at both ends. [2007] New mill & overlay. Milled an average of 1 1/4" and paved 0.20' in July 2007.										
964	Critical Finding Smart Flag	2	Routine	11/16/2016	1 EA	1	0	N/A	N/A	N/A
			Routine	11/19/2015	1 EA	1	0	N/A	N/A	N/A
Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.										
965	Concrete Shear Cracking Smart Flag	2	Routine	11/16/2016		0	0	0	0	N/A
			Routine	11/19/2015		0	0	0	0	N/A
Notes:										
981	Signing	2	Routine	11/16/2016	1 EA	1	0	0	0	0
			Routine	11/19/2015	1 EA	1	0	0	0	0
Notes: [2003-2015] Horizontal clearance signs are in place. Load posting signs are in place.										
982	Approach Guardrail	2	Routine	11/16/2016	1 EA	0	1	0	N/A	N/A
			Routine	11/19/2015	1 EA	0	1	0	N/A	N/A
Notes: [2007-2015] There is moderate damage to all four segments but still functions as intended.										
984	Deck & Approach Drainage	2	Routine	11/16/2016	1 EA	0	1	0	N/A	N/A
			Routine	11/19/2015	1 EA	0	1	0	N/A	N/A
Notes: [2005-2015] Drains off the bridge east and west. Drainage is operating properly.										
985	Slopes & Slope Protection	2	Routine	11/16/2016	1 EA	0	1	0	N/A	N/A
			Routine	11/19/2015	1 EA	0	1	0	N/A	N/A
Notes: [2009-2015] Slope protection has moderate deterioration. Grouted riprap has moderate cracking and settlement. [2005-2015] Minor to moderate erosion at the SW & NW corners. Slope protection consists of grouted rip rap.										
986	Curb & Sidewalk	2	Routine	11/16/2016	1 EA	0	1	0	N/A	N/A
			Routine	11/19/2015	1 EA	0	1	0	N/A	N/A
Notes: [2014-2015] There is a 2" settlement of walk @ SE corner of bridge. [2013-2015] Major horizontal crack w/ spalling along face of north curb (44') [2012-2015] Minor cracking and moderate spalling are present. [2004-2015] Settlement of sidewalk at the NE & NW corners have been patched with bituminous.										
988	Miscellaneous Items	2	Routine	11/16/2016		0	0	0	N/A	N/A
			Routine	11/19/2015		0	0	0	N/A	N/A
Notes:										

General Notes: 2016 Bridge safety inspection was completed by Dan Bodelson, Brian Essler & Rob Gaetz on 11/16/2016.
2015 Bridge safety inspection was completed by Brian Essler & Dan Bodelson on 11/19/2015.
2014 Bridge safety inspection was completed by Dan Bodelson, Brian Essler & Randy Bussiere on 11/21/2014.
2013 Bridge safety inspection was completed by Dan Bodelson & Brian Essler on 11/07/2013.
2012 Bridge safety inspection was completed by B. Wieman on 11/26/2012.
2011 Bridge safety inspection was conducted by B. Wieman on 11/9/2011.
2010 Bridge safety inspection by B. Wieman & D. Bodelson on 11/02/2010.

MINNESOTA BRIDGE INSPECTION REPORT

12/02/2016

Inspector: CO Bridge

BRIDGE 4533 CSAH 77 OVER MC RY

County: Ramsey	Location: 0.2 MI E OF JCT CSAH 45	Length: 65.9 ft.
City: New Brighton	Route: 04 - CSAH 77 Ref. Pt.: 001+00.820	Deck Width: 63.5 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 3423 sq. ft. / %
Section: 29 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 5 - Prestressed Concrete 2 - List: Stringer/Multi-beam or Girder	Local Agency Bridge Nbr.:	Culvert: N/A
NBI Deck: 5 Super: 4 Sub: 5 Chan: N Culv: N		Postings: 26 40 40

Open, Posted, Closed: P - Posted for Load
MN Scour Code: A - NON WATERWAY

Appraisal Ratings - Approach: 6 Waterway: N	Unofficial Structurally Deficient Y
Required Bridge Signs - Load Posting: 2 - Vehicle & Semi (Type R12-5)	Unofficial Functionally Obsolete N
Horizontal: 1 - Object Markers	Unofficial Sufficiency Rating 43.6
Vertical: 0 - Not Required	

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
----------	--------------	-------------	------------	----------	----------	----------	----------	----------

16	Reinforced Concrete Top Flange	Routine	11/16/2016	4185 SF	0	418	3055	712
		Migrated Values		4185 SF	0	418	3055	712

Notes: [2016] Migrator assumed CS1.
 [2016] Extensive delamination & spalling, exposed rebar with section loss.
 [2016] 10% - 418 SF CS2, 73% - 3055 SF CS3, 17% - 712 SF CS4 - see attached file.

510	Wearing Surfaces	Routine	11/16/2016	3423 SF	3081	0	342	0
		Migrated Values		3423 SF	3081	0	342	0

Notes: Bituminous Overlay Notes: [2010-2016] There is moderate to major longitudinal and transverse cracking of bituminous overlay.
 [2009-2016] There is deck leakage @ deck joints (transverse cracking) & along pre-cast sections- 6 on each side of centerline (longitudinal cracking).
 Milled an average of 1 1/4" and paved 0.20' in July 2007.
 Difficult to determine the condition of concrete deck due to the bituminous overlay.

BRIDGE 4533 CSAH 77 OVER MC RY

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
110	Reinforced Concrete Open Girder/Beam	Routine	11/16/2016	2640 LF	0	248	1936	456
		Migrated Values		2640 LF	0	248	1936	456
<p>Notes: [2016] Migrator estimated the quantity of the channel spans. Verify the quantity by multiplying the number of vertical beams (2 beams per precast section) by the deck length. [2016] 1320 ft. of precast sections x 2 = 2640 ft. beams. [2016] 10% - 248ft. CS2, 73% - 1936 ft., CS3, 17% - 456 ft. - CS4 - see attached file. [2015-2016] Spans 1,2,3,6,7,8,9,10,11,14,15,18,19 & 20 have major spalls with exposed rebar and some significant section loss. Spans 4,5,12,13,16 & 17 have major delamination. [2014-2016] West span has major delamination on channels #1, #10, #12, & #14. [2014-2016] Center span has major delamination on channels #2, #6, & #9. [2014-2016] East span has major delamination on channels #1, #4, #5, #9, #12, & #14. [2013-2016] West span has major spalls w/ exposed rebar on channels #3, #7, #9, #11, #15, #16, #19, #21. Major effluence on channel #4 [2013-2016] Center span has major spalls w/ exposed rebar on channels #3, #7, #10, #15, #19, #21 [2013-2016] East span has major spalls w/ exposed rebar on channels #3,#8, #10, #11, #19, #21 [2009-2014] Numerous minor shear & flexure cracking exist throughout all pre-cast channel spans. Also contains some leaching through from the deck.100% in condition state 3.</p> <p>Span #1 [2013-2014] Channel #1, #10, #14, #15, #18 & #20 have longitudinal cracking w/corrosion 100% length. #14 & #15 have 8' of delamination with section loss. Chan. #2 & #3 has exposed re-bar w/section loss 100% length. Also leaching through from the deck. Chan. #5 has 4' long. crack. w/corr. Chan. #4, #6, #7& #12 has long. crack. w/corr. 50% length. Chan. #8 & #9 has long. crack. w/corr. 100% length. Chan. #8 has 4' exposed re-bar w/ sect. loss. Chan. #8 10 have 2' of delamination w/ sect. loss @ pier. Channel #14 15 have 4' delamination @ abutment. Chan. #18 has 6' of delam. w/ sect. loss. Chan. #13 has a 4' longitudinal crack & 6" moderate spall w/corr. @ abutment. Chan. #16 - 2' & #17 - 1' of long. crack. w/corrosion. Chan. #11, #18 & #19 have long. cracking 100% length with 50% delam. & section loss.</p> <p>Span #2 [2011-2014] Chan. #2 & #3 have cracking w/corr. 100% length & delam. w/ exposed re-bar & sect. loss 75% L. Chan. #1, #4, #5, #16 & #17 have 2' crack. w/corr. @ each pier. Chan. #8 has 4' crack w/corr. @ west pier & 2' crack. w/corr. @ east pier. Chan. #6, #7, #11, #12 & #13 have long. crack. w/corr. 50% length. #7 has 2' delamination w/section loss. Chan. #9 & #10 have delam. w/ exposed re-bar & sect. loss 50% L. Chan. #14 & #15 have cracking 100% length. Chan. #14 & #15 also has exposed re-bar & sect. loss 75% length. Chan. #18, #19 & #20 cracking w/corr. 100% L. Chan #19 has delam. w/ exposed re-bar & sect. loss 100% length.</p> <p>Span #3 [2011-2014] Chan. #7, #10, #13, #15, #16, #17 has long. crack. w/corr. 50% length. Chan. #1, #2 & #3 have long. crack. w/corr. 75% length. Channel #2,#3,#9,#10 & #11 have 6' of delamination w/ exposed re-bar & section loss @ east abutment. Chan. #4 & #5 have 50% long. crack. w/corrosion. #4 has 2' delam. @ abut. Chan. #6 has 1' long. crack. w/corr. @ pier. Chan. #8, #18, #19 & #20 have long crack. w/corr. 100% length. Channel #19 has 8' of delam. w/ exposed re-bar & sect. loss. Chan. #14 has a 1' spall & 6' longitudinal crack with corrosion.</p>								
205	Reinforced Concrete Column	Routine	11/16/2016	10 EA	0	6	4	0
		Migrated Values		10 EA	0	6	4	0
<p>Notes: [2016] Major delamination on column # 6, move to CS3 [2015-2016] The north side of column #3 & #5 at the top has exposed re-bar with corrosion. [2013-2016] Minor spalls are present. The north side of #7 column at the top has exposed re-bar with corrosion. [2003-2016] Numerous minor horizontal & vertical cracking. Rebar and form tie corrosion is present on columns.</p>								

BRIDGE 4533 CSAH 77 OVER MC RY

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
215	Reinforced Concrete Abutment	Routine	11/16/2016	196 LF	0	105	91	0
		Migrated Values		196 LF	0	105	91	0
<p>Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:0 CS2:30 CS3:10 CS4:0). [2016] 17' on all 4 wingwalls with 128' of abutment = 196 ft. Total. [2016] 3 wingwalls @ 17' = 51' + 54' abut. = 105 ft. CS2 - 1 wingwall @ 17' with 74' abut. = 91 ft. CS3. [2016] There is spall at the NW corner abutment back wall. [2014-2016] There is a major 1" delamination on the top of the west abutment between channels 5 & 15. [2014-2016] There is a major spall at west abutment below #16 channel. [2013-2016] The west abutment contains minor to moderate spalls throughout. There is a major spall at west abutment below #5 channel. [2010-2016] The east abutment contains major spalls at channel #5, channels #3 & #16 at construction joints. [2008-2016] There are 2 moderate vertical cracks in each abutment with delamination at the construction joints. [2003-2016] There are 36 LF of horizontal cracks on east abut. & 35 LF on west abut. 4" below the abutment seat. Scaling at abutment seats. Hairline cracks outside edges of SE & SW corners of bridge seats 1994-2015. Sealed in 1982. Reappeared in 1983. Visible 1983-2015. [2013-2016] There is delamination at the NW corner abutment back wall.</p> <p>Wingwall notes: [2013-2015] Minor spalls present on all concrete wingwalls. [2008-2015] There is a major spall at the NW corner bridge seat. [2003-2015] There is minor cracking with evidence of corrosion at the SW & NW corners. [2005-2015] There also is some cracking all corners at back wall bridge seats.</p>								
220	Reinforced Concrete Pile Cap/Footing	Routine	11/16/2016	106 LF	0	106	0	0
		Migrated Values		106 LF	0	106	0	0
<p>Notes: [2016] Migrator assumed 10LF per EA quantity, a total of 100 LF. [2016] 9.5' between 5 piers = 4 x 9.5' = 38' + 7.5' on north & south ends = 53 ft. x 2 (east & west piers) = 106' total CS 2 [2015-2016] Minor spalls are present with numerous minor horizontal & vertical cracking.</p>								
234	Reinforced Concrete Pier Cap	Routine	11/16/2016	128 LF	0	54	74	0
		Migrated Values		128 LF	0	54	74	0
<p>Notes: [2014-2016] There is moderate delamination on the north construction joint of the east pier cap. [2009-2016] There is moderate vertical cracking at construction joints. There are moderate spalls underneath side of concrete caps. There are 36 LF of horizontal cracking on each pier cap.</p>								
330	Metal Bridge Railing	Routine	11/16/2016	200 LF	0	200	0	0
		Migrated Values		200 LF	0	200	0	0
<p>Notes: [2016] Migrator assumed concrete/metal combination type rail. [2016] 200 ft. CS 2 for Metal Bridge Rail. [2016] Minor chalking & fading of finish coat. [2015] 18 LF in CS 3 & 182 LF in CS 2. [2015-2016] 75% of concrete posts have moderate spalls & delamination with corrosion present. [2015-2016] There is moderate spalls on #9, #11 & #12 posts on the south side. [2014-2016] There is longitudinal cracking on top of railing the east 1/2 of the north side railing. [2009-2016] There is longitudinal cracking on top of railing the west 1/2 of the north side railing. [2006-2016] There is major delamination with section loss south side on the #5 post. [2004-2016] Concrete parapet needs repair & paint. Galvanizing protection is chalking on metal railing. [2009-2014] There is moderate delamination of #9, #11 & #12 posts on the south side. [2004-2014] 50% of concrete posts have moderate spalling & delamination with corrosion present. Railing is a combination concrete parapet & metal railing.</p>								
515	Steel Protective Coating	Routine	11/16/2016	260 SF	0	260	0	0
		Migrated Values		260 SF	0	260	0	0
<p>Notes: [2016] Migrator assumed CS1 and a quantity of 999 SF. [2016] 200 LF x 1.3' high = 260 SF [2016] Minor chalking & fading of finish coat.</p>								

BRIDGE 4533 CSAH 77 OVER MC RY

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
331	Reinforced Concrete Bridge Railing	Routine	11/16/2016	200 LF	0	100	100	0
		Migrated Values		200 LF	0	100	100	0
<p>Notes: [2016] Migrator assumed concrete/metal combination type rail. [2016] 100 LF in CS2 & 100 LF in CS3 for Concrete Bridge Rail. [2016] 30' of moderate delamination on east half of north side of railing. [2016] major 1' x 6" spall on post # 11 on north side with cracks & delamination on all posts on north side. [2015] 18 LF in CS 3 & 182 LF in CS 2. [2015] 75% of concrete posts have moderate spalls & delamination with corrosion present. [2015] There is moderate spalls on #9, #11 & #12 posts on the south side. [2014-2015] There is longitudinal cracking on top of railing the east 1/2 of the north side railing. [2009-2015] There is longitudinal cracking on top of railing the west 1/2 of the north side railing. [2006-2015] There is major delamination with section loss south side on the #5 post. [2004-2015] Concrete parapet needs repair & paint. Galvanizing protection is chalking on metal railing. [2009-2014] There is moderate delamination of #9, #11 & #12 posts on the south side. [2004-2014] 50% of concrete posts have moderate spalling & delamination with corrosion present. Railing is a combination concrete parapet & metal railing.</p>								
800	Critical Deficiencies or Safety Hazards	Routine	11/16/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION.</p>								
822	Bituminous Approach Roadway	Routine	11/16/2016	2 EA	0	2	0	0
		Migrated Values		2 EA	0	2	0	0
<p>Notes: [2016] Moderate cracks over piers. [2010-2016] Moderate cracking with settlement present at both ends. [2007] New mill & overlay. Milled an average of 1 1/4" and paved 0.20' in July 2007.</p>								
883	Concrete Shear Cracking	Routine	11/16/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: Use this element to monitor the presence of shear cracking on concrete elements. Pay particular attention to the concrete pier caps. [2016] no shear cracking present.</p>								
890	Load Posting or Vertical Clearance Signing	Routine	11/16/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: [2016] Structure requires a vertical clearance sign or load posting sign. [2003-2016] Horizontal clearance signs are in place. Load posting signs are in place.</p>								
891	Other Bridge Signing	Routine	11/16/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: [2003-2016] Horizontal clearance signs are in place. Load posting signs are in place.</p>								
892	Slopes & Slope Protection	Routine	11/16/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
<p>Notes: [2009-2016] Slope protection has moderate deterioration. Grouted riprap has moderate cracking and settlement. [2005-2016] Minor to moderate erosion at the SW & NW corners. Slope protection consists of grouted rip rap.</p>								
893	Guardrail	Routine	11/16/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
<p>Notes: [2007-2016] There is moderate damage to all four segments but still functions as intended. [2016] Guardrail transitions do not meet current standards. - Posts are 3' spacing @ bridge, not 1'-6 3/4" as per MnDOT Standard Plate</p>								
894	Deck & Approach Drainage	Routine	11/16/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
<p>Notes: [2005-2016] Drains off the bridge east and west. Drainage is operating properly.</p>								

BRIDGE 4533 CSAH 77 OVER MC RY

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
895	Sidewalk, Curb, & Median	Routine	11/16/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2016] There is a 3" settlement of walk @ SE corner of bridge, should be patched with bituminous. [2016] 1' x 1' major spall in SW corner of walk. [2014-2015] There is a 2" settlement of walk @ SE corner of bridge. [2013-2016] Major horizontal crack w/ spalling along face of north curb (44') [2012-2016] Minor cracking and moderate spalling are present. [2004-2016] Settlement of sidewalk at the NE & NW corners have been patched with bituminous.								
900	Protected Species	Routine	11/16/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure. [2061] No protective species found.								

General Notes: 2016 Bridge safety inspection was completed by Dan Bodelson, Brian Essler & Rob Gaetz on 11/16/2016.
 2015 Bridge safety inspection was completed by Brian Essler & Dan Bodelson on 11/19/2015.
 2014 Bridge safety inspection was completed by Dan Bodelson, Brian Essler & Randy Bussiere on 11/21/2014.
 2013 Bridge safety inspection was completed by Dan Bodelson & Brian Essler on 11/07/2013.
 2012 Bridge safety inspection was completed by B. Wieman on 11/26/2012.
 2011 Bridge safety inspection was conducted by B. Wieman on 11/9/2011.
 2010 Bridge safety inspection by B. Wieman & D. Bodelson on 11/02/2010.
 2010 Also inspected by MN/DOT Bridge Dept. as part of compliance review.
 2009 Bridge safety inspection by B. Wieman on 7/21/2009.
 2008 Bridge safety inspection by B. Paine & B. Wieman 10/27/2008.
 2007 Bridge safety inspection by B. Wieman 7/26/2007 .
 Bridge rating by TKDA 11/28/2006. Inventory rating - HS 24.9, Operating rating HS 41.5.
 Graffiti is on abutment, pier columns & wing walls 2003-2015.
 Bridge #4533 was constructed in 1926. Bridge #4533 was remodeled in 1973.

- 58. Deck NBI: There is major longitudinal and transverse cracking of bituminous overlay.
There is deck leakage @ deck joints (transverse cracking) & along pre-cast sections
 - 36A. Brdg Railings NBI: Vehichular railings meet current standards.
 - 36B. Transitions NBI: Guardrail transitions do not meet current standards.
Posts are 3' spacing @ bridge, not 1'-6 3/4" as per MnDOT Standard Plate
 - 36C. Appr Guardrail NBI: Approach guardrail meets current standards.
 - 36D. Appr Guardrail Terminal NBI: Guardrail terminations meet current standards.
 - 59. Superstructure NBI: Major spalls w/ exposed rebar & significant section loss on channels
 - 60. Substructure NBI: Major delamination & spalls on abutment
Minor spalls with exposed rebar on columns
 - 61. Channel NBI: No Water
 - 62. Culvert NBI: Bridge
 - 71. Waterway Adeq NBI: No Water
 - 72. Appr Roadway Alignment NBI: Minor speed reduction due to horizontal & vertical curves
- Inventory Notes:

Dan Bodelson
 Inspector's Signature

Nicklaus Fischer
 Reviewer's Signature

Pictures



Photo 1 -



Photo 2 -

Pictures



Photo 3 -



Photo 4 -

Pictures



Photo 5 -



Photo 6 -

Pictures



Photo 7 -



Photo 8 -

Pictures



Photo 9 -



Photo 10 -

Pictures



Photo 11 -



Photo 12 -

Pictures



Photo 13 -



Photo 14 -

Pictures



Photo 15 -



Photo 16 -

Pictures



Photo 17 -



Photo 18 -

Pictures



Photo 19 -



Photo 20 -

Pictures



Photo 21 -



Photo 22 -

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------

BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the Minnesota Bridge Office upon receipt of the 7 Day FC Report; however, it is an **OPTIONAL** tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 4533	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 11/16/2016	STRUCTURE TYPE: Prestressed Concrete tringer/Multi-beam or Girder
FACILITY CARRIED: CSAH 77	FEATURES INTERSECTED: MC RY
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE	
<input type="checkbox"/> FRACTURE CRITICAL	
<input type="checkbox"/> PINNED ASSEMBLY:	
<input type="checkbox"/> SPECIAL:	
<input type="checkbox"/> DAMAGE:	
<input type="checkbox"/> COMPLEX:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path	Connection <input type="checkbox"/> Riveted
<input type="checkbox"/> Structural	Type: <input type="checkbox"/> Bolted
<input type="checkbox"/> Internal	<input type="checkbox"/> Welded
	<input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance Monitoring Plan
 Complex Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer