

**2016 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 5664
CSAH 55(JACKSON) over BNSF RR**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: St Paul

STATE: Minnesota

Date(s) of Inspection: 04/29/2016

**Equipment Used: Full Body Harness, Bucket Van, Non-destructive Testing
Equipment - Panametrics Epoch XT portable flaw detector.
2.25 MHz 1/2" diameter normal beam transducer.**

Owner: County Highway Agency

Inspected By: Ekstrand, Ron; Engel, Michael; Grau, Joe; Reimer, Dan

**Report Written By: Ron Ekstrand
Report Reviewed By: Glenn Pagel
Final Report Date: 06/08/2016**




Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
STRUCTURE INVENTORY	3
ROUTINE INSPECTION DATA	4
ELEMENTS	9
PICTURES	14
THUMBNAIL PICTURES	24
CULVERT	25
CHANNEL	26
SCOUR POA	28
MAINTENANCE	29
STRUCTURAL ASSESSMENT REPORT - ROUTINE	30

Minnesota Structure Inventory Report

Bridge ID: 5664

CSAH 55(JACKSON)

over BNSF RR

Date: 06/08/2016

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City St Paul			
Township			
Desc. Loc. 0.8 MI N OF JCT TH 94			
Sect., Twp., Range 31 - 029N - 22W			
Latitude		Sec	
Deg 44	Min 57	46.34	
Longitude		Sec	
Deg 93	Min 5	52.52	
Custodian 27 - Railroad			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		1939	
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 4 - MUNICIPAL			
Date Opened to Traffic			
On-Off System 1 - ON			
Legislative District 65A			
ABC Suitable			

STRUCTURE			
Service On 5 - Highway-pedestrian			
Service Under 2 - Railroad			
Main Span Type			
4 - Steel Continuous		01 - Beam Span	
Main Span Detail			
Appr. Span Type			
Appr. Span Detail			
Skew		13 R	
Culvert Type			
Barrel Length		ft.	
Cantilever ID P - Pinned Hinge			

NUMBER OF SPANS			
MAIN: 9	APPR: 0	TOTAL: 9	
Main Span Length		66.0	ft.
Structure Length		485.7	ft.
Deck Width (Out-to-Out)		57.0	ft.
Deck Material 1 - Concrete Cast-in-Place			
Wear Surf Type 4 - Low Slump Concrete			
Wear Surf Install Year 1982			
Wear Course/Fill Depth		0.21	ft.
Deck Membrane 0 - None			
Deck Rebars 0 - None			
Deck Rebars Install Year			
Structure Area (Out-to-Out)		27685	sq. ft.
Roadway Area (Curb-to-Curb)		19429	sq. ft.
Sidewalk Width		Lt 7.50	ft. Rt 7.50
Curb Height		Lt 1.17	ft. Rt 1.17
Rail Type		Lt 40	Rt 40

ROADWAY			
Bridge Match ID (TIS) 0			
Roadway O/U Key Route On Structure			
Route Sys 04 - CSAH		Number 55	
Roadway Name or Description			
CSAH 55			
Level of Service 1 - MAINLINE			
Roadway Type 2 - 2-way traffic			
Control Section (TH Only)			
Reference Point 000+00.110			
Detour Length		1.0	mi
Lanes		On 2	Under 0
		ADT 7229	Year 2011
HCACT		0	ADTT 0 %
Functional Class 16 - Urban - Minor Arterial			

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	40.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.	39.9	ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	44.0	ft.	
Bridge Roadway Width	40.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	2 - Riveted
Abutment Foundation	4 - MASONRY
(Material/Type)	1 - SPRD SOIL
Pier Foundation	1 - CONC
(Material/Type)	1 - SPRD SOIL
Historic Status	5 - Not eligible

PAINT	
Year Painted	1982
Unsound Paint %	
Painted Area	3218 sq. ft.
Primer Type	2 - Lead, Iron Oxide - non
Finish Type	C - Lead Silica Chromate

BRIDGE SIGNS	
Posted Load	2 - Vehicle & Semi (Type R12-5)
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	199
Unofficial Structurally Deficient	Y
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	34.5
Routine Inspection Date	04/29/2016
Routine Inspection Frequency	12
Inspector Name	CO Bridge
Status	P - Posted for Load

NBI CONDITION RATINGS	
Deck	6 - Satisfactory Condition
Unsound Deck %	1
Superstructure	4 - Poor Condition
Substructure	4 - Poor Condition
Channel	N - Not Applicable
Culvert	N - Not Applicable

NBI APPRAISAL RATINGS	
Structure Evaluation	3
Deck Geometry	5
Underclearances	4
Water Adequacy	N - Not Applicable
Approach Alignment	7 - Better than present minir

SAFETY FEATURES	
Bridge Railing	0 - SUBSTANDARD
GR Transition	0 - SUBSTANDARD
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	0 - SUBSTANDARD

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical	N		
Underwater	N		
Pinned Asbly.	N	60 mo.	11/19/2012
Spec. Feat.			

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening		sq. ft.	
Navigation Control N - Not applicable, no waterw			
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code A - NON WATER' Year			

CAPACITY RATINGS			
Design Load	5 - HS 20		
Operating Rating	0 - Unknown	20.5	
Inventory Rating	0 - Unknown	8.5	
Posting VEH: 10	SEMI: 20	DBL: 20	
Rating Date 07/15/2014			

Minnesota Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MINNESOTA BRIDGE INSPECTION REPORT

06/08/2016

BRIDGE 5664 CSAH 55(JACKSON) OVER BNSF RR

ROUTINE INSP. DATE: 04/29/2016

County: Ramsey	Location: 0.8 MI N OF JCT TH 94	Length: 485.7 ft.
City: St Paul	Route: 04 - CSAH 55 Ref. Pt.: 000+00.110	Deck Width: 57.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 19429 sq. ft. / 1%
Section: 31 Township: 029N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: 3218 sq. ft. / %
Span Type: 4 - Steel Continuous 2 -	Local Agency Bridge Nbr.:	Culvert: N/A
List: Stringer/Multi-beam or Girder		Postings: 10 20 20
NBI Deck: 6 Super: 4 Sub: 4 Chan: N Culv: N		
	Open, Posted, Closed: P - Posted for Load	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 7 Waterway: N		Unofficial Structurally Deficient Y
Required Bridge Signs - Load Posting: 2 - Vehicle & Semi (Type R12-5)	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 34.5

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY	QTY	QTY	QTY	QTY
						CS 1	CS 2	CS 3	CS 4	CS 5
022	Low Slump O/L (Concrete Deck with Uncoated Rebar)	2	Routine	04/29/2016	27685 SF	0	27685	0	0	0
			Routine	04/29/2015	27685 SF	0	27685	0	0	0

Notes: 500 + feet of transverse cracks in the LS concrete overlay. 06-15
 Combined area of unsound wear surface is 2% or less than total deck area. 2011-15
 Recommend resealing of cracks. 2011-15
 Need LS overlay photos-2012

107	Painted Steel Girder or Beam	2	Routine	04/29/2016	4839 LF	3808	823	35	50	123
			Routine	04/29/2015	4839 LF	3808	823	35	50	123

Notes: Facia beams and several spans over the railroad tracks are gunite covered. 1995-2015
 Gunite has fallen off the east facia girder. 2004
 Verify that the bottom angle iron there is 80% section loss in the north facia beams at the north bearing. 2001
 The bridge crew removed the gunite from the bottom of the facia beams on the 2, 3rd & 4th spans from the south end. 2005
 Bay West uses some of the land under some of the south spans for their equipment and storage.
 They reported they have no problems with loose concrete from the bridge. 2008
 (2009) Facia beams actively shedding gunnite and pack rust. Removed at 3rd bay. 2010
 Paint system failure over 20% of all beams. 2011-15
 Severe corrosion with extensive flaking rust present. 2011-15
 Extensive to severe deterioration of identified beam ends. 2015
 Load-carrying capacity has been reduced. 2014-15
 Section loss has been identified at various beam ends. 2015

161	Pin & Hanger (or Hinge Pin) Assembly (Painted)	2	Routine	04/29/2016	24 EA	0	0	0	24	0
			Routine	04/29/2015	24 EA	0	0	0	24	0

Notes: [2007] Mn/DOT Bridge Office performed ultrasonic inspection of the single pin hinge connections, no significant UT indications were found. However, there is severe pack rust between the steel plates at the pinned connections.
 (2012) No change.
 MN DOT inspection of pins. Nov. 2012
 Quantity change to (8 X 3) = 24 Total. 2015

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
205	Reinforced Concrete Column	2	Routine	04/29/2016	40 EA	12	16	9	3	N/A
			Routine	04/29/2015	40 EA	12	16	9	3	N/A
<p>Notes: Five columns of the north pier need shotcrete repair. 02-11. One column has 3' of rusty exposed rebar at the bottom. 06-11. There is 15 sq. ft. + of spalling and exposed rebar at one column at the 4th pier from the south end. 2013</p> <p>Extensive cracking and delams at columns, CS3. 2011-13 4 columns at first set, from the north. 2013 Moderate cracking and minor delams at 12 columns, CS2. 2011-13</p> <p>Severe deterioration and cracking is present at identified columns. 2014-15 Spalling and delamination of columns is severe. 2014-15 Exposed reinforcement is corroded and rusted. 2014-15</p>										
217	Masonry, Other or Combination Material Abutment	2	Routine	04/29/2016	118 LF	63	15	40	0	N/A
			Routine	04/29/2015	118 LF	63	15	40	0	N/A
<p>Notes: The north abutment has moderate shaling. Several diagonal cracks at the north abutment. 92-08. (2009) N.abut showing large diagonal cracks, settlement/ 'tipping' noted. S. abut. cracking vertical and horizontal, gunite repairs full width. 10-15</p>										
234	Reinforced Concrete Pier Cap	2	Routine	04/29/2016	469 LF	447	6	16	0	N/A
			Routine	04/29/2015	469 LF	447	6	16	0	N/A
<p>Notes: Several spalls and cracks on the piers. 90-15 The north pier needs repair. 92-13 There is 8 + sq. ft. spalled of the south face of the north pier cap. 10-15</p> <p>Extensive deterioration, cracking, leaching and staining. 2014-15 Delams and spalling is prevalent at pier # 2. 2014-15</p>										
300	Strip Seal Deck Joint	2	Routine	04/29/2016	226 LF	222	2	2	N/A	N/A
			Routine	04/29/2015	226 LF	222	2	2	N/A	N/A
<p>Notes: The strip seal at the north pier and at the fourth pier from the south end leaks. 02-08. One foot of gland is out of the extrusion at the north expansion joint. 04.-15</p>										
301	Poured Deck Joint	2	Routine	04/29/2016	97 LF	15	0	82	N/A	N/A
			Routine	04/29/2015	97 LF	15	0	82	N/A	N/A
<p>Notes: Changed quantity to 97 LF in 2015. Poured sealant is missing. Concrete repairs and joint replacement is necessary. 2015</p>										
311	Expansion Bearing	2	Routine	04/29/2016	100 EA	0	80	20	N/A	N/A
			Routine	04/29/2015	100 EA	0	80	20	N/A	N/A
<p>Notes: There are many anchor bolts missing. 86-15 Moderate to severe deterioration, Extensive corrosion present. 2012-15 Many bearings are no longer functioning as intended. Frozen or severely restricted bearings are present. 2015</p>										
313	Fixed Bearing	2	Routine	04/29/2016	80 EA	0	70	10	N/A	N/A
			Routine	04/29/2015	80 EA	0	70	10	N/A	N/A
<p>Notes: Moderate to severe deterioration, Extensive corrosion present. 2012-15 Isolated anchor connections have rusted off completely. 2015 Many bearings are no longer functioning as intended.</p>										

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
321	Concrete Approach Slab-Concrete Wearing Surface	2	Routine	04/29/2016	2 EA	0	2	0	0	N/A
			Routine	04/29/2015	2 EA	0	2	0	0	N/A
Notes: Moderate deterioration. 2011-15 Moderate cracking and settlement present. 2011-15 Some bituminous patching / overlay present. 2011-15										
334	Metal Bridge Railing (Coated or Painted)	2	Routine	04/29/2016	968 LF	0	908	60	0	0
			Routine	04/29/2015	968 LF	0	908	60	0	0
Notes: Moderate paint failure on railing. Heavy rusting on base plates. 06-15 Bent railing, sixth panel from the northwest end. 88-15 Some base plate welds are broken at the top of the angle iron. 08-13 Corrected 2014										
357	Pack Rust Smart Flag	2	Routine	04/29/2016	1 EA	0	0	1	0	N/A
			Routine	04/29/2015	1 EA	0	0	1	0	N/A
Notes: see element #161 pin and hanger. 2012-15 see bearing elements. 2015										
358	Concrete Deck Cracking Smart Flag	2	Routine	04/29/2016	1 EA	0	1	0	0	N/A
			Routine	04/29/2015	1 EA	0	1	0	0	N/A
Notes: Moderate cracking of deck present. 2011-15										
359	Underside of Concrete Deck Smart Flag	2	Routine	04/29/2016	1 EA	0	1	0	0	0
			Routine	04/29/2015	1 EA	0	1	0	0	0
Notes: Moderate cracking of deck present. 2011-15 Efflorescence, staining and leaching present. 2011-15 Distressed area on the underside of the deck is 2% or less than the total deck area. 2011-15 Need 555 SF to be over the 2% of total deck area. 2011-15										
362	Traffic Impact Smart Flag	2	Routine	04/29/2016	1 EA	0	1	0	N/A	N/A
			Routine	04/29/2015	1 EA	0	1	0	N/A	N/A
Notes: Impact damage at NW railing. 2011 Steel member has been bent. 2015										
363	Section Loss Smart Flag	2	Routine	04/29/2016	1 EA	0	0	1	0	N/A
			Routine	04/29/2015	1 EA	0	0	1	0	N/A
Notes: Steel beam element has section loss. 2015 All exterior beam ends have significant section loss. 2015 Need a percent of section loss calculated. 2013-15 Less than 10% section loss = CS-3 More than 10% section loss = CS-4 The bridge owner has been notified of the section loss at the beam ends. 2015										

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
380	Secondary Structural Elements	2	Routine	04/29/2016	286 EA	280	0	6	0	N/A
			Routine	04/29/2015	286 EA	280	0	6	0	N/A
Notes: The exterior diaphragm at the fifth pier from the south and the center diaphragm in the south span is spalled. 92-12 The south center diaphragm is spalled with exposed rebar. 07-12 A diaphragm is cracked and spalled at the fourth span from the north abutment (at the SE. corner of the fourth span) 95-02.										
387	Reinforced Concrete Wingwall	2	Routine	04/29/2016	4 EA	1	3	0	0	N/A
			Routine	04/29/2015	4 EA	1	3	0	0	N/A
Notes: The southwest wing wall is pulled away "X". Check this dimension. 02-06. 1 1/4" in 2007 - 2010. SE wingwall - loose fill, sidewalk is voided. 2015 NE wingwall - shale stone crumbling. 2015 NW wingwall - shale stone cracked and crumbling. 2015										
964	Critical Finding Smart Flag	2	Routine	04/29/2016	1 EA	1	0	N/A	N/A	N/A
			Routine	04/29/2015	1 EA	1	0	N/A	N/A	N/A
Notes: Previous comments > DO NOT DELETE THIS CRITICAL FINDING SMART FLAG. There is 80% section loss in some of the north fascia beams at the north bearing on the bottom flange. 06-08. Kevin Nelson and Tracy Moe discussed this element and determined that it is not a critical condition at this time. Annual inspections should continue to assess this condition. 07-10.										
981	Signing	2	Routine	04/29/2016	1 EA	1	0	0	0	0
			Routine	04/29/2015	1 EA	1	0	0	0	0
Notes: Added element 981 in 2014. Load posting signs in place. 2014-15										
983	Plowstraps	2	Routine	04/29/2016	1 EA	1	0	0	N/A	N/A
			Routine	04/29/2015	1 EA	1	0	0	N/A	N/A
Notes:										
986	Curb & Sidewalk	2	Routine	04/29/2016	1 EA	0	1	0	N/A	N/A
			Routine	04/29/2015	1 EA	0	1	0	N/A	N/A
Notes: Several transverse cracks are present. 02-15 Ped ramp at the SE end needs replacing. 10-15 Moderate damage, cracking and spalling present. 2011-15										
988	Miscellaneous Items	1	Routine	04/29/2016	1 EA	1	0	0	N/A	N/A
			Routine	04/29/2015	1 EA	1	0	0	N/A	N/A
Notes: Bicycle lanes 7 1/2 ft wide were added to the curb side of the deck on each side of the bridge. The bridge is now a two lane bridge for motorized vehicular traffic. This change was made by placing a stripe in the existing concrete deck. 2008-11.										

General Notes: Have Excel Energy check gas main that is very rusty at the S. Abt.05-06. Mr. Garth at N.S.P. was notified on December 4, 2006. On December 5, 2006 it was requested that N.S.P. mark the gas main as abandoned. He said he will inquire if it can be removed or marked. If it is removed it would be capped at the abutments. 06. The gas main is capped. 08-12

58. Deck NBI: Moderate cracking, leaching and wear. 2011
 Minor delams / spalling. 2011

36A. Brdg Railings NBI:

36B. Transitions NBI: Posted speed does NOT exceed 40 MPH. 2014

36C. Appr Guardrail NBI:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
36D.	Appr Guardrail Terminal NBI:									
59.	Superstructure NBI:		Advanced deterioration is present. 2015-16 Extensive to severe corrosion at bearing areas. 2015-16 Bearing function is restricted 2015-16 Steel beams have section loss at the critical stress areas. 2015-16 Fascia beam ends have significant to severe section loss. 2015							
60.	Substructure NBI:		Advanced deterioration of identified columns. 2014-16 Advanced scaling, cracking and leaching is present. 2014-16 Significant cracking is present. 2014-16 Extensive delamination and spalling of identified columns. 2014-16							
61.	Channel NBI:									
62.	Culvert NBI:									
71.	Waterway Adeq NBI:									
72.	Appr Roadway Alignment NBI:									
	Inventory Notes:		BNSF contacts:							
			Michael Anderson	bridges and structures supervisor	(763) 782-3310	cell (612) 749-3401				
			Lane Gilliland	bridge inspector	michael.anderson5@bnsf.com	cell (612) 219-4219				
			Bridge owner contacts Ramsey County - Bret Wieman - 651-266-7126 - Kathy Jaschke - 651-266-7192							

Ron Ekstrand
Inspector's Signature

Glenn Pagel
Reviewer's Signature

MINNESOTA BRIDGE INSPECTION REPORT

06/08/2016

Inspector: CO Bridge

BRIDGE 5664 CSAH 55(JACKSON) OVER BNSF RR

County: Ramsey	Location: 0.8 MI N OF JCT TH 94	Length: 485.7 ft.
City: St Paul	Route: 04 - CSAH 55 Ref. Pt.: 000+00.110	Deck Width: 57.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsd: 19429 sq. ft. / 1%
Section: 31 Township: 029N Range: 22W Maint. Area:		Paint Area/ Pct. Unsd: 3218 sq. ft. / %
Span Type: 4 - Steel Continuous 2 -	Local Agency Bridge Nbr.:	Culvert: N/A
List: Stringer/Multi-beam or Girder		Postings: 10 20 20
NBI Deck: 6 Super: 4 Sub: 4 Chan: N Culv: N		
	Open, Posted, Closed: P - Posted for Load	
	MN Scour Code: A - NON WATERWAY	

Appraisal Ratings - Approach: 7	Waterway: N	Unofficial Structurally Deficient Y
Required Bridge Signs - Load Posting: 2 - Vehicle & Semi (Type R12-5)	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 34.5

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
12	Reinforced Concrete Deck	Routine	04/29/2016	27685 SF	26631	500	554	0
		Migrated Values	06/08/2016	27685 SF	26631	500	554	0
	Notes: Moderate cracking of the under deck is present. 2011-16 CS2 Efflorescence / light leaching, minor staining present. 2011-16 CS2							
	Heavy leaching with some build up. 2016 CS3 Water / salt saturation with rust staining in various areas. 2016 CS3							
510	- Wearing Surfaces	Routine	04/29/2016	19429 SF	13601	3885	1943	0
		Migrated Values	06/08/2016	19429 SF	13601	3885	1943	0
	Notes: Low Slump Overlay with Uncoated Rebar deck. 500 + feet of transverse cracks in the LS concrete overlay. 2006-16 Unsealed cracks 1/8" and less are present. CS2 2016 Unsealed cracks 1/8" and more are present. CS3 2016 Various spalls and some plow damage at the joints. 2016 1' X 10' bituminous patch at the CL of the deck. 2016							
107	Steel Open Girder/Beam	Routine	04/29/2016	4839 LF	3808	858	50	123
		Migrated Values	06/08/2016	4839 LF	3808	858	50	123
	Notes: Fascia beams and beams over the railroad tracks are gunite covered. 2016 At the bottom angle iron there is section loss at the fascia beams at the bearings. 2001-16 The bridge crew removed the gunite from the bottom of the fascia beams on the 2, 3rd & 4th spans from the south end. 2005 (2009) Fascia beams actively shedding gunnite and pack rust. Removed at 3rd bay. 2010 Severe corrosion with extensive flaking rust present. 2011-16 Load-carrying capacity has been reduced. 2014-16 Corrosion and section loss has been identified at various beam ends. 2015-16 Pack Rust Notes: see element #161 pin and hanger. 2012-15							
515	- Steel Protective Coating	Routine	04/29/2016	16144 SF	12916	807	1614	807
		Migrated Values	06/08/2016	16144 SF	12916	807	1614	807
	Notes: Quantity changed to 16,144 SF. 2016 Paint system failure over 20% of all beams. 2011-16							

BRIDGE 5664 CSAH 55(JACKSON) OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
161	Steel Pin and Pin & Hanger Assembly or both	Routine	04/29/2016	24 EA	0	0	24	0
		Migrated Values	06/08/2016	24 EA	0	0	24	0
<p>Notes: [2007] Mn/DOT Bridge Office performed ultrasonic inspection of the single pin hinge connections, no significant UT indications were found. However, there is severe pack rust between the steel plates at the pinned connections. (2012) No change. MN DOT inspection of pins. Nov. 2012 Quantity change to (8 X 3) = 24 Total. 2015 Corrosion of pins and pack rust is present. 2016 Movement is restricted from the presence of flaking / pack rust. 2016</p>								
515	Steel Protective Coating	Routine	04/29/2016	164 SF	0	0	0	164
		Migrated Values	06/08/2016	164 SF	0	0	0	164
<p>Notes: Quantity changed to 164 sf. 2016 Paint system is failing. More than 16% rusting steel. 2016</p>								
205	Reinforced Concrete Column	Routine	04/29/2016	40 EA	11	17	9	3
		Migrated Values	06/08/2016	40 EA	11	17	9	3
<p>Notes: Extensive cracking and delams at columns, CS3. 2011-16 Moderate cracking and minor delams at 12 columns, CS2. 2011-16 Severe deterioration and cracking is present at identified columns. 2014-16 Exposed reinforcement is corroded and rusted. 2014-16 PIR structural review was done in 2014. Strength of the element has been reduced. 2016</p>								
215	Reinforced Concrete Abutment	Routine	04/29/2016	90 LF	10	10	70	0
		Migrated Values	06/08/2016	90 LF	10	10	70	0
<p>Notes: Repaired areas are unsound. 2016 Quantity changed to 90 LF. 2016 S. abut. cracking vertical and horizontal, gunite repairs full width. 10-15 Leaching, staining, scaling and cracking is present. 2016</p>								
217	Masonry Abutment	Routine	04/29/2016	118 LF	63	15	40	0
		Migrated Values	06/08/2016	118 LF	63	15	40	0
<p>Notes: The masonry abutment has a concrete cap and seat on top of the stone. 2016 The north abutment has moderate cracking of the concrete cap/seat. 2016 Diagonal cracks at the north abutment (at the sides). 2016 Weathering / abrasion / delamination is present. 2016 10% to 25% loss of block thickness in isolated areas. 2016 Blocks are split at isolated areas. 2016 Cracking or voids are present in the mortar. 2016</p>								
234	Reinforced Concrete Pier Cap	Routine	04/29/2016	469 LF	447	6	16	0
		Migrated Values	06/08/2016	469 LF	447	6	16	0
<p>Notes: Several spalls and cracks on the piers. 1990-2016 There is 8 + sq. ft. spalled of the south face of the north pier cap. 10-16 Extensive deterioration, cracking, leaching and staining. 2014-16 Delams and spalling is prevalent at pier # 2. 2014-16</p>								
300	Strip Seal Expansion Joint	Routine	04/29/2016	226 LF	222	2	0	2
		Migrated Values	06/08/2016	226 LF	222	2	0	2
<p>Notes: The strip seal at the north pier and at the fourth pier from the south end leaks. 2002-16 One foot of gland is out of the extrusion at the north expansion joint. 2004-16</p>								
301	Pourable Joint Seal	Routine	04/29/2016	97 LF	15	0	0	82
		Migrated Values	06/08/2016	97 LF	15	0	0	82
<p>Notes: Changed quantity to 97 LF in 2015. Poured sealant is missing. Concrete repairs and joint replacement is necessary. 2015-16</p>								

BRIDGE 5664 CSAH 55(JACKSON) OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
311	Movable Bearing	Routine	04/29/2016	100 EA	0	80	0	20
		Migrated Values	06/08/2016	100 EA	0	80	0	20
<p>Notes: There are many anchor bolts missing. 86-16 Moderate to severe deterioration, Extensive corrosion present. 2012-16 Many bearings are no longer functioning as intended. Frozen or severely restricted bearings are present. 2015-16</p>								
313	Fixed Bearing	Routine	04/29/2016	80 EA	0	70	0	10
		Migrated Values	06/08/2016	80 EA	0	70	0	10
<p>Notes: Moderate to severe deterioration, Extensive corrosion present. 2012-16 Isolated anchor connections have rusted off completely. 2015-16 Many bearings are no longer functioning as intended. 2015-16</p>								
321	Reinforced Concrete Approach Slab	Routine	04/29/2016	1507 SF	1417	80	10	0
		Migrated Values	06/08/2016	1507 SF	1417	80	10	0
<p>Notes: Moderate deterioration - spalls / delams. present. No exposed rebar. 2011-16 Unsealed moderate cracking and settlement present. 2016 Various width cracks are present. All sealant (if present) has failed. 2016 Bituminous patching / overlay present. 2011-16</p>								
330	Metal Bridge Railing	Routine	04/29/2016	1936 LF	968	964	4	0
		Migrated Values	06/08/2016	1936 LF	968	964	4	0
<p>Notes: Moderate paint failure on railing. Heavy rusting on base plates. 2006-16 Bent railing, sixth panel from the northwest end. 1988-2015 Some base plate welds are broken at the top of the angle iron. 08-13 Corrected 2014 Quantity changed to 1,936 LF. chain link fence included. 2016</p>								
	515 - Steel Protective Coating	Routine	04/29/2016	2904 SF	0	01742	872	290
		Migrated Values	06/08/2016	2904 SF	0	01742	872	290
<p>Notes: 2,904 SF total. 2016</p>								
800	Critical Deficiencies or Safety Hazards	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION. There is 80% section loss in some of the north facia beams at the north bearing on the bottom flange. 06-08. Kevin Nelson and Tracy Moe dicussed this element and determined that it is not a critical condition. Annual inspections should continue to assess this condition. 07-10.</p>								
810	Concrete Decks - Cracking & Sealing	Routine	04/29/2016	1311 LF	0	1000	300	11
		Migrated Values	06/08/2016	1311 LF	0	1000	300	11
<p>Notes: Moderate cracking of deck present. 2011-16 Quantity changed to 1,311 LF. 2016 Unsealed cracks from .012 to over 1/8". 2016</p>								
815	Plow Fingers	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
855	Secondary Members (Superstructure)	Routine	04/29/2016	286 EA	280	0	6	0
		Migrated Values	06/08/2016	286 EA	280	0	6	0
<p>Notes: The exterior diaphragm at the fifth pier from the south and the center diaphragm in the south span is spalled. 92-12 The south center diaphragm is spalled with exposed rebar. 07-16 A diaphragm is cracked and spalled at the fourth span from the north abutment (at the SE. corner of the fourth span) 95-02.</p>								
880	Impact Damage	Routine	04/29/2016	1 EA	0	1	0	0
		Migrated Values	06/08/2016	1 EA	0	1	0	0
<p>Notes: Impact damage at NW railing. 2011 Steel member has been bent. 2015 no change 2016</p>								

BRIDGE 5664 CSAH 55(JACKSON) OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
881	Steel Section Loss	Routine	04/29/2016	1 EA	0	0	1	0
		Migrated Values	06/08/2016	1 EA	0	0	1	0
<p>Notes: Steel beam element has section loss. 2015-16 All exterior beam ends have significant section loss. 2015-16 Need a percent of section loss calculated. 2013-16 Less than 10% section loss = CS-3 More than 10% section loss = CS-4 The bridge owner has been notified of the section loss at the beam ends. 2015-16</p>								
883	Concrete Shear Cracking	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: Use this element to monitor the presence of shear cracking on concrete elements. Pay particular attention to the concrete pier caps.</p>								
890	Load Posting or Vertical Clearance Signing	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: [2016] Structure requires a vertical clearance sign or load posting sign. Required load posting signs are present. 2014-16</p>								
892	Slopes & Slope Protection	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: Use this element to rate the condition of slopes and slope protection.</p>								
894	Deck & Approach Drainage	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: Use this element to rate the condition, function, and adequacy of the drainage system.</p>								
895	Sidewalk, Curb, & Median	Routine	04/29/2016	1 EA	0	1	0	0
		Migrated Values	06/08/2016	1 EA	0	1	0	0
<p>Notes: Several transverse cracks are present. 02-16 Ped ramp at the SE end is heaved upward. 10-16 Moderate damage, cracking and spalling present. SW has sunken panels. 2011-16</p>								
899	Miscellaneous Items	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: Bicycle lanes 7 1/2 ft wide were added to the curb side of the deck on each side of the bridge. The bridge is now a two lane bridge for motorized vehicular traffic. This change was made by placing a stripe on the existing concrete deck. 2008-11</p>								
900	Protected Species	Routine	04/29/2016	1 EA	1	0	0	0
		Migrated Values	06/08/2016	1 EA	1	0	0	0
<p>Notes: Use this element to track the presence of protected species living on this structure. None found. 2016</p>								
<p>General Notes: Have Excel Energy check gas main that is very rusty at the S. Abt.05-06. Mr. Garth at N.S.P. was notified on December 4, 2006. On December 5, 2006 it was requested that N.S.P. mark the gas main as abandoned. He said he will inquire if it can be removed or marked. If it is removed it would be capped at the abutments. 06. The gas main is capped. 08-12</p>								
<p>58. Deck NBI: Moderate cracking, leaching and wear. 2011 Minor delams / spalling. 2011</p>								
<p>36A. Brdg Railings NBI:</p>								
<p>36B. Transitions NBI: Posted speed does NOT exceed 40 MPH. 2014</p>								
<p>36C. Appr Guardrail NBI:</p>								
<p>36D. Appr Guardrail Terminal NBI:</p>								
<p>59. Superstructure NBI: Advanced deterioration is present. 2015-16 Extensive to severe corrosion at bearing areas. 2015-16 Bearing function is restricted 2015-16</p>								

BRIDGE 5664 CSAH 55(JACKSON) OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
	Steel beams have section loss at the critical stress areas. 2015-16							
	Fascia beam ends have significant to severe section loss. 2015							
60.	Substructure NBI:	Advanced deterioration of identified columns. 2014-16						
		Advanced scaling, cracking and leaching is present. 2014-16						
		Significant cracking is present. 2014-16						
		Extensive delamination and spalling of identified columns. 2014-16						
61.	Channel NBI:							
62.	Culvert NBI:							
71.	Waterway Adeq NBI:							
72.	Appr Roadway Alignment NBI:							
	Inventory Notes:	BNSF contacts:						
		Michael Anderson	bridges and structures supervisor	(763) 782-3310	cell (612) 749-3401			
		Lane Gilliland	bridge inspector	michael.anderson5@bnsf.com	cell (612) 219-4219			
		Bridge owner contacts						
		Ramsey County - Bret Wieman	- 651-266-7126					
			- Kathy Jaschke	- 651-266-7192				

Ron Ekstrand
Inspector's Signature

Glenn Pagel
Reviewer's Signature

Pictures



Photo 1 - NB Jackson - 5664_001



Photo 2 - 2013 Side view_1

Pictures



Photo 3 - SB Jackson - 5664_002



Photo 4 - 2015 google deckview

Pictures



Photo 5 - abut beam - NW.end



Photo 6 - abut NE bearing

Pictures



Photo 7 - abut NE fascia beam



Photo 8 - abut NE fascia beam (2)

Pictures



Photo 9 - abut NE fascia beam



Photo 10 - abut SW fascia b mapcracking

Pictures



Photo 11 - pier 2 - column E.inner.side



Photo 12 - pier 2 - column E.side

Pictures



Photo 13 - pier 2 - column W.inner.side



Photo 14 - pier 2 - column W.side

Pictures



Photo 15 - pier 2 - columns East view



Photo 16 - pier 2 - columns N.side

Pictures



Photo 17 - wing NE_4



Photo 18 - wing NE_5

Pictures



Photo 19 - wing NW_3



Photo 20 - wing SE_1



1. NB Jackson - 5664_001.JPG



2. 2013 Side view_1.JPG



3. SB Jackson - 5664_002.JPG



4. 2015 google deckview.PNG



5. abut beam - NW.end.JPG



6. abut NE bearing.JPG



7. abut NE fascia beam.JPG



8. abut NE fascia beam (2).JPG



9. abut NE fascia beam.JPG



10. abut SW fascia b mapcracking.JPG



11. pier 2 - column E.inner.side.JPG



12. pier 2 - column E.side.JPG



13. pier 2 - column W.inner.side.JPG



14. pier 2 - column W.side.JPG



15. pier 2 - columns East view.JPG



16. pier 2 - columns N.side.JPG



17. wing NE_4.JPG



18. wing NE_5.JPG



19. wing NW_3.JPG



20. wing SE_1.JPG

Channel

Bridge No.: 5664

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	N	

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:			
Downstream Bank Protection:			
Bridge Revetment:			
Minnesota Scour Code:	A - NON WATERWAY		

Underwater Inspection

Underwater Inspection By Divers: _____
 No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point:	_____	High Water Elev.:	_____	Current Water Elev.:	_____
Pile Tip Elev.:	_____	Low Water Elev.:	_____	Current Streambed Elev.:	_____
		Scour Hole Elev.:	_____	Current Scour Hole Elev.:	_____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per Minnesota Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 5664

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to Minnesota's Bridge Scour website for other
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------

BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the Minnesota Bridge Office upon receipt of the 7 Day FC Report; however, it is an **OPTIONAL** tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 5664	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 04/29/2016	STRUCTURE TYPE: Steel Continuous tringer/Multi-beam or Girder
FACILITY CARRIED: CSAH 55(JACKSON)	FEATURES INTERSECTED: BNSF RR
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> COMPLEX:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- | | |
|---|---|
| <input type="checkbox"/> Repair/Maintenance | <input type="checkbox"/> Monitoring Plan |
| <input type="checkbox"/> Complex | <input type="checkbox"/> Increased Inspection Frequency |

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer