

**2015 ROUTINE  
BRIDGE INSPECTION REPORT**



**BRIDGE # 62001  
RICE ST over BNSF RR**

**DISTRICT:** Metro

**COUNTY:** Ramsey

**CITY/TOWNSHIP:** Little Canada

**Date(s) of Inspection:** 11/05/2015

**Equipment Used:**

**Owner:** County Highway Agency

**Inspected By:** Essler, Brian

**Report Written By:** Brian Essler

**Report Reviewed By:** Nicklaus Fischer

**Final Report Date:** 01/07/2016

MnDOT Bridge Office  
3485 Hadley Avenue North  
Oakdale, MN 55128



# Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	10
THUMBNAIL PICTURES	14
CULVERT	15
CHANNEL	16
SCOUR POA	18
CHANNEL X-SECTION	19
MAINTENANCE	20
STRUCTURAL ASSESSMENT REPORT - ROUTINE	21

# MnDOT Structure Inventory Report

Bridge ID: 62001

RICE ST

over BNSF RR

Date: 01/07/2016

GENERAL			
<b>Agency Br. No.</b>			
District Metro			
<b>Maint. Area</b>		<b>Crew</b>	
County 062 - Ramsey			
City Little Canada			
Township			
Desc. Loc. 0.6 MI S OF JCT TH 694			
<b>Sect., Twp., Range</b>		6 - 029N - 22W	
<b>Latitude Deg</b>	<b>Min</b>	<b>Sec</b>	8.98
<b>Longitude Deg</b>	<b>Min</b>	<b>Sec</b>	22.38
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
<b>BMU Agreement</b>			
<b>Year Built</b>		1986	
<b>MN Year Reconstructed</b>			
<b>FHWA Year Reconstructed</b>			
<b>MN Temporary Status</b>			
<b>Bridge Plan Location</b> 1 - CENTRAL			
<b>Date Opened to Traffic</b> 9/1/1987			
<b>On-Off System</b> 1 - ON			
<b>Legislative District</b> 54B			

STRUCTURE	
<b>Service On</b>	5 - Highway-pedestrian
<b>Service Under</b>	2 - Railroad
<b>Main Span Type</b>	
4 - Steel Continuous	01 - Beam Span
<b>Main Span Detail</b>	
<b>Appr. Span Type</b>	
<b>Appr. Span Detail</b>	
<b>Skew</b>	6 L
<b>Culvert Type</b>	
<b>Barrel Length</b>	ft.
<b>Cantilever ID</b>	

NUMBER OF SPANS		
<b>MAIN:</b>	3	<b>TOTAL:</b> 3
<b>APPR:</b>	0	
<b>Main Span Length</b>	50.0	ft.
<b>Structure Length</b>	134.5	ft.
<b>Deck Width (Out-to-Out)</b>	71.3	ft.
<b>Deck Material</b>	1 - Concrete Cast-in-Place	
<b>Wear Surf Type</b>	4 - Low Slump Concrete	
<b>Wear Surf Install Year</b>	1986	
<b>Wear Course/Fill Depth</b>	0.17	ft.
<b>Deck Membrane</b>	0 - None	
<b>Deck Rebars</b>	1 - Epoxy Coated Reinforcing	
<b>Deck Rebars Install Year</b>	1986	
<b>Structure Area (Out-to-Out)</b>	9590	sq. ft.
<b>Roadway Area (Curb-to-Curb)</b>	7664	sq. ft.
<b>Sidewalk Width</b>	Lt 6.00	Rt 6.00
<b>Curb Height</b>	Lt 0.83	Rt 0.83
<b>Rail Type</b>	Lt 21	Rt 21

ROADWAY	
<b>Bridge Match ID (TIS)</b> 0	
<b>Roadway O/U Key</b> Route On Structure	
<b>Route Sys</b>	04 - CSAH
<b>Number</b>	49
<b>Roadway Name or Description</b>	
RICE ST	
<b>Level of Service</b>	1 - MAINLINE
<b>Roadway Type</b>	2 - 2-way traffic
<b>Control Section (TH Only)</b>	
<b>Reference Point</b>	005+00.513
<b>Detour Length</b>	3.0 mi
<b>Lanes</b>	On 2 Under 0
<b>ADT</b>	17928
<b>Year</b>	2008
<b>HCACT</b>	717
<b>ADTT</b>	4 %
<b>Functional Class</b> 16 - Urban - Minor Arterial	

RDWY DIMENSIONS			
<b>If Divided</b>	<b>NB-EB</b>	<b>SB-WB</b>	
<b>Roadway Width</b>	57.00	ft.	ft.
<b>Vertical Clearance</b>		ft.	ft.
<b>Max. Vert. Clear.</b>		ft.	ft.
<b>Horizontal Clear.</b>	56.9	ft.	ft.
<b>Lateral Clearance</b>		ft.	ft.
<b>Appr. Surface Width</b>	54.0	ft.	
<b>Bridge Roadway Width</b>	57.0	ft.	
<b>Median Width On Bridge</b>		ft.	

MISC. BRIDGE DATA	
<b>Structure Flared</b>	0 - No flare
<b>Parallel Structure</b>	N - No parallel structure
<b>Field Conn. ID</b>	4 - Bolted
<b>Abutment Foundation</b>	1 - CONC
<b>(Material/Type)</b>	0 - UNKNOWN
<b>Pier Foundation</b>	1 - CONC
<b>(Material/Type)</b>	0 - UNKNOWN
<b>Historic Status</b>	5 - Not eligible

PAINT	
<b>Year Painted</b>	1986
<b>Unsound Paint %</b>	10
<b>Painted Area</b>	9080 sq. ft.
<b>Primer Type</b>	D - Organic Zinc - 3309
<b>Finish Type</b>	G - Chorinated Rubber Alum

BRIDGE SIGNS	
<b>Posted Load</b>	0 - Not Required
<b>Traffic</b>	0 - Not Required
<b>Horizontal</b>	0 - Not Required
<b>Vertical</b>	N - Not Applicable

INSPECTION	
<b>Userkey</b>	102
<b>Unofficial Structurally Deficient</b>	N
<b>Unofficial Functionally Obsolete</b>	N
<b>Unofficial Sufficiency Rating</b>	94.8
<b>Routine Inspection Date</b>	11/05/2015
<b>Routine Inspection Frequency</b>	24
<b>Inspector Name</b>	County, Ramsey
<b>Status</b>	A - Open

NBI CONDITION RATINGS	
<b>Deck</b>	6 - Satisfactory Condition
<b>Unsound Deck %</b>	
<b>Superstructure</b>	6 - Satisfactory Condition
<b>Substructure</b>	7 - Good Condition
<b>Channel</b>	N - Not Applicable
<b>Culvert</b>	N - Not Applicable

NBI APPRAISAL RATINGS	
<b>Structure Evaluation</b>	6
<b>Deck Geometry</b>	9
<b>Underclearances</b>	9
<b>Water Adequacy</b>	N - Not Applicable
<b>Approach Alignment</b>	7 - Better than present minir

SAFETY FEATURES	
<b>Bridge Railing</b>	1 - MEETS STANDARDS
<b>GR Transition</b>	0 - SUBSTANDARD
<b>Appr. Guardrail</b>	0 - SUBSTANDARD
<b>GR Termini</b>	N - NOT REQUIRED

IN DEPTH INSP.			
	Y/N	Freq	Date
<b>Frac. Critical</b>			
<b>Underwater</b>			
<b>Pinned Asbly.</b>			
<b>Spec. Feat.</b>			

WATERWAY	
<b>Drainage Area (sq. mi.)</b>	
<b>Waterway Opening</b>	sq. ft.
<b>Navigation Control</b>	N - Not applicable, no waterw
<b>Pier Protection</b>	
<b>Nav. Clr. (ft.)</b>	Vert. ft. Horiz. ft.
<b>Nav. Vert. Lift Bridge Clear. (ft.)</b>	
<b>MN Scour Code</b>	A - NON WATER' Year

CAPACITY RATINGS		
<b>Design Load</b>	5 - HS 20	
<b>Operating Rating</b>	1 - LF (LF)	HS 33.6
<b>Inventory Rating</b>	1 - LF (LF)	HS 20.2
<b>Posting VEH:</b>	<b>SEMI:</b>	<b>DBL:</b>
<b>Rating Date</b>	10/25/2013	

MnDOT Permit Codes	
<b>A:</b>	1 - No Restriction
<b>B:</b>	1 - No Restriction
<b>C:</b>	1 - No Restriction

# MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 62001

RICE ST over BNSF RR

Date: 01/07/2016

**MnDOT BRIDGE INSPECTION REPORT**

01/07/2016

Inspector: County, Ramsey

**BRIDGE 62001 RICE ST OVER BNSF RR**

**ROUTINE INSP. DATE: 11/05/2015**

County: Ramsey	Location: 0.6 MI S OF JCT TH 694	Length: 134.5 ft.
City: Little Canada	Route: 04 - CSAH 49 Ref. Pt.: 005+00.513	Deck Width: 71.3 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 7664 sq. ft. / %
Section: 6 Township: 029N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: 9080 sq. ft. / 10%
Span Type: 4 - Steel Continuous 02 -	Local Agency Bridge Nbr.:	Culvert: N/A
List: Stringer/Multi-beam or Girder		Postings:
NBI Deck: 6 Super: 6 Sub: 7 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 7 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 94.8

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
107	Painted Steel Girder or Beam	2	Routine	11/05/2015	1073 LF	805	268	0	0	0
			Routine	11/14/2013	1073 LF	805	268	0	0	0

Requires Monitoring  Monitored

Notes: Rust on bottom flange NE corner at abutment 2015  
 There is 25% in condition 2 2005-2015.  
 Minor paint failure on fascia 1999-2015.  
 24" deep rolled beams. Organic Zinc/Chlorinated Rubber Aluminum paint system 1987.

205	Reinforced Concrete Column	2	Routine	11/05/2015	8 EA	0	8	0	0	N/A
			Routine	11/14/2013	8 EA	0	8	0	0	N/A

Requires Monitoring  Monitored

Notes: There were consolidation issues due to construction procedures 2007-2015.  
 There is evidence of corrosion at the column 1 2005-2015.  
 Superficial hairline cracks with occasional spalls 2003-2015.  
 Columns have RR crash struts.

215	Reinforced Concrete Abutment	2	Routine	11/05/2015	144 LF	123	22	0	0	N/A
			Routine	11/14/2013	144 LF	123	22	0	0	N/A

Requires Monitoring  Monitored

Notes: There are 2 spalls with corrosion @ SW corner back wall 2015.  
 There is a 2' moderate crack on the face of the north abutment between girders 4 & 5 2015.  
 Moderate crack in back wall between beams 5 & 6 by construction joint 2013-2015  
 There is minor corrosion NW corner @ backwall 2007-2015.  
 There are 4 minor vertical cracks & minor deterioration of 2 expansion joints @ south abutment 2003-2015.  
 There are 2 -6" areas of delamination with corrosion @ SW corner backwall 2003-2013.  
 The north abutment has minor deterioration of 2 expansion joints @ bridge seat and backwall 2003-2015.  
 There are minor horizontal and vertical cracking @ backwall north side 2003-2015.  
 The north abutment has 6 minor - moderate vertical cracks 2009-2015.  
 15% is condition state 2 2009-2011.  
 10% is condition state 2 2005-2007.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
234	Reinforced Concrete Pier Cap	2	Routine	11/05/2015	144 LF	0	144	0	0	N/A
			Routine	11/14/2013	144 LF	0	144	0	0	N/A

Requires Monitoring  Monitored

Notes: There is evidence of corrosion and cracking at column 8 2011-2015.  
 There is minor cracking @ column 5 2007-2015.  
 Minor cracking with occasional spalls 2003-2015.  
 There were consolidation issues due to construction procedures 2007.

300	Strip Seal Deck Joint	2	Routine	11/05/2015	141 LF	0	141	0	N/A	N/A
			Routine	11/14/2013	141 LF	0	141	0	N/A	N/A

Requires Monitoring  Monitored

Notes: 100% in condition state 2 -2011-2015.  
 Minor corrosion of steel 2005-2015.  
 Strip seal exp. joints have leakage at both ends of bridge. 2005-2015  
 Needs to be flushed & cleaned for further inspection 2003-2015.  
 Previous inspections - Leakage at gutter line 1988. Also leak at centerline south side 2001.  
 Strip seals (Type "H") at abutments.

301	Poured Deck Joint	2	Routine	11/05/2015	141 LF	0	141	0	N/A	N/A
			Routine	11/14/2013	141 LF	0	141	0	N/A	N/A

Requires Monitoring  Monitored

Notes: Moderate leakage. Should be replaced @ both ends 2007-2015.  
 Minor leakage. Adhesion & cohesion failures are present 2003-2005.

310	Elastomeric (Expansion) Bearing	2	Routine	11/05/2015	20 EA	19	1	0	N/A	N/A
			Routine	11/14/2013	20 EA	19	1	0	N/A	N/A

Requires Monitoring  Monitored

Notes: Minor evidence of corrosion exists at the SW corner 2005-2015.  
 No evidence of deterioration 2003.

311	Expansion Bearing	2	Routine	11/05/2015	20 EA	19	4	0	N/A	N/A
			Routine	11/14/2013	20 EA	19	1	0	N/A	N/A

Requires Monitoring  Monitored

Notes: Minor evidence of corrosion exists at the SW corner 2005-2013.  
 Little evidence of deterioration exists 2003.

313	Fixed Bearing	2	Routine	11/05/2015	12 EA	12	0	0	N/A	N/A
			Routine	11/14/2013	12 EA	12	0	0	N/A	N/A

Requires Monitoring  Monitored

Notes: Little evidence of deterioration exists 2003-2015.  
 Interior pier bearings (both piers) are fixed.

## Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
321	Concrete Approach Slab-Concrete Wearing Surface	2	Routine	11/05/2015	2 EA	0	2	0	0	N/A
			Routine	11/14/2013	2 EA	0	2	0	0	N/A

 Requires Monitoring Monitored

Notes: There is longitudinal cracking at expansion joints 2005-2015.  
 Minor - moderate spalls present on both approaches 2003-2015.  
 New bituminous mill & overlay in 2009. There is still traffic impact on the north approach slab due to bituminous match 2009.  
 [1993-2007] Bituminous roadway is low at approaches.

333	Masonry, Other or Combination Material Railing	2	Routine	11/05/2015	269 LF	0	269	0	N/A	N/A
			Routine	11/14/2013	269 LF	0	269	0	N/A	N/A

 Requires Monitoring Monitored

Notes: There are numerous moderate size cracks & spalls with evidence of corrosion - both sides 2007-2015.  
 100% in condition 2 2005-2015.  
 SW corner @ post has been patched but is cracking 2003-2015.  
 Fence on the west side has been pushed out by plows at two locations 2011.  
 Minor but numerous cracks and spalls 2001-2007.  
 SW corner post has 1 SF spall 1992-2003.  
 Rail Type: Code #21.

358	Concrete Deck Cracking Smart Flag	2	Routine	11/05/2015	1 EA	0	1	0	0	N/A
			Routine	11/14/2013	1 EA	0	1	0	0	N/A

 Requires Monitoring Monitored

Notes: There are numerous transverse cracking extending inward from the sidewalk from both sides 2009-2015.  
 There is a moderate cracking all the way across @ mid span 2009-2015.  
 There is some minor - moderate transverse cracking @ mid span 2007.  
 Minor cracking 2003-2005.  
 SBL: repaired area @ center of bridge 1992.

359	Underside of Concrete Deck Smart Flag	2	Routine	11/05/2015	1 EA	0	1	0	0	0
			Routine	11/14/2013	1 EA	0	1	0	0	0

 Requires Monitoring Monitored

Notes: There is a 6" X 6" spall at the north abutment at beam 8 2015  
 there is a 3' X 1' spall between beam 5 & 6 and a 2' X 2' spall with exposed rebar between beam 1 & 2 above the tracks 2015  
 There is delamination @ center of bridge (5' x 2') 2013-2015  
 There is a spall with exposed rebar between beams 7 & 8 above tracks (2' x 1') 2013-2015  
 There are 2 transverse cracks @ mid span entire width. Some delamination is beginning 2011 - 2015.  
 There are numerous transverse cracking extending inward from both sides 2009-2015.  
 South abut. - pier has 80 LF of cracks, between piers 225 LF of cracks and from pier - no. abut. 64 LF of cracks for a total of 369 LF of transverse cracks with leaching & efflorescence 2011 - 2015.  
 There is a transverse crack @ mid span entire width 2007-2009.  
 Previous inspections - There are 3 cracks west side & 5 cracks east side 2007.  
 Transverse cracking with efflorescence and minor rusting. Mostly at center bridge entire width 2001.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
377	Low Slump O/L (Concrete Deck with Epoxy Rebar)	2	Routine	11/05/2015	9591 SF	0	9591	0	0	0
			Routine	11/14/2013	9591 SF	0	9591	0	0	0

Requires Monitoring  Monitored

Notes: There is a 1' X6" spall in the SB lane 2015.  
 There is transverse cracking throughout deck 2011-2015.  
 There are numerous transverse extending into the deck from the sidewalk on both sides 2009-2015.  
 There is a moderate size transverse crack the full width @ mid span 2009-2015.  
 There is a 12' moderate size transverse crack @ northbound mid span east side 2007.  
 There is a 6' minor size transverse crack 4' north of the mid span crack 2007.  
 Minor longitudinal & transverse cracking 2002-2005.

380	Secondary Structural Elements	1	Routine	11/05/2015	2 EA	2	0	0	0	N/A
			Routine	11/14/2013						

Requires Monitoring  Monitored

Notes: Railroad struts along columns 2015

387	Reinforced Concrete Wingwall	1	Routine	11/05/2015	4 EA	0	4	0	0	N/A
			Routine	11/14/2013	4 EA	0	4	0	0	N/A

Requires Monitoring  Monitored

Notes: There is moderate spalling and cracking w/evidence of corrosion at NE wingwall 2011 - 2015.  
 There is minor vertical cracking @ NW wing wall 2011 - 2015.  
 There is spalling @ SE wingwall & NW wingwall 2007-2015.  
 SW abutment wing has minor cracking with occasional spalls and evidence of corrosion 2002-2015.  
 Abutment wings have minor cracking with occasional spalls and evidence of corrosion 2003-2005.

964	Critical Finding Smart Flag	2	Routine	11/05/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	11/14/2013	1 EA	1	0	N/A	N/A	N/A

Requires Monitoring  Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

981	Signing	2	Routine	11/05/2015	1 EA	1	0	0	0	0
			Routine	11/14/2013	1 EA	1	0	0	0	0

Requires Monitoring  Monitored

Notes: Horizontal clearance signs are in place 2003-2015.



## Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
982	Approach Guardrail	2	Routine	11/05/2015	1 EA	1	0	0	N/A	N/A
			Routine	11/14/2013	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: There is no crash attenuator for the guardrail system 2009-2015.  
Guardrail is in place at the NW corner 2003-2015.

984	Deck & Approach Drainage	2	Routine	11/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/14/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: There is some standing water @ NE approach panel 2009-2015.  
No drainage problems 2003-2007.

985	Slopes & Slope Protection	2	Routine	11/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/14/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Bituminous aggregate slopes. Some movement of aggregate. Moderate deterioration 2003-2015.

986	Curb & Sidewalk	2	Routine	11/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/14/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: There is a spall@ expansion joint NE corner 2015.  
Scrapes from snow plow on east & west sides 2013-2015.  
There are numerous moderate transverse cracks & spalls both sides 2009-2015.  
Minor cracking with spalls present 2003-2007. Cracking and settlement at sidewalk SW corner 2001-2015.  
There is some delamination @ expansion joint NE corner 2007-2013.  
North approach: right curb has 1 LF of spall (0.8' deep) 1992.

988	Miscellaneous Items	2	Routine	11/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/14/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Utility line conduit located between girders 7 & 8 2015.  
Graffiti on abutments, pier struts, columns, SE wing wall and girders 2003-2015.

General Notes: 2015 Bridge safety inspection was conducted by Dan Bodelson and Brian Essler on 11/5/2015.  
2013 Bridge safety inspection was conducted by Brian Essler and Dan Bodelson on 11/14/2013.  
2011 Bridge safety inspection was conducted by B. Wieman and D. Bodelson on 11/8/2011.  
BRIDGE #62001, YEAR 2000. Turnback to Ramsey County. Railroad Bridge Constructed in 1986-87. Ramsey County has ownership & responsibility.  
Bridge #62001, Railroad bridge constructed 1986-87. Mn/DOT ownership & responsibility. Photos 1999.  
188) One active RR track below. 6" gas main in east bay. [1999] Extensive graffiti below bridge.<BR><BR>[2009] Bridge safety inspection was completed by B. Wieman 10/23/2009.  
2007 Bridge safety inspection was completed by B. Wieman & B. Essler 8/20/2007.  
2005 Bridge safety inspection was completed by Bret Wieman. 9/26/2005.  
125) 3 lanes (including center turn lane). Low slump overlay (only top mat has epoxy rebar) 1987. Chaining found no delamination 1993. Underside of deck has 300 LF of transverse leaching cracks (some rust stains) - mostly in center of center span (photo in 1999). 186) [1988] Sidewalk has 60 LF of transverse cracks. 188) One active RR track below. 6" gas main in east bay. [1999] Extensive graffiti below bridge.  
\*BRIDGE #62001, YEAR 2000. Turnback to Ramsey County. Railroad Bridge Constructed in 1986-87. Ramsey County has

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
	ownership & responsibility. Bridge #62001, Railroad bridge constructed 1986-87.									
	58. Deck NBI: Moderate cracking & spalls.									
	36A. Brdg Railings NBI: Rail Type: Code #21.									
	36B. Transitions NBI:									
	36C. Appr Guardrail NBI:									
	36D. Appr Guardrail Terminal NBI:									
	59. Superstructure NBI: Corrosion on bottom flange fascia beams & at bearings.									
	60. Substructure NBI: Minor cracking. Isolated delamination & spalls.									
	61. Channel NBI: Not over water									
	62. Culvert NBI: Bridge									
	71. Waterway Adeq NBI: Not over water									
	72. Appr Roadway Alignment NBI: Minor sight distance problem due to vertical curve									
	Inventory Notes:									

\_\_\_\_\_  
 Brian Essler  
 Inspector's Signature

\_\_\_\_\_  
 Nicklaus Fischer  
 Reviewer's Signature

# Pictures



Photo 1 -



Photo 2 -

# Pictures



Photo 3 -



Photo 4 -

# Pictures



Photo 5 -



Photo 6 -

# Pictures




Photo 7 -



1. bearing NE cor..JPG



2. east side.JPG



3. looking north.JPG




4. looking south.JPG



5. spall & crack under deck.JPG



6. spalls by wing on SW cor..JPG



7. west side.JPG

## Culvert

Bridge No.: 62001

<b>Culvert</b>
----------------

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
<b>Culvert Overall:</b>	<b>NBI Item 62</b>	<u>N</u>	Bridge

MnDOT Scour Code: A - NON WATERWAY

<b>Waterway Inspection</b>
----------------------------

Item No.	Yes, No, NA or Not Visible	Description
1.	<u>        </u>	Is there a significant build-up of debris?
2.	<u>        </u>	Is there erosion of the embankment around the headwalls?
3.	<u>        </u>	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	<u>        </u>	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	<u>        </u>	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	<u>        </u>	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	<u>        </u>	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	<u>        </u>	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	<u>        </u>	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	<u>        </u>	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

**Notes:**

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On \_\_\_\_\_ By \_\_\_\_\_



**Channel**

Bridge No.: 62001

**Channel**

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
<b>Channel Overall:</b>	<b>NBI Item 61</b>	N	Not over water

**Bank Protection/Revetment**

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
<b>Upstream Bank Protection:</b>	_____	_____	_____
<b>Downstream Bank Protection:</b>	_____	_____	_____
<b>Bridge Revetment:</b>	_____	_____	_____
<b>MnDOT Scour Code:</b>	<u>A - NON WATERWAY</u>		

**Underwater Inspection**

**Underwater Inspection By Divers:** \_\_\_\_\_

**No. of Piers To Be Inspected:** \_\_\_\_\_

**Waterway Characteristics**

**Reference Point:** \_\_\_\_\_ **High Water Elev.:** \_\_\_\_\_ **Current Water Elev.:** \_\_\_\_\_

**Pile Tip Elev.:** \_\_\_\_\_ **Low Water Elev.:** \_\_\_\_\_ **Current Streambed Elev.:** \_\_\_\_\_

**Scour Hole Elev.:** \_\_\_\_\_ **Current Scour Hole Elev.:** \_\_\_\_\_

**Waterway Inspection: (Not applicable for culverts)**

<b>Item No.</b>	<b>Yes, No, NA or Not Visible</b>	<b>Description</b>
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. \_\_\_\_\_ Have the scour countermeasures been damaged or otherwise made ineffective?

**Notes:**

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On \_\_\_\_\_ By \_\_\_\_\_

## Scour POA

Bridge No.: 62001

<b>Scour POA</b>
------------------

1. Is POA on File? \_\_\_\_\_
2. Date of most recent POA: \_\_\_\_\_
3. Here is a link to MnDOT's Bridge Scour website for other resources:
  - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
  - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

### Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? \_\_\_\_\_

# Channel Section

## Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

## Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

**Distance Measured From:**

**Elev. of Ref. Pt:**

**Depth to Water Surface:**

**WS Elev:**

**Vertical Datum:**

**Comments:**

**Distance Measured From:**

**Elev. of Ref. Pt:**

**Depth to Water Surface:**

**WS Elev:**

**Vertical Datum:**

# Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



# BRIDGE STRUCTURAL ASSESSMENT REPORT

## PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62001	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 11/05/2015	STRUCTURE TYPE: Steel Continuous Stringer/Multi-beam or Girder
FACILITY CARRIED: RICE ST	FEATURES INTERSECTED: BNSF RR
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

- Was a critical finding identified during this inspection or upon structural review?  Yes  No
  - If selected "Yes" above, state briefly the finding(s):
- If a critical finding was identified, what is the current status?  Pending  
 Resolved  
 N/A
  - Briefly state actions taken:
- Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured.  Yes  No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating?  Yes  No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance       Monitoring Plan  
 Other       Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

**Bridge Office Reviewer**