


**2016 ROUTINE  
BRIDGE INSPECTION REPORT**



**BRIDGE # 62032  
CP RAIL over CSAH 49(RICE ST)**

**DISTRICT:** Metro

**COUNTY:** Ramsey

**CITY/TOWNSHIP:** Little Canada

**STATE:** Minnesota


**Date of Inspection:** 10/13/2016

**Equipment Used:**

**Owner:** County Highway Agency

**Inspected By:** Bodelson, Dan

**Report Written By:** Dan Bodelson  
**Report Reviewed By:** Nicklaus Fischer  
**Final Report Date:** 11/28/2016



# Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
STRUCTURE INVENTORY	3
ROUTINE INSPECTION DATA	4
ELEMENTS	7
PICTURES	11
MAINTENANCE	19
STRUCTURAL ASSESSMENT REPORT - ROUTINE	20

# Minnesota Structure Inventory Report

Bridge ID: 62032

CP RAIL

over CSAH 49(RICE ST)

Date: 11/28/2016

GENERAL	
<b>Agency Br. No.</b>	
District Metro	
<b>Maint. Area</b>	<b>Crew</b>
County 062 - Ramsey	
City Little Canada	
Township	
Desc. Loc. 0.5 MI S OF JCT TH 694	
Sect., Twp., Range 31 - 030N - 22W	
<b>Latitude</b>	<b>Deg 45 Min 2 Sec 17.80</b>
<b>Longitude</b>	<b>Deg 93 Min 6 Sec 22.30</b>
Custodian 02 - County Highway Agency	
Owner 02 - County Highway Agency	
<b>BMU Agreement</b>	
<b>Year Built</b>	1986
<b>MN Year Reconstructed</b>	
<b>FHWA Year Reconstructed</b>	
<b>MN Temporary Status</b>	
Bridge Plan Location 1 - CENTRAL	
Date Opened to Traffic	
On-Off System 0 - OFF	
Legislative District 54B	
ABC Suitable	

STRUCTURE	
<b>Service On</b> 2 - Railroad	
<b>Service Under</b> 1 - Highway, w/ or w/out ped.	
<b>Main Span Type</b>	
3 - Steel	05 - Thru Girder
<b>Main Span Detail</b>	
<b>Appr. Span Type</b>	
<b>Appr. Span Detail</b>	
<b>Skew</b>	74 L
<b>Culvert Type</b>	
<b>Barrel Length</b>	ft.
<b>Cantilever ID</b>	

NUMBER OF SPANS			
<b>MAIN:</b>	2	<b>APPR:</b>	0
<b>TOTAL:</b>	2		
<b>Main Span Length</b>	142.4	ft.	
<b>Structure Length</b>	315.0	ft.	
<b>Deck Width (Out-to-Out)</b>	22.0	ft.	
<b>Deck Material</b>	5 - Steel Plate (includes orthotr)		
<b>Wear Surf Type</b>	N - Not Applicable (applies onl		
<b>Wear Surf Install Year</b>			
<b>Wear Course/Fill Depth</b>	0.00	ft.	
<b>Deck Membrane</b>	0 - None		
<b>Deck Rebars</b>	N - Not Applicable (no deck)		
<b>Deck Rebars Install Year</b>			
<b>Structure Area (Out-to-Out)</b>	6930	sq. ft.	
<b>Roadway Area (Curb-to-Curb)</b>	sq. ft.		
<b>Sidewalk Width</b>	Lt 0.00	ft.	Rt 0.00
<b>Curb Height</b>	Lt 0.00	ft.	Rt 0.00
<b>Rail Type</b>	Lt NN		Rt NN

ROADWAY		
<b>Bridge Match ID (TIS)</b>		
Roadway O/U Key none		
<b>Route Sys</b>	<b>Number</b>	
<b>Roadway Name or Description</b>		
<b>Level of Service</b>		
<b>Roadway Type</b>		
<b>Control Section (TH Only)</b>		
<b>Reference Point</b>		
<b>Detour Length</b>	mi	
<b>Lanes</b>	<b>On</b>	<b>Under 2</b>
	<b>ADT</b>	<b>Year</b>
<b>HCACT</b>	0	<b>ADTT 0 %</b>
<b>Functional Class</b>		

RDWY DIMENSIONS		
<b>If Divided</b>	<b>NB-EB</b>	<b>SB-WB</b>
<b>Roadway Width</b>	ft.	ft.
<b>Vertical Clearance</b>	ft.	ft.
<b>Max. Vert. Clear.</b>	ft.	ft.
<b>Horizontal Clear.</b>	ft.	ft.
<b>Lateral Clearance</b>	ft.	ft.
<b>Appr. Surface Width</b>	ft.	
<b>Bridge Roadway Width</b>	ft.	
<b>Median Width On Bridge</b>	ft.	

MISC. BRIDGE DATA	
<b>Structure Flared</b>	0 - No flare
<b>Parallel Structure</b>	N - No parallel structure
<b>Field Conn. ID</b>	
<b>Abutment Foundation</b>	1 - CONC
<b>(Material/Type)</b>	0 - UNKNOWN
<b>Pier Foundation</b>	1 - CONC
<b>(Material/Type)</b>	0 - UNKNOWN
<b>Historic Status</b>	5 - Not eligible

PAINT	
<b>Year Painted</b>	1986
<b>Unsound Paint %</b>	30
<b>Painted Area</b>	50720 sq. ft.
<b>Primer Type</b>	D - Organic Zinc - 3309
<b>Finish Type</b>	H - Vinyl

BRIDGE SIGNS	
<b>Posted Load</b>	0 - Not Required
<b>Traffic</b>	0 - Not Required
<b>Horizontal</b>	0 - Not Required
<b>Vertical</b>	0 - Not Required

INSPECTION	
<b>Userkey</b>	102
<b>Unofficial Structurally Deficient</b>	N
<b>Unofficial Functionally Obsolete</b>	N
<b>Unofficial Sufficiency Rating</b>	-2
<b>Routine Inspection Date</b>	10/13/2016
<b>Routine Inspection Frequency</b>	12
<b>Inspector Name</b>	CO Bridge
<b>Status</b>	A - Open

NBI CONDITION RATINGS	
<b>Deck</b>	7 - Good Condition
<b>Unsound Deck %</b>	
<b>Superstructure</b>	7 - Good Condition
<b>Substructure</b>	6 - Satisfactory Condition
<b>Channel</b>	N - Not Applicable
<b>Culvert</b>	N - Not Applicable

NBI APPRAISAL RATINGS	
<b>Structure Evaluation</b> N	
<b>Deck Geometry</b>	N
<b>Underclearances</b>	6
<b>Water Adequacy</b>	N - Not Applicable
<b>Approach Alignment</b>	7 - Better than present minir

SAFETY FEATURES	
<b>Bridge Railing</b>	N - NOT REQUIRED
<b>GR Transition</b>	N - NOT REQUIRED
<b>Appr. Guardrail</b>	N - NOT REQUIRED
<b>GR Termini</b>	N - NOT REQUIRED

IN DEPTH INSP.			
	Y/N	Freq	Date
<b>Frac. Critical</b>	N		
<b>Underwater</b>	N		
<b>Pinned Asbly.</b>	N		
<b>Spec. Feat.</b>			

WATERWAY			
<b>Drainage Area (sq. mi.)</b>			
<b>Waterway Opening</b>	sq. ft.		
<b>Navigation Control</b>	N - Not applicable, no waterw		
<b>Pier Protection</b>			
<b>Nav. Clr. (ft.)</b>	<b>Vert.</b>	ft.	<b>Horiz.</b>
<b>Nav. Vert. Lift Bridge Clear. (ft.)</b>			
<b>MN Scour Code</b>	A - NON WATER'	<b>Year</b>	

CAPACITY RATINGS			
<b>Design Load</b>	8 - RAILROAD		
<b>Operating Rating</b>	5 - NRAP	80.0	
<b>Inventory Rating</b>	5 - NRAP	80.0	
<b>Posting VEH:</b>	<b>SEMI:</b>	<b>DBL:</b>	
<b>Rating Date</b>			
<b>Minnesota Permit Codes</b>			
A: N - N/A			
B: N - N/A			
C: N - N/A			

# Minnesota Structure Inventory Report

Bridge ID: 62032

CP RAIL over CSAH 49(RICE ST)

Date: 10/12/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
<b>Agency Br. No.</b> Crew <b>District</b> 05 <b>Maint. Area</b> <b>County</b> 062 - Ramsey <b>City</b> Little Canada <b>Township</b> <b>Desc. Loc.</b> 0.5 MI S OF JCT TH 694 <b>Sect., Twp., Range</b> 31 - 030N - 22W <b>Latitude</b> 45 ° 2 ' 17.80 " <b>Longitude</b> 93 ° 6 ' 22.30 " <b>Custodian</b> 02 - County Highway Agency <b>Owner</b> 02 - County Highway Agency <b>BMU Agreement</b> <b>Year Built</b> 1986 <b>MN Year Reconstructed</b> <b>FHWA Year Reconstructed</b> <b>MN Temporary Status</b> <b>Bridge Plan Location</b> 1 - CENTRAL <b>Date Opened to Traffic</b> <b>On - Off System</b> 0 - OFF <b>Legislative District</b> 54B <b>Potential ABC</b> 2 - N/A	<b>Bridge Match ID (TIS)</b> <b>Roadway O/U Key</b> <b>Route Sys</b> <span style="float: right;"><b>Number</b></span> <b>Roadway Name or Description</b> <b>Level of Service</b> <b>Roadway Type</b> <b>Control Section (TH Only)</b> <b>Reference Point</b> <b>Detour Length</b> <span style="float: right;">mi.</span> <b>Lanes</b> <b>ON</b> <b>UNDER</b> 2 <b>ADT</b> <b>YEAR</b> <b>HCA DT</b> <b>ADTT</b> % <b>Functional Class</b>	<b>Userkey</b> 102 <b>Structurally Deficient</b> N <b>Functionally Obsolete</b> N <b>Sufficiency Rating</b> -2 <b>Routine Inspection Date</b> 10/13/2016 <b>Routine Inspection Frequency</b> 12 <b>Inspector Name</b> Bodelson, Dan <b>Status</b> A - Open																				
	<b>+ RDWY DIMENSIONS +</b>	<b>+ NBI CONDITION RATINGS +</b>																				
	<b>If Divided</b> <b>NB-EB</b> <b>SB-WB</b> <b>Roadway Width</b> <span style="float: right;">ft. ft.</span> <b>Vertical Clearance</b> <span style="float: right;">ft. ft.</span> <b>Max. Vert. Clear.</b> <span style="float: right;">ft. ft.</span> <b>Horizontal Clear.</b> <span style="float: right;">ft. ft.</span> <b>Lateral Clearance</b> <span style="float: right;">ft. ft.</span> <b>Appr. Surface Width</b> <span style="float: right;">ft.</span> <b>Bridge Roadway Width</b> <span style="float: right;">ft.</span> <b>Median Width On Bridge</b> <span style="float: right;">ft.</span>	<b>Deck</b> 7 <b>Unsound Deck %</b> <b>Superstructure</b> 7 <b>Substructure</b> 6 <b>Channel</b> N <b>Culvert</b> N																				
<b>+ STRUCTURE +</b>	<b>+ MISC. BRIDGE DATA +</b>	<b>+ NBI APPRAISAL RATINGS +</b>																				
<b>Service On</b> 2 - Railroad <b>Service Under</b> 1 - Highway, w/ or w/out ped. <b>Main Span Type</b> 3 - Steel <b>Main Span Design</b> 05 - Thru Girder <b>Main Span Detail</b> <b>Appr. Span Type</b> <b>Appr. Span Design</b> <b>Appr. Span Detail</b> <b>Skew</b> 74 <b>LEFT</b> <b>Culvert Type</b> <b>Barrel Length</b> <b>Cantilever ID</b>  <b>Number of Spans</b> <b>MAIN: 2 APPR: 0 TOTAL:</b> <b>Main Span Length</b> 142.4 ft. <b>Structure Length</b> 315.0 ft. <b>Deck Width (Out-to-Out)</b> 22.0 ft. <b>Deck Material</b> 5 - Steel Plate (includes <b>Wear Surf Type</b> N - Not Applicable (applies <b>Wear Surf Install Year</b> <b>Wear Course/Fill Depth</b> 0.00 ft. <b>Deck Membrane</b> 0 - None <b>Deck Rebars</b> N - Not Applicable (no deck) <b>Deck Rebars Install Year</b> <b>Structure Area (Out-to-Out)</b> 6930 sq. ft. <b>Roadway Area (Curb-to-Curb)</b> sq. ft. <b>Sidewalk Width</b> 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. <b>Curb Height</b> Lt 0.00 ft. Rt 0.00 ft. <b>Rail Type</b> Lt NN Rt NN	<b>Structure Flared</b> 0 - No flare <b>Parallel Structure</b> N - No parallel structure <b>Field Conn. ID</b> <b>Abutment Foundation (Material/Type)</b> 1 - CONC <b>Pier Foundation (Material/Type)</b> 0 - UNKNOWN <b>Historic Status</b> 5 - Not eligible	<b>Structure Evaluation</b> N <b>Deck Geometry</b> N <b>Underclearances</b> 6 <b>Waterway Adequacy</b> N <b>Approach Alignment</b> 7																				
	<b>+ PAINT +</b>	<b>+ SAFETY FEATURES +</b>																				
	<b>Year Painted</b> 1986 <b>Unsound Paint %</b> 30 <b>Painted Area</b> 50720 sq. ft. <b>Primer Type</b> D - Organic Zinc - 3309 <b>Finish Type</b> H - Vinyl	<b>Bridge Railing</b> N - NOT REQUIRED <b>GR Transition</b> N - NOT REQUIRED <b>Appr. Guardrail</b> N - NOT REQUIRED <b>GR Termini</b> N - NOT REQUIRED																				
	<b>+ BRIDGE SIGNS +</b>	<b>+ IN DEPTH INSP. +</b>																				
	<b>Posted Load</b> 0 - Not Required <b>Traffic</b> 0 - Not Required <b>Horizontal</b> 0 - Not Required <b>Vertical</b> 0 - Not Required	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td><b>Frac. Critical</b></td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td><b>Underwater</b></td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td><b>Pinned Asbly.</b></td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td><b>Spec. Feat.</b></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	<b>Frac. Critical</b>	N			<b>Underwater</b>	N			<b>Pinned Asbly.</b>	N			<b>Spec. Feat.</b>			
	Y/N	Freq	Date																			
<b>Frac. Critical</b>	N																					
<b>Underwater</b>	N																					
<b>Pinned Asbly.</b>	N																					
<b>Spec. Feat.</b>																						
		<b>+ WATERWAY +</b>																				
		<b>Drainage Area (sq. mi.)</b> <b>Waterway Opening (sf.)</b> <b>Navigation Control</b> N - Not applicable, no <b>Pier Protection</b> - <b>Nav. Clr. (ft.)</b> <b>Vert.</b> 0.0 <b>Horiz.</b> 0.0 <b>Nav. Vert. Lift Bridge Clear. (ft.)</b> <b>MN Scour Code</b> A - NON  <b>+ CAPACITY RATINGS +</b> <b>Design Load</b> 8 - RAILROAD <b>Operating Rating</b> 7 - RAILROAD 80.0 <b>Inventory Rating</b> 7 - RAILROAD 80.0 <b>Posting VEH:</b> <b>SEMI:</b> <b>DBL:</b> <b>Rating Date</b> <b>Overweight Permit Codes</b> <b>A</b> N - N/A <b>B</b> N - N/A <b>C</b> N - N/A																				

**MINNESOTA BRIDGE INSPECTION REPORT**

11/28/2016

**BRIDGE 62032 CP RAIL OVER CSAH 49(RICE ST)**

**ROUTINE INSP. DATE: 10/13/2016**

County: Ramsey	Location: 0.5 MI S OF JCT TH 694	Length: 315.0 ft.
City: Little Canada	Route: Ref. Pt.:	Deck Width: 22.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 31 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: 50720 sq. ft. / 30%
Span Type: 3 - Steel 3 - Girder and Floorbeam	Local Agency Bridge Nbr.:	Culvert: N/A
List: System		Postings:
NBI Deck: 7 Super: 7 Sub: 6 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 7 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: 0 - Not Required	Unofficial Sufficiency Rating N

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
107	Painted Steel Girder or Beam	2	Routine	10/13/2016	630 LF	410	220	0	0	0
			Routine	10/14/2015	630 LF	410	220	0	0	0

Notes: [1999-2015] Minor chalking and paint failure present on both sides.  
 [2012-2015] The north side contains 35% peeling of paint with rusting near top of bottom flange.  
 [2012-2015] There is some flecking of paint on the south side.  
 There is graffiti @ top inside girders 2007-2011.  
 Two 130" deep welded steel "Through Girders" serve as railing.

152	Painted Steel Floorbeam	2	Routine	10/13/2016	2402 LF	1681	721	0	0	0
			Routine	10/14/2015	2402 LF	1681	721	0	0	0

Notes: [2012-2015] Approximately 30% of floor beams contains minor rusting.  
 24" deep rolled steel floorbeams (30" spacing) - the skewed end floorbeams have independent bearings.

210	Reinforced Concrete Pier Wall	2	Routine	10/13/2016	89 LF	0	89	0	0	N/A
			Routine	10/14/2015	89 LF	0	89	0	0	N/A

Notes: [2014-2015] 9 - minor vertical cracks on east side  
 [2014-2015] Reinforced Concrete Pier Wall contains numerous moderate spalls on both sides.  
 [2009-2015] The west side has 5 vertical cracks 18' each- two are near the construction joint.  
 [2011-2015] There is some scraping on the east side from County plows .  
 [2013] The east side has 6 minor horizontal cracks 80' each  
 [2009-2013] The east side has 8 vertical cracks 18' each- two are near the construction joint.  
 Utility line on west side of pier wall.

215	Reinforced Concrete Abutment	2	Routine	10/13/2016	180 LF	0	180	0	0	N/A
			Routine	10/14/2015	180 LF	0	180	0	0	N/A

Notes: [2015] moderate delamination of construction joints on both sides.  
 [2014-2015] East abutment has numerous minor cracks on north end, also some paint failure on SE corner  
 [2013-2015] East abutment has 50' minor horizontal cracks on south 1/2, 5' - 6' up from walk  
 [2013-2015] East abutment has 20' moderate horizontal cracks on south end, 2' - 3' up from walk  
 [2012-2015] East abutment has 8 X 15' = 120 LF of moderate vertical cracks with efflorescence.  
 [2014-2015] West abutment has 1' diagonal minor crack near parapet on south end  
 [2014-2015] 4" spall on west abutment 30' from north end  
 [2014-2015] scrapes on west abutment from snow plow  
 [2012-2015] West abutment has >200 LF of random moderate size cracks.  
 [2010-2015] West abutment has scrapes on west abutment from city plows.  
 [2011-2015] Moderate size spalling throughout. The north 10' of the West abutment has corrosion present .  
 [2012-2013] East abutment near SE corner has minor to moderate horizontal & vertical cracking with efflorescence.  
 [2012-2013] Both abutments contain moderate horizontal cracks & spalls. Minor deterioration of construction joints both sides.

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
311	Expansion Bearing	2	Routine	10/13/2016	20 EA	0	20	0	N/A	N/A
			Routine	10/14/2015	20 EA	0	20	0	N/A	N/A
Notes: [2012-2015] Moderate deterioration is present. [2002-2015] Vertical & horizontal alignment are within limits. Abutment bearings (and all floorbeam bearings) are expansion.										
313	Fixed Bearing	2	Routine	10/13/2016	4 EA	0	4	0	N/A	N/A
			Routine	10/14/2015	4 EA	0	4	0	N/A	N/A
Notes: [2013-2015] Evidence of moderate corrosion is present. Main girder pier bearings are fixed.										
387	Reinforced Concrete Wingwall	2	Routine	10/13/2016	4 EA	0	4	0	0	N/A
			Routine	10/14/2015	4 EA	0	4	0	0	N/A
Notes: [2013-2015]SE wing has 21' minor cracks w/effluence on east & west ends. [2002-2015] SE corner has minor vertical cracking w/deterioration of cork expansion joints. [2015] SW corner has 20 LF minor horizontal cracking with efflorescence and occasional spalls. [2013-2015] SW wing has 2' minor crack across top. [2014-2015] NE wingwall has 2 1' minor vertical cracks [2003-2015] NE corner has minor horizontal cracking w/spalls. [2007-2015] NW WW has delamination @ NW corner near abutment. NW corner has numerous horizontal & vertical cracking w/spalling and deterioration of cork expansion joints. Wingwalls have chain link fencing on top. [2004-2014] SW corner has 20 LF minor horizontal cracking with occasional spalls.										
401	Steel Ballast Plate Deck (Railroad Bridges)	1	Routine	10/13/2016	6932 SF	0	6932	0	0	0
			Routine	10/14/2015	6932 SF	0	6932	0	0	0
Notes: [2007-2015] Paint system has some failure- surface corrosion is present. Steel Ballast Plate Deck contains minor deck leakage. [2013-2015] Bridge #62032 has a 7/8" Steel ballast plate deck with rock ballast. [2009-2015] Two ballast plate clips missing near east and west ends. Eight ballast plate clips are loose & hanging. Recommend removal of ballast plate clips. Element #30 was deleted in 2007. Element #401 was created. There is one active railroad track.										
964	Critical Finding Smart Flag	2	Routine	10/13/2016	1 EA	1	0	N/A	N/A	N/A
			Routine	10/14/2015	1 EA	1	0	N/A	N/A	N/A
Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.										
981	Signing	2	Routine	10/13/2016	1 EA	0	1	0	0	0
			Routine	10/14/2015	1 EA	0	1	0	0	0
Notes: [2015] New 9 button at the south side pier wall. [2004-2015] No horizontal clearance sign at SW corner. [2009-2014] Crash attenuators are OK. 9 button at the south side pier wall is bent. Crash attenuators have been repaired in 2007. Damage to signs at crash attenuators due to traffic impact in 2004.										
982	Approach Guardrail	2	Routine	10/13/2016	1 EA	0	1	0	N/A	N/A
			Routine	10/14/2015	1 EA	0	1	0	N/A	N/A
Notes: [2015] Crash attenuator are in good condition. [2014] The south attenuator has been damaged [2010-2013] Guardrail system is present and good condition. Crash attenuator have been repaired in 2015. Crash attenuators have been replaced at both sides of bridge in 2007. Replaced with Quadguard Type I & Type II. Crash attenuators have been damaged at both ends of piers in 2004.										

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
984	Deck & Approach Drainage	2	Routine	10/13/2016	1 EA	1	0	0	N/A	N/A
			Routine	10/14/2015	1 EA	1	0	0	N/A	N/A

Notes: [2003-2015] Drainage system is functioning properly.

985	Slopes & Slope Protection	2	Routine	10/13/2016	1 EA	1	0	0	N/A	N/A
			Routine	10/14/2015	1 EA	1	0	0	N/A	N/A

Notes: [2015] Moderate erosion at NE wingwall. minor settlement at all others.  
[2003-2014] Slope protection is OK. Some minor settlement near wingwalls.

General Notes: [2016] Bridge safety inspection was completed by Brian Essler & Dan Bodelson & Randy Bussiere on 10/13/2016.  
[2015] Bridge safety inspection was completed by Brian Essler & Dan Bodelson on 10/14/2015.  
[2014] Bridge safety inspection was completed by Dan Bodelson & Brian Essler on 10/17/2014.  
[2014] New tracks & ballast were installed by Railroad this summer  
[2013] Bridge safety inspection was completed by Dan Bodelson & Brian Essler on 10/25/2013.  
[2012] Bridge safety inspection was completed by B. Wieman on 10/30/2012.  
2011 Bridge safety inspection was completed by B. Wieman and D Bodelson on 10/28/2011. Lateral bracing is in place. No sign of collision damage 2011.  
2010 Bridge safety inspection was completed by B. Wieman and D Bodelson 12/3/2010.  
2009 Bridge safety inspection was completed by B. Wieman on 10/26/2009.  
2007 Bridge safety inspection was completed by B. Wieman and B. Essler 8/21/2007.  
2006 Bridge safety inspection was completed by Bret Wieman and Dan Bodelson 10/30/2006.  
\*BRIDGE #62032, YEAR 2000 - Turnback to Ramsey County. Ramsey County has ownership & maintenance responsibility.  
\*BRIDGE #62032, YEAR 1999 Railroad Bridge Constructed in 1986-87. Mn/DOT has ownership & maintenance responsibility.  
[1999] Photos.

58. Deck NBI: Moderate paint failure and minor corrosion

36A. Brdg Railings NBI: Railroad bridge over roadway

36B. Transitions NBI: Railroad bridge over roadway

36C. Appr Guardrail NBI: Railroad bridge over roadway

36D. Appr Guardrail  
Terminal NBI: Railroad bridge over roadway

59. Superstructure NBI: Moderate paint failure and minor corrosion

60. Substructure NBI: Moderate cracks, delamination and spalls

61. Channel NBI: Not over water

62. Culvert NBI: Bridge

71. Waterway Adeq NBI: Not over water

72. Appr Roadway  
Alignment NBI: Minor sight distance problem with no speed reduction

Inventory Notes:

Dan Bodelson  
Inspector's Signature

Nicklaus Fischer  
Reviewer's Signature

# MINNESOTA BRIDGE INSPECTION REPORT

11/28/2016

Inspector: CO Bridge

## BRIDGE 62032 CP RAIL OVER CSAH 49(RICE ST)

County: Ramsey	Location: 0.5 MI S OF JCT TH 694	Length: 315.0 ft.
City: Little Canada	Route: Ref. Pt.:	Deck Width: 22.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 31 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: 50720 sq. ft. / 30%
Span Type: 3 - Steel 3 - Girder and Floorbeam	Local Agency Bridge Nbr.:	Culvert: N/A
List: System		Postings:
NBI Deck: 7 Super: 7 Sub: 6 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	

Appraisal Ratings - Approach: 7 Waterway: N	Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Unofficial Sufficiency Rating N
Traffic: 0 - Not Required	
Vertical: 0 - Not Required	

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
30	Steel Deck Corrugated/Orthotropic/Etc.	Routine	10/13/2016	6930 SF	6791	0	139	0
		Migrated Values		6930 SF	6791	0	139	0
	Notes: [2007-2016] Paint system has some failure- surface corrosion is present. Steel Ballast Plate Deck contains minor deck leakage. [2013-2016] Bridge #62032 has a 7/8" Steel ballast plate deck with rock ballast. [2009-2016] Two ballast plate clips missing near east and west ends. Eight ballast plate clips are loose & hanging. Recommend removal of ballast plate clips. Element #30 was deleted in 2007. Element #401 was created. There is one active railroad track.							
	510 - Wearing Surfaces	Routine	10/13/2016	6930 SF	6930	0	0	0
		Migrated Values		6930 SF	6930	0	0	0
	Notes: [2016] Migrator assumed CS1. Railroad bridge - no wearing surface.							
107	Steel Open Girder/Beam	Routine	10/13/2016	630 LF	410	220	0	0
		Migrated Values		630 LF	410	220	0	0
	Notes: [1999-2016] Minor chalking and paint failure present on both sides. [2012-2016] The north side contains 35% peeling of paint with rusting near top of bottom flange. [2012-2016] There is some flaking of paint on the south side. There is graffiti @ top inside girders 2007-2011. Two 130" deep welded steel "Through Girders" serve as railing.							
	515 - Steel Protective Coating	Routine	10/13/2016	32550 SF	21158	11392	0	0
		Migrated Values		32550 SF	21158	11392	0	0
	Notes: [2016] Migrator used inventory quantity of 50,720 SF and estimated the condition states. [2016] 2 thru girders - 11' + 11' + 1.5' + 1.5' + 1.5' + 1.5' = 28' x 315' long = 8820 SF x 2 = 17,640 SF 2 thru girders - 315' x 11' high = 3465 SF x 2 = 6930 SF x 2 sides = 13,860 SF 60 - knee bracing - (2.0' + 0.5')/2 x 7 = 8.75 SF x 2 sides = 17.5 SF each x 60 = 1050 SF Total = 32,550 SF 35% in condition state 2, 65% in condition state 1							
152	Steel Floor Beam	Routine	10/13/2016	2402 LF	1681	721	0	0
		Migrated Values		2402 LF	1681	721	0	0
	Notes: [2012-2016] Approximately 30% of floor beams contains minor rusting. 24" deep rolled steel floorbeams (30" spacing) - the skewed end floorbeams have independent bearings.							
	515 - Steel Protective Coating	Routine	10/13/2016	26629 SF	18640	7989	0	0
		Migrated Values		26629 SF	18640	7989	0	0
	Notes: [2016] Migrator assumed quantity of 999 SF and estimated the condition states. 136 - floor beams - 2.25' + 2.25' + 1.1' + 1.1' + 1.1' + 1.1' = 8.9' x 22' long = 195.8 SF x 136 = 26,629 SF [2016] 30% in condition state 2, 70% in condition state 1.							



**BRIDGE 62032 CP RAIL OVER CSAH 49(RICE ST)**

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
210	Reinforced Concrete Pier Wall	Routine	10/13/2016	89 LF	0	89	0	0
		Migrated Values		89 LF	0	89	0	0
<p>Notes: [2014-2016] 9 - minor vertical cracks on east side                      [2012-2016] Reinforced Concrete Pier Wall contains numerous moderate spalls on both sides.                      [2009-2016] The west side has 5 vertical cracks 18' each- two are near the construction joint.                      [2011-2016] There is some scraping on the east side from County plows .                      [2013] The east side has 6 minor horizontal cracks 80' each                      [2009-2013] The east side has 8 vertical cracks 18' each- two are near the construction joint.                      Utility line on west side of pier wall.</p>								
215	Reinforced Concrete Abutment	Routine	10/13/2016	462 LF	40	422	0	0
		Migrated Values		462 LF	40	422	0	0
<p>Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:0 CS2:40 CS3:0 CS4:0).                      [2016]Wingwalls - SW = 23', SE = 84', NW = 116', NE = 19'. Ttotal = 242 LF + 180' abutments = 422 LF                      [2016] moderate delamination of construction joints on both sides.                      [2014-2016] East abutment has numerous minor cracks on north end, also some paint failure on SE corner                      [2013-2016] East abutment has 50' minor horizontal cracks on south 1/2, 5' - 6' up from walk                      [2013-2016] East abutment has 20' moderate horizontal cracks on south end, 2' - 3' up from walk also some moderate spalling with rust stains.                      [2012-2016] East abutment has 8 X 15' = 120 LF of moderate vertical cracks with efflorescence.                      [2014-2016] West abutment has 1' diagnol minor crack near parapet on south end                      [2014-2016] 4" spall on west abutment 30' from north end                      [2014-2016] scrapes on west abutment from snow plow                      [2012-2016] West abutment has &gt;200 LF of random moderate size cracks.                      [2010-2016] West abutment has scrapes with moderate spalling from city plows.                      [2011-2016] Moderate size spalling throughout. The north 10' of the West abutment has corrosion present .                      [2012-2013] East abutment near SE corner has minor to moderate horizontal &amp; vertical cracking with efflorescence.                      [2012-2013] Both abutments contain moderate horizontal cracks &amp; spalls. Minor deterioration of construction joints both sides.</p> <p>Wingwall notes: [2013-2016]SE wing has 21' minor cracks w/effluence on east &amp; west ends with minor spalls.                      [2002-2016] SE corner has minor vertical cracking w/deterioration of cork expansion joints.                      [2015-2016] SW corner has 20 LF minor horizontal cracking with efflorescence and occasional spalls.                      [2013-2016] SW wing has 2' minor crack across top.                      [2014-2016] NE wingwall has 2 1' minor vertical cracks                      [2003-2016] NE corner has minor horizontal cracking w/spalls.                      [2007-2016] NW WW has 3' x 1' spall @ SW corner near abutment. NW corner has numerous horizontal &amp; vertical cracking w/spalling and deterioration of cork expansion joints.                      Wingwalls have chain link fencing on top.                      [2004-2014] SW corner has 20 LF minor horizontal cracking with occasional spalls.</p>								
311	Movable Bearing	Routine	10/13/2016	20 EA	0	20	0	0
		Migrated Values		20 EA	0	20	0	0
<p>Notes: [2012-2016] Moderate deterioration is present.                      [2002-2016] Vertical &amp; horizontal alignment are within limits.                      Abutment bearings (and all floorbeam bearings) are expansion.</p>								
313	Fixed Bearing	Routine	10/13/2016	4 EA	0	4	0	0
		Migrated Values		4 EA	0	4	0	0
<p>Notes: [2013-2016] Evidence of moderate corrosion is present.                      Main girder pier bearings are fixed.</p>								
800	Critical Deficiencies or Safety Hazards	Routine	10/13/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION.</p>								
891	Other Bridge Signing	Routine	10/13/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
<p>Notes: [2015] New 9 button at the south side pier wall.                      [2004-2016] No horizontal clearance sign at SW corner.                      [2009-2014] Crash attenuators are OK. 9 button at the south side pier wall is bent.                      Crash attenuators have been repaired in 2007.                      Damage to signs at crash attenuators due to traffic impact in 2004.</p>								

**BRIDGE 62032 CP RAIL OVER CSAH 49(RICE ST)**

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
892	Slopes & Slope Protection	Routine	10/13/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: [2015-2016] Moderate erosion at NE wingwall. minor settlement at all others. [2003-2014] Slope protection is OK. Some minor settlement near wingwalls.								
893	Guardrail	Routine	10/13/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2015-2016] Crash attenuator are in good condition. [2014] The south attenuator has been damaged [2010-2013] Guardrail system is present and good condition. Crash attenuator have been repaired in 2015. Crash attenuators have been replaced at both sides of bridge in 2007. Replaced with Quadguard Type I & Type II. Crash attenuators have been damaged at both ends of piers in 2004.								
894	Deck & Approach Drainage	Routine	10/13/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: [2003-2016] Drainage system is functioning properly.								
900	Protected Species	Routine	10/13/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure. [2016] No protective species found.								

General Notes: [2016] Bridge safety inspection was completed by Brian Essler & Dan Bodelson & Randy Bussiere on 10/13/2016.  
 [2015] Bridge safety inspection was completed by Brian Essler & Dan Bodelson on 10/14/2015.  
 [2014] Bridge safety inspection was completed by Dan Bodelson & Brian Essler on 10/17/2014.  
 [2014] New tracks & ballast were installed by Railroad this summer  
 [2013] Bridge safety inspection was completed by Dan Bodelson & Brian Essler on 10/25/2013.  
 [2012] Bridge safety inspection was completed by B. Wieman on 10/30/2012.  
 2011 Bridge safety inspection was completed by B. Wieman and D Bodelson on 10/28/2011. Lateral bracing is in place. No sign of collision damage 2011.  
 2010 Bridge safety inspection was completed by B. Wieman and D Bodelson 12/3/2010.  
 2009 Bridge safety inspection was completed by B. Wieman on 10/26/2009.  
 2007 Bridge safety inspection was completed by B. Wieman and B. Essler 8/21/2007.  
 2006 Bridge safety inspection was completed by Bret Wieman and Dan Bodelson 10/30/2006.  
 \*BRIDGE #62032, YEAR 2000 - Turnback to Ramsey County. Ramsey County has ownership & maintenance responsibility.  
 \*BRIDGE #62032, YEAR 1999 Railroad Bridge Constructed in 1986-87. Mn/DOT has ownership & maintenance responsibility.  
 [1999] Photos.

- 58. Deck NBI: Moderate paint failure and minor corrosion
  - 36A. Brdg Railings NBI: Railroad bridge over roadway
  - 36B. Transitions NBI: Railroad bridge over roadway
  - 36C. Appr Guardrail NBI: Railroad bridge over roadway
  - 36D. Appr Guardrail Terminal NBI: Railroad bridge over roadway
  - 59. Superstructure NBI: Moderate paint failure and minor corrosion
  - 60. Substructure NBI: Moderate cracks, delamination and spalls
  - 61. Channel NBI: Not over water
  - 62. Culvert NBI: Bridge
  - 71. Waterway Adeq NBI: Not over water
  - 72. Appr Roadway Alignment NBI: Minor sight distance problem with no speed reduction
- Inventory Notes:

**BRIDGE 62032 CP RAIL OVER CSAH 49(RICE ST)**

---

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
-------------	--------------	-------------	------------	----------	-------------	-------------	-------------	-------------

---

Dan Bodelson  
Inspector's Signature

---

Nicklaus Fischer  
Reviewer's Signature

---

# Pictures




Photo 1 -



Photo 2 -

# Pictures



Photo 3 -



Photo 4 -



# Pictures



Photo 5 -



Photo 6 -

# Pictures



Photo 7 -



Photo 8 -

# Pictures



Photo 9 -



Photo 10 -



# Pictures



Photo 11 -



Photo 12 -

# Pictures




Photo 13 -




Photo 14 -



# Pictures



Photo 15 -



Photo 16 -

# Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------

# BRIDGE STRUCTURAL ASSESSMENT REPORT

**PURPOSE:**

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the Minnesota Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62032	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 10/13/2016	STRUCTURE TYPE: Steel Order and Floorbeam System
FACILITY CARRIED: CP RAIL	FEATURES INTERSECTED: CSAH 49(RICE ST)
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> COMPLEX:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review?  Yes       No
  - a) If selected "Yes" above, state briefly the finding(s):
  
2. If a critical finding was identified, what is the current status?  Pending  
 Resolved  
 N/A
  - a) Briefly state actions taken:
  
3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured.  Yes       No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating?  Yes  No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- |   |   |
|---|---|
| <input type="checkbox"/> Repair/Maintenance | <input type="checkbox"/> Monitoring Plan                |
| <input type="checkbox"/> Complex            | <input type="checkbox"/> Increased Inspection Frequency |

Explain recommended actions:

6. Other comments:

**Bridge Office Reviewer**