

**2015 ROUTINE  
BRIDGE INSPECTION REPORT**



**BRIDGE # 62079  
CO Road E (CSAH 15 over BNSF RR)**

**DISTRICT: Metro**

**COUNTY: Ramsey**

**CITY/TOWNSHIP: WHITE BEAR  
LAKE**

**Date(s) of Inspection: 11/12/2015**

**Equipment Used:**

**Owner: County Highway Agency**

**Inspected By: Bodelson, Dan; Essler, Brian**

**Report Written By: Dan Bodelson**

**Report Reviewed By: Nicklaus Fischer**

**Final Report Date: 01/05/2016**

**MnDOT Bridge Office  
3485 Hadley Avenue North  
Oakdale, MN 55128**



# Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	10
THUMBNAIL PICTURES	14
CULVERT	15
CHANNEL	16
SCOUR POA	18
CHANNEL X-SECTION	19
MAINTENANCE	20
STRUCTURAL ASSESSMENT REPORT - ROUTINE	21

# MnDOT Structure Inventory Report

Bridge ID: 62079

CO Road E (CSAH 15

over BNSF RR

Date: 01/05/2016

GENERAL			
<b>Agency Br. No.</b>			
District Metro			
<b>Maint. Area</b>		<b>Crew</b>	
County 062 - Ramsey			
City WHITE BEAR LAKE			
Township			
Desc. Loc. 0.2 MI E OF JCT TH 61			
<b>Sect., Twp., Range</b>		34 - 030N - 22W	
<b>Latitude Deg</b>	45	<b>Min</b>	3
<b>Sec</b>	1.07		
<b>Longitude Deg</b>	93	<b>Min</b>	1
<b>Sec</b>	57.75		
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
<b>BMU Agreement</b>			
<b>Year Built</b>		1977	
<b>MN Year Reconstructed</b>			
<b>FHWA Year Reconstructed</b>			
<b>MN Temporary Status</b>			
<b>Bridge Plan Location</b> 1 - CENTRAL			
<b>Date Opened to Traffic</b> 1/1/1977			
<b>On-Off System</b> 1 - ON			
<b>Legislative District</b> 54B			

STRUCTURE	
<b>Service On</b>	5 - Highway-pedestrian
<b>Service Under</b>	2 - Railroad
<b>Main Span Type</b>	
5 - Prestress or Precast 01 - Beam Span	
<b>Main Span Detail</b>	
<b>Appr. Span Type</b>	
<b>Appr. Span Detail</b>	
<b>Skew</b>	10 R
<b>Culvert Type</b>	
<b>Barrel Length</b>	ft.
<b>Cantilever ID</b>	

NUMBER OF SPANS		
<b>MAIN:</b>	3	<b>TOTAL:</b> 3
<b>APPR:</b>	0	
<b>Main Span Length</b>	50.8	ft.
<b>Structure Length</b>	154.0	ft.
<b>Deck Width (Out-to-Out)</b>	86.3	ft.
<b>Deck Material</b>	1 - Concrete Cast-in-Place	
<b>Wear Surf Type</b>	4 - Low Slump Concrete	
<b>Wear Surf Install Year</b>	1977	
<b>Wear Course/Fill Depth</b>	0.12	ft.
<b>Deck Membrane</b>	0 - None	
<b>Deck Rebars</b>	1 - Epoxy Coated Reinforcing	
<b>Deck Rebars Install Year</b>	1977	
<b>Structure Area (Out-to-Out)</b>	13290	sq. ft.
<b>Roadway Area (Curb-to-Curb)</b>	9548	sq. ft.
<b>Sidewalk Width</b>	Lt 10.00	Rt 12.00
<b>Curb Height</b>	Lt 0.50	Rt 0.50
<b>Rail Type</b>	Lt 21	Rt 21

ROADWAY	
<b>Bridge Match ID (TIS)</b> 0	
<b>Roadway O/U Key</b> Route On Structure	
<b>Route Sys</b>	04 - CSAH
<b>Number</b>	15
<b>Roadway Name or Description</b>	
CSAH 15	
<b>Level of Service</b>	1 - MAINLINE
<b>Roadway Type</b>	2 - 2-way traffic
<b>Control Section (TH Only)</b>	
<b>Reference Point</b> 009+00.621	
<b>Detour Length</b>	2.0 mi
<b>Lanes</b>	On 4 Under 0
<b>ADT</b>	12948
<b>Year</b>	2008
<b>HCACT</b>	259
<b>ADTT</b>	2 %
<b>Functional Class</b> 16 - Urban - Minor Arterial	

RDWY DIMENSIONS			
<b>If Divided</b>	<b>NB-EB</b>	<b>SB-WB</b>	
<b>Roadway Width</b>	62.00	ft.	ft.
<b>Vertical Clearance</b>		ft.	ft.
<b>Max. Vert. Clear.</b>		ft.	ft.
<b>Horizontal Clear.</b>	61.9	ft.	ft.
<b>Lateral Clearance</b>		ft.	ft.
<b>Appr. Surface Width</b>	60.0	ft.	
<b>Bridge Roadway Width</b>	62.0	ft.	
<b>Median Width On Bridge</b>		ft.	

MISC. BRIDGE DATA	
<b>Structure Flared</b>	0 - No flare
<b>Parallel Structure</b>	N - No parallel structure
<b>Field Conn. ID</b>	
<b>Abutment Foundation</b>	1 - CONC
<b>(Material/Type)</b>	3 - FTG PILE
<b>Pier Foundation</b>	1 - CONC
<b>(Material/Type)</b>	1 - SPRD SOIL
<b>Historic Status</b>	5 - Not eligible

PAINT	
<b>Year Painted</b>	
<b>Unsound Paint %</b>	
<b>Painted Area</b>	sq. ft.
<b>Primer Type</b>	
<b>Finish Type</b>	

BRIDGE SIGNS	
<b>Posted Load</b>	0 - Not Required
<b>Traffic</b>	0 - Not Required
<b>Horizontal</b>	0 - Not Required
<b>Vertical</b>	N - Not Applicable

INSPECTION	
<b>Userkey</b>	102
<b>Unofficial Structurally Deficient</b>	N
<b>Unofficial Functionally Obsolete</b>	N
<b>Unofficial Sufficiency Rating</b>	98.2
<b>Routine Inspection Date</b>	11/12/2015
<b>Routine Inspection Frequency</b>	24
<b>Inspector Name</b>	County, Ramsey
<b>Status</b>	A - Open

NBI CONDITION RATINGS	
<b>Deck</b>	7 - Good Condition
<b>Unsound Deck %</b>	
<b>Superstructure</b>	7 - Good Condition
<b>Substructure</b>	7 - Good Condition
<b>Channel</b>	N - Not Applicable
<b>Culvert</b>	N - Not Applicable

NBI APPRAISAL RATINGS	
<b>Structure Evaluation</b> 7	
<b>Deck Geometry</b>	6
<b>Underclearances</b>	9
<b>Water Adequacy</b>	N - Not Applicable
<b>Approach Alignment</b>	8 - Equal to present desirabl

SAFETY FEATURES	
<b>Bridge Railing</b>	1 - MEETS STANDARDS
<b>GR Transition</b>	1 - MEETS STANDARDS
<b>Appr. Guardrail</b>	1 - MEETS STANDARDS
<b>GR Termini</b>	1 - MEETS STANDARDS

IN DEPTH INSP.		
	Y/N	Date
<b>Frac. Critical</b>		
<b>Underwater</b>		
<b>Pinned Asbly.</b>		
<b>Spec. Feat.</b>		

WATERWAY	
<b>Drainage Area (sq. mi.)</b>	
<b>Waterway Opening</b>	sq. ft.
<b>Navigation Control</b>	N - Not applicable, no waterw
<b>Pier Protection</b>	
<b>Nav. Clr. (ft.)</b>	Vert. ft. Horiz. ft.
<b>Nav. Vert. Lift Bridge Clear. (ft.)</b>	
<b>MN Scour Code</b>	A - NON WATER' Year

CAPACITY RATINGS		
<b>Design Load</b>	5 - HS 20	
<b>Operating Rating</b>	1 - LF (LF)	HS 42.6
<b>Inventory Rating</b>	1 - LF (LF)	HS 25.5
<b>Posting VEH:</b>	<b>SEMI:</b>	<b>DBL:</b>
<b>Rating Date</b> 5/5/2003		
<b>MnDOT Permit Codes</b>		
<b>A:</b> 1 - No Restriction		
<b>B:</b> 1 - No Restriction		
<b>C:</b> 1 - No Restriction		

# MnDOT Structure Inventory Report

## Additional Roadways

Bridge ID: 62079

CO Road E (CSAH 15 over BNSF RR)

Date: 01/05/2016

# MnDOT BRIDGE INSPECTION REPORT

01/05/2016

Inspector: County, Ramsey

**BRIDGE 62079 CO Road E (CSAH 15 OVER BNSF RR)**

**ROUTINE INSP. DATE: 11/12/2015**

County: Ramsey	Location: 0.2 MI E OF JCT TH 61	Length: 154.0 ft.
City: WHITE BEAR LAKE	Route: 04 - CSAH 15 Ref. Pt.: 009+00.621	Deck Width: 86.3 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 9548 sq. ft. / %
Section: 34 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 5 - Prestressed Concrete 02 -	Local Agency Bridge Nbr.:	Culvert: N/A
List: Stringer/Multi-beam or Girder		Postings:
NBI Deck: 7 Super: 7 Sub: 7 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 8 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 98.2

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
109	Prestressed Concrete Girder or Beam	2	Routine	11/12/2015	1384 LF	0	1382	2	0	N/A
			Routine	11/27/2013	1384 LF	0	1382	2	0	N/A
			<input type="checkbox"/> Requires Monitoring			<input type="checkbox"/> Monitored				
Notes: [2007-2015] Girders #6 & #7 east end has moderate size spall. 36" Deep pre-stressed beams.										

205	Reinforced Concrete Column	2	Routine	11/12/2015	10 EA	0	10	0	0	N/A
			Routine	11/27/2013	10 EA	0	10	0	0	N/A
			<input type="checkbox"/> Requires Monitoring			<input type="checkbox"/> Monitored				
Notes: [2007-2015] Column #2 has a 6" spall at base. [2003-2015] Minor spalls are present. There are spalls at south end of west strut. West strut is charred from fire 1998. Both piers have RR crash struts.										

215	Reinforced Concrete Abutment	2	Routine	11/12/2015	180 LF	172	8	0	0	N/A
			Routine	11/27/2013	180 LF	172	8	0	0	N/A
			<input type="checkbox"/> Requires Monitoring			<input type="checkbox"/> Monitored				
Notes: [2015] 3" x 2" spall in NW corner. [2003-2015] The south 1/2 of both abutments have 4 vertical cracks. 4X2 X 2' = 16 LF of vertical cracks.										

234	Reinforced Concrete Pier Cap	2	Routine	11/12/2015	180 LF	180	0	0	0	N/A
			Routine	11/27/2013	180 LF	180	0	0	0	N/A
			<input type="checkbox"/> Requires Monitoring			<input type="checkbox"/> Monitored				
Notes: [2003-2015] No deficiencies of concrete pier cap. There is some debris on top of the concrete caps.										

## Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
300	Strip Seal Deck Joint	2	Routine	11/12/2015	180 LF	0	180	0	N/A	N/A
			Routine	11/27/2013	180 LF	0	180	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2003-2015] Minor leakage, needs to be cleaned and flushed for further inspection.  
Type "H" strip seal installed at abutments 1977.

301	Poured Deck Joint	2	Routine	11/12/2015	180 LF	0	180	0	N/A	N/A
			Routine	11/27/2013	180 LF	0	180	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2003-2015] Minor adhesion and cohesion failures. Some leaching below pier joints.

310	Elastomeric (Expansion) Bearing	2	Routine	11/12/2015	27 EA	27	0	0	N/A	N/A
			Routine	11/27/2013	27 EA	27	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2003-2015] Abutment bearings encased by concrete diaphragms. Some minor deterioration.

313	Fixed Bearing	2	Routine	11/12/2015	27 EA	27	0	0	N/A	N/A
			Routine	11/27/2013	27 EA	27	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2013-2015] Interior bearings (Both piers) are fixed. Some minor deterioration.

321	Concrete Approach Slab-Concrete Wearing Surface	2	Routine	11/12/2015	2 EA	0	2	0	0	N/A
			Routine	11/27/2013	2 EA	0	2	0	0	N/A

 Requires Monitoring Monitored

Notes: [2011-2015] Moderate spalls are present on both approach panels. There is some deterioration of the west approach slab at construction joint.

[2009-2015] There is minor- moderate settlement of both approach panels.

[2013-2015] The west approach slab has 40 LF of major longitudinal cracks. The east approach slab has 40 LF of moderate longitudinal cracking. The approach panel cracks require rehabilitation. Some major spalls are present at cracks.

[1985] Approach modified to match widened sidewalk.

## Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
333	Masonry, Other or Combination Material Railing	2	Routine	11/12/2015	308 LF	0	308	0	N/A	N/A
			Routine	11/27/2013	308 LF	0	308	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2015] Spall on west end & @ center of north railing.  
 [2007-2015] There are some scrapes on the north side due to snow plows.  
 [2007-2015] There are mid section vertical cracks with efflorescence at fence posts. Concrete parapet also needs surface treatment.  
 [2003-2015] Chain link fence is bent outward at the NW corner.  
 Rail code 21 (Concrete parapet & 6 FT C-L fence).

358	Concrete Deck Cracking Smart Flag	2	Routine	11/12/2015	1 EA	0	1	0	0	N/A
			Routine	11/27/2013	1 EA	0	1	0	0	N/A

 Requires Monitoring Monitored

Notes: [2013-2015] There are numerous moderate size transverse and diagonal cracks. Diagonal cracking at the corners. There are 250 LF of unsealed moderate size cracks.

359	Underside of Concrete Deck Smart Flag	2	Routine	11/12/2015	1 EA	0	1	0	0	0
			Routine	11/27/2013	1 EA	0	1	0	0	0

 Requires Monitoring Monitored

Notes: [2011-2015] Total distressed area is less than 2% (condition state 2).  
 Span #1  
 [2011-2015] Between girders #2 & #3 near abutment there is a 1' X 2' spall with corrosion and exposed rebar. Also a 4' diagonal crack w/efflorescence between girders #2 & #3 near abutment.  
 [2013-2015] Between #5 & #6 girders there is a 6" X 6" & 1.5' x 6" spall at pier.  
 [2013-2015] Between girders #7 & #8 @ west abutment there are 4 diagonal cracks with efflorescence.  
 [2013-2015] Between girders #8 & #9 @ west abutment there is a 6' diagonal crack with efflorescence.  
 [2015] Between girders #8 & #9 @ west abutment some delamination (4' x 6" & 2' x 6")  
 Midspan  
 [2011-2015] There are 2 transverse cracks w/efflorescence between #6 & #7 girders at mid span.  
 Span #3  
 [2013-2015] Between girders #2 & #3 at abutment there is some delamination and corrosion present.  
 [2013-2015] There is a 4' diagonal crack w/efflorescence between girders #6 & #7 near east abutment. There are also two transverse cracks w/eff. between pier & east abutment between girder #6 & #7. Between #6 & #7 there are several patches from barrier anchors placed during staged construction 1983. The patches are still holding.  
 [2013-2015] Between #7 & #8 there are 1- 6' and 2- 4' diagonal cracks w/ efflorescence. Between girders #8 & #9 there are 3- 4' diagonal cracks w/efflorescence .  
 [2013-2015] Underside of deck has a total of 150 LF of minor leaching cracks.  
 [2013-2015] Some leaching below pier joints.

## Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
377	Low Slump O/L (Concrete Deck with Epoxy Rebar)	2	Routine	11/12/2015	13293 SF	0	13293	0	0	0
			Routine	11/27/2013	13293 SF	0	13293	0	0	0

 Requires Monitoring Monitored

Notes: [2011-2015] There is approximately 250 LF of unsealed moderate size cracks. Numerous transverse and diagonal cracks developing throughout deck. Moderate size diagonal cracking at corners.  
 [2007-2015] Distress deck area is < 2.0%.  
 [2011-2015] There are 3 moderate - major spalls @ expansion device on the east end.  
 [2005-2015] Low slump wearing surface has exposed aggregate.  
 [1977] Low slump overlay (3 Lanes - 1 each direction & center turn lane).  
 [2005-2015] Low slump overlay has light scale both sides.

380	Secondary Structural Elements	1	Routine	11/12/2015	72 EA	0	72	0	0	N/A
			Routine	11/27/2013						

 Requires Monitoring Monitored

Notes: [2005-2015] Concrete diaphragms in place.

387	Reinforced Concrete Wingwall	2	Routine	11/12/2015	4 EA	2	2	0	0	N/A
			Routine	11/27/2013	4 EA	2	2	0	0	N/A

 Requires Monitoring Monitored

Notes: [2015] 6" minor crack in top of SE wingwall.  
 [2015] 3' minor vertical crack in NW wingwall.  
 [2013-2015] SW wingwall has minor horizontal cracking with a moderate spall on top.  
 [2013-2015] NE WW contains two moderate spalls.  
 [2013-2015] NW and SE wingwalls has some minor deterioration.

964	Critical Finding Smart Flag	2	Routine	11/12/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	11/27/2013	1 EA	1	0	N/A	N/A	N/A

 Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

981	Signing	2	Routine	11/12/2015	1 EA	1	0	0	0	0
			Routine	11/27/2013	1 EA	1	0	0	0	0

 Requires Monitoring Monitored

Notes: [2007-2015] All required signing is in place.



## Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
982	Approach Guardrail	2	Routine	11/12/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/27/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2013-2015] Guardrail system has no twisted ends at NE & SW corners, but due to low speed not required.  
[2013-2015] Minor damage to guardrail system but still functioning.

984	Deck & Approach Drainage	2	Routine	11/12/2015	1 EA	1	0	0	N/A	N/A
			Routine	11/27/2013	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2003-2015] Drains to the west. System is functioning properly.

985	Slopes & Slope Protection	2	Routine	11/12/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/27/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [1988-2015] Bituminous aggregate slopes are loose and being displaced. Minor to moderate deterioration. Another seal application is recommended.

986	Curb & Sidewalk	2	Routine	11/12/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/27/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2015] scrapes on south curb from snowplows.  
[2007-2015] Curb has a 2' X 6" major spall on south side near east end.  
[2007-2015] Sidewalk has transverse cracking on both sides. Sidewalk has numerous minor cracking.  
[2007-2015] There is a 2" drop off at SE corner, 2" drop off at NW corner and 1" drop off at SW corner.  
Sidewalks widened 10 FT north, 12 FT south 1985.

988	Miscellaneous Items	2	Routine	11/12/2015	1 EA	0	1	0	N/A	N/A
			Routine	11/27/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [1989-2015] One active RR track below.  
[2013-2015] Graffiti is on abutments, girders, pier columns, pier webs and wingwalls.  
[2003-2015] Utility pole at NE corner is on roadway side of guardrail.

General Notes: 2015 bridge safety inspection by Dan Bodelson & Brian Essler on 11/12/2015.  
2013 bridge safety inspection by B. Wieman and D. Bodelson on 11/27/2013.  
2011 bridge safety inspection by B. Wieman and D. Bodelson.  
Photos. 2005. 2009 Bridge safety inspection was completed by B. Wieman.  
2007 Bridge safety inspection was completed by B. Wieman and B. Essler 8/17/2007.  
2005 Bridge safety inspection by Bret Wieman and Dan Bodelson. 8/30/2005.  
Photos 2005. Bridge constructed in 1977.

58. Deck NBI: Concrete deck has minor cracking, leaching & scale.

36A. Brdg Railings NBI: Vehicular railings meet current standards.

36B. Transitions NBI: Guardrail transitions meet current standards.

36C. Appr Guardrail NBI: Approach guardrail meets current standards.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
36D.	Appr Guardrail Terminal NBI:		Guardrail terminations meet current standards.							
59.	Superstructure NBI:		Concrete has minor cracking & spalls.							
60.	Substructure NBI:		Abutments & Piers have minor cracking & spalls.							
61.	Channel NBI:		Roadway over BNSF RR.							
62.	Culvert NBI:		Roadway over BNSF RR.							
71.	Waterway Adeq NBI:		Roadway over BNSF RR.							
72.	Appr Roadway Alignment NBI:		No speed reduction required.							
	Inventory Notes:									

\_\_\_\_\_  
 Dan Bodelson  
 Inspector's Signature

\_\_\_\_\_  
 Nicklaus Fischer  
 Reviewer's Signature

# Pictures



Photo 1 -



Photo 2 -

# Pictures



Photo 3 -



Photo 4 -

# Pictures



Photo 5 -



Photo 6 -

# Pictures



Photo 7 -



Photo 8 -



1. crack under bridge.JPG



2. east bearings.JPG



3. looking north.JPG



4. looking south.JPG



5. more cracks under bridge.JPG



6. south beams.JPG



7. west bearings.JPG



8. west pier.JPG

### Culvert

Bridge No.: 62079

<b>Culvert</b>
----------------

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
<b>Culvert Overall:</b>	<b>NBI Item 62</b>	<u>N</u>	Roadway over BNSF RR.

MnDOT Scour Code: A - NON WATERWAY

<b>Waterway Inspection</b>
----------------------------

Item No.	Yes, No, NA or Not Visible	Description
1.	<u>          </u>	Is there a significant build-up of debris?
2.	<u>          </u>	Is there erosion of the embankment around the headwalls?
3.	<u>          </u>	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	<u>          </u>	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	<u>          </u>	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	<u>          </u>	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	<u>          </u>	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	<u>          </u>	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	<u>          </u>	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	<u>          </u>	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

**Notes:**

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On \_\_\_\_\_ By \_\_\_\_\_



**Channel**

Bridge No.: 62079

**Channel**

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	N	Roadway over BNSF RR.

**Bank Protection/Revetment**

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:			
Downstream Bank Protection:			
Bridge Revetment:			
MnDOT Scour Code:	A - NON WATERWAY		

**Underwater Inspection**

Underwater Inspection By Divers: \_\_\_\_\_  
 No. of Piers To Be Inspected: \_\_\_\_\_

**Waterway Characteristics**

Reference Point: \_\_\_\_\_ High Water Elev.: \_\_\_\_\_ Current Water Elev.: \_\_\_\_\_  
 Pile Tip Elev.: \_\_\_\_\_ Low Water Elev.: \_\_\_\_\_ Current Streambed Elev.: \_\_\_\_\_  
 Scour Hole Elev.: \_\_\_\_\_ Current Scour Hole Elev.: \_\_\_\_\_

**Waterway Inspection: (Not applicable for culverts)**

<b>Item No.</b>	<b>Yes, No, NA or Not Visible</b>	<b>Description</b>
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. \_\_\_\_\_ Have the scour countermeasures been damaged or otherwise made ineffective?

**Notes:**

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On \_\_\_\_\_ By \_\_\_\_\_

## Scour POA

Bridge No.: 62079

<b>Scour POA</b>
------------------

1. Is POA on File? \_\_\_\_\_
2. Date of most recent POA: \_\_\_\_\_
3. Here is a link to MnDOT's Bridge Scour website for other resources:
  - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
  - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

### Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? \_\_\_\_\_

# Channel Section

## Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

## Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

# Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



# BRIDGE STRUCTURAL ASSESSMENT REPORT

## PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62079	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 11/12/2015	STRUCTURE TYPE: Prestressed Concrete Stringer/Multi-beam or Girder
FACILITY CARRIED: CO Road E (CSAH 15	FEATURES INTERSECTED: BNSF RR
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

- Was a critical finding identified during this inspection or upon structural review?  Yes  No  
  - If selected "Yes" above, state briefly the finding(s):
- If a critical finding was identified, what is the current status?  Pending  
 Resolved  
 N/A  
  - Briefly state actions taken:
- Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured.  Yes  No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating?  Yes  No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance       Monitoring Plan  
 Other       Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

**Bridge Office Reviewer**