


**2015 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 62522
CSAH 45 over CO DITCH # 2**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: New Brighton

Date(s) of Inspection: 10/26/2015

Equipment Used:

Owner: County Highway Agency

Inspected By: Essler, Brian

Report Written By: Brian Essler

Report Reviewed By: Nicklaus Fischer

Final Report Date: 01/07/2016

**MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128**



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	7
THUMBNAIL PICTURES	10
CULVERT	11
CHANNEL	12
SCOUR POA	14
CHANNEL X-SECTION	15
MAINTENANCE	16
STRUCTURAL ASSESSMENT REPORT - ROUTINE	17

MnDOT Structure Inventory Report

Bridge ID: 62522

CSAH 45

over CO DITCH # 2

Date: 01/07/2016

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City New Brighton			
Township			
Desc. Loc. 0.4 MI N OF JCT TH 694			
Sect., Twp., Range		20 - 030N - 23W	
Latitude Deg	45	Min	4
Sec			16.38
Longitude Deg	93	Min	12
Sec			19.54
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		1967	
MN Year Reconstructed		1989	
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 3 - COUNTY			
Date Opened to Traffic			
On-Off System		1 - ON	
Legislative District 50B			

STRUCTURE			
Service On 1 - Highway			
Service Under 5 - Waterway			
Main Span Type			
5 - Prestress or Precast 13 - Box Culvert			
Main Span Detail			
Appr. Span Type			
Appr. Span Detail			
Skew	12	R	
Culvert Type	W105D		
Barrel Length	91	ft.	
Cantilever ID			

NUMBER OF SPANS			
MAIN:	2	APPR:	0
TOTAL:	2		
Main Span Length	10.2	ft.	
Structure Length	22.5	ft.	
Deck Width (Out-to-Out)	0.0	ft.	
Deck Material	N - Not Applicable		
Wear Surf Type	6 - Bituminous		
Wear Surf Install Year			
Wear Course/Fill Depth	4.25	ft.	
Deck Membrane	0 - None		
Deck Rebars	N - Not Applicable (no deck)		
Deck Rebars Install Year			
Structure Area (Out-to-Out)	0	sq. ft.	
Roadway Area (Curb-to-Curb)	sq. ft.		
Sidewalk Width	Lt 0.00	ft.	Rt 0.00
Curb Height	Lt 0.00	ft.	Rt 0.00
Rail Type	Lt NN	Rt NN	

ROADWAY			
Bridge Match ID (TIS) 0			
Roadway O/U Key Route On Structure			
Route Sys	04 - CSAH	Number	45
Roadway Name or Description			
CSAH 45			
Level of Service 1 - MAINLINE			
Roadway Type 2 - 2-way traffic			
Control Section (TH Only)			
Reference Point 000+00.650			
Detour Length	1.0	mi	
Lanes	On 2	Under 0	
	ADT 5179	Year	2008
HCACT	0	ADTT	0 %
Functional Class 16 - Urban - Minor Arterial			

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	50.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.		ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	50.0	ft.	
Bridge Roadway Width	0.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	N - N/A
(Material/Type)	N - N/A
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	97.8
Routine Inspection Date	10/26/2015
Routine Inspection Frequency	24
Inspector Name	County, Ramsey
Status	A - Open

NBI CONDITION RATINGS	
Deck	N - Not Applicable
Unsound Deck %	
Superstructure	N - Not Applicable
Substructure	N - Not Applicable
Channel	7 - Needs minor repairs
Culvert	6 - Deterioration or initial disint

NBI APPRAISAL RATINGS	
Structure Evaluation 6	
Deck Geometry	N
Underclearances	N
Water Adequacy	8 - Bridge Above Approache
Approach Alignment	7 - Better than present minir

SAFETY FEATURES	
Bridge Railing	N - NOT REQUIRED
GR Transition	N - NOT REQUIRED
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	N - NOT REQUIRED

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical			
Underwater			
Pinned Asbly.			
Spec. Feat.			

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening	100	sq. ft.	
Navigation Control	0 - No nav. control on waterw		
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code	E - CULVERT	Year	

CAPACITY RATINGS			
Design Load	4 - H 20		
Operating Rating	5 - NRAP	24.0	
Inventory Rating	5 - NRAP	18.0	
Posting VEH:	SEMI:	DBL:	
Rating Date 01/23/1985			

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 62522

CSAH 45 over CO DITCH # 2

Date: 01/07/2016

MnDOT BRIDGE INSPECTION REPORT

01/07/2016

Inspector: County, Ramsey

BRIDGE 62522 CSAH 45 OVER CO DITCH # 2

ROUTINE INSP. DATE: 10/26/2015

County: Ramsey	Location: 0.4 MI N OF JCT TH 694	Length: 22.5 ft.
City: New Brighton	Route: 04 - CSAH 45 Ref. Pt.: 000+00.650	Deck Width: 0.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 20 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: W105D
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: 7 Culv: 6	Open, Posted, Closed: A - Open	
	MN Scour Code: E - CULVERT	

Appraisal Ratings - Approach: 7 Waterway: 8		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 97.8

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
241	Reinforced Concrete Culvert	2	Routine	10/26/2015	223 LF	0	218	5	0	N/A
			Routine	10/08/2013	223 LF	0	218	5	0	N/A

Requires Monitoring Monitored

Notes: There is moderate scaling @ both culvert floors and water line 2015.
 There is some deterioration of construction joints both culverts. Also major spalling where tie bars anchor to extend east & west 2009-2015.
 Culvert #2 has deterioration & infiltration @ #3 & #5 joint 2009-2015. Culvert #2 has exposed re-bar with corrosion east of where RCP drains into culvert 2009-2015.
 There is some minor amount of riprap in both culverts 2013-2015.
 The tie bars are rusting 2007-2015.
 Minor cracking and leaching are present. Some corrosion where structure was cut into top of culvert #1 on the east side of Long Lake Road 2001-2015.
 There is evidence of corrosion and slight separation of joints. Lift holes need patching. There is spalling @ tie bars 2003-2015.
 There is some scaling @ both culvert floors and water line 2009-2013.
 North barrel was modified for local drainage system 1996 . Floor was inspected during widening 1989.

361	Scour Smart Flag	2	Routine	10/26/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/08/2013	1 EA	0	1	0	N/A	N/A

Requires Monitoring Monitored

Notes: Minor scour @ NE & SE corners of the bank. Also some erosion of riprap 2003-2015.

388	Culvert Headwall, Wingwall or Other End Treatment	2	Routine	10/26/2015	2 EA	0	2	0	0	N/A
			Routine	10/08/2013	2 EA	0	2	0	0	N/A

Requires Monitoring Monitored

Notes: The north end of east headwall is offset 3" from south end. 2013-2015
 There is a major crack at west end headwall. Also settlement of riprap @ north side of west end headwall 2009-2015.
 Minor to moderate cracking is present 2001-2015. Minor spalling @ top of east end Headwall #2 2003-2015.
 Replaced in 1989.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
964	Critical Finding Smart Flag	2	Routine	10/26/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	10/08/2013	1 EA	1	0	N/A	N/A	N/A

 Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

982	Approach Guardrail	2	Routine	10/26/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/08/2013	1 EA	1	0	0	N/A	N/A

 Requires Monitoring MonitoredNotes: Guardrail system in place during inspection 2003-2015.
Guardrail system updated in 1990.
Cable system guardrail

984	Deck & Approach Drainage	2	Routine	10/26/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/08/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Debris in vain drains. Needs clean out 2005-2015. Drainage system is functioning properly 2003.

985	Slopes & Slope Protection	1	Routine	10/26/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/08/2013						

 Requires Monitoring Monitored

Notes: Minor erosion on all corners 2015

986	Curb & Sidewalk	2	Routine	10/26/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/08/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring MonitoredNotes: Major spalls in curb on east side of Long Lake Rd. 2013-2015
Moderate settlement in curb on east side of Long Lake Rd. 2013-2015
Moderate cracking on both sides. There are major spalls on the west side curb 2007-2015.
Minor cracking 2005. Superficial deterioration 2003.

987	Roadway over Culvert	2	Routine	10/26/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/08/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring MonitoredNotes: Roadway has cracks with moderate settlement 2001-2015.
Roadway cracks sealed 2015

General Notes: 2015 Bridge safety inspection was completed on 10/26/2015 by Brian Essler & Dan Bodelson
2013 Bridge safety inspection was completed on 10/03/2013 by Dan Bodelson & Brian Essler
2011 Bridge safety inspection was conducted by B. Wieman on 10/5/2011.
2009 Bridge safety inspection was completed by B. Wieman 7/08/2009.
2007 Bridge safety inspection was completed by B. Wieman 7/25/2007.
BRIDGE WIDENED IN 1989. Culvert extensions are pre-cast sectional 5'H X 10'W X 6'L.
South culvert is 101 LF X 5'H X 10'W. North culvert is 121 LF X 5'H X 10'W. Total length is 222 LF.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
	58. Deck NBI:		Culvert							
	36A. Brdg Railings NBI:		Guardrail is not attached to culvert							
	36B. Transitions NBI:		Guardrail is not attached to culvert							
	36C. Appr Guardrail NBI:		Single cable guardrail							
	36D. Appr Guardrail Terminal NBI:									
	59. Superstructure NBI:		Culvert							
	60. Substructure NBI:		Culvert							
	61. Channel NBI:		Minor bank erosion, Minor debris in channel							
	62. Culvert NBI:		Moderate scaling and minor cracking with minor spalling							
	71. Waterway Adeq NBI:		Greater than 3' of freeboard							
	72. Appr Roadway Alignment NBI:		Minor sight problem due to horizontal curve							
	Inventory Notes:									

 Brian Essler

Inspector's Signature

 Nicklaus Fischer

Reviewer's Signature

Pictures



Photo 1 -



Photo 2 -

Pictures



Photo 3 -



Photo 4 -

Pictures



Photo 5 -



1. IMG_0205.JPG



2. IMG_0206.JPG



3. IMG_0207.JPG



4. IMG_0209.JPG



5. IMG_0208.JPG

Culvert

Bridge No.: 62522

Culvert

Item	Description	Condition	Comments
Culvert Overall:	NBI Item 62	6	Moderate scaling and minor cracking with minor spalling

MnDOT Scour Code: E - CULVERT

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there erosion of the embankment around the headwalls?
3.	_____	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	_____	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	_____	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	_____	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	_____	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	_____	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 62522

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	<u>7</u>	Minor bank erosion, Minor debris in channel

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	<u>E - CULVERT</u>		

Underwater Inspection

Underwater Inspection By Divers: _____
 No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____ High Water Elev.: _____ Current Water Elev.: _____
 Pile Tip Elev.: _____ Low Water Elev.: _____ Current Streambed Elev.: _____
 Scour Hole Elev.: _____ Current Scour Hole Elev.: _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 62522

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62522 BRIDGE OWNER: County Highway Agency
 DATE INSPECTED: 10/26/2015 STRUCTURE TYPE: Concrete
Culvert (includes frame culverts)
 FACILITY CARRIED: CSAH 45 FEATURES INTERSECTED: CO DITCH # 2

TYPE OF INSPECTION: ROUTINE
 FRACTURE CRITICAL
 PINNED ASSEMBLY:
 SPECIAL:
 DAMAGE:
 OTHER:

Check all that apply:

Redundancy:	<input type="checkbox"/> Load Path	Connection	<input type="checkbox"/> Riveted
	<input type="checkbox"/> Structural	Type:	<input type="checkbox"/> Bolted
	<input type="checkbox"/> Internal		<input type="checkbox"/> Welded
			<input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance Monitoring Plan
 Other Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer