

**2016 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 62541
COMO AVE over BNSF RR**

DISTRICT: Metro **COUNTY:** Ramsey **CITY/TOWNSHIP:** St Paul
STATE: Minnesota

Date of Inspection: 10/20/2016

Equipment Used: Full Body Harness, Confined Space Entry, Other, Other -
Reachall UB-60 & Lift Truck (both provided by City of St.
Paul)

Owner: County Highway Agency

Inspected By: Engel, Michael; Grau, Joe; Lee, Joseph; Reimer, Dan

Report Written By: Joseph Lee
Report Reviewed By: Glenn Pagel
Final Report Date: 12/15/2016




Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
APPENDIX A: STRUCTURE INVENTORY	2
ELEMENTS	3
THUMBNAIL PICTURES	9

Minnesota Structure Inventory Report

Bridge ID: 62541

COMO AVE over BNSF RR

Date: 12/09/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
Agency Br. No. Crew District 05 Maint. Area County 062 - Ramsey City St Paul Township Desc. Loc. AT WESTERN AVE Sect., Twp., Range 25 - 029N - 23W Latitude 44 ° 57 ' 55.15 " Longitude 93 ° 7 ' 2.67 " Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 1985 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 4 - MUNICIPAL Date Opened to Traffic 10/1/1985 On - Off System 1 - ON Legislative District 65A Potential ABC 2 - N/A	Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 04 - CSAH Number 32 Roadway Name or Description CSAH 32-COMO AVE Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point 004+00.501 Detour Length 1.0 mi. Lanes ON 2 UNDER 0 ADT 7300 YEAR 2005 HCA DT ADTT % Functional Class 16 - Urban - Minor Arterial	Userkey 199 Structurally Deficient N Functionally Obsolete N Sufficiency Rating 95.3 Routine Inspection Date 10/20/2016 Routine Inspection Frequency 12 Inspector Name Lee, Joseph Status A - Open																				
		+ NBI CONDITION RATINGS +																				
		Deck 6 Unsound Deck % Superstructure 6 Substructure 6 Channel N Culvert N																				
		+ NBI APPRAISAL RATINGS +																				
		Structure Evaluation 6 Deck Geometry 9 Underclearances 4 Waterway Adequacy N Approach Alignment 8																				
		+ SAFETY FEATURES +																				
		Bridge Railing 1 - MEETS STANDARDS GR Transition 0 - SUBSTANDARD Appr. Guardrail 0 - SUBSTANDARD GR Termini 0 - SUBSTANDARD																				
		+ IN DEPTH INSP. +																				
		<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td style="text-align: center;">N</td> <td style="text-align: center;">24</td> <td style="text-align: center;">10/23/2013</td> </tr> <tr> <td>Underwater</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Pinned Asbly.</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	Frac. Critical	N	24	10/23/2013	Underwater	N			Pinned Asbly.	N			Spec. Feat.			
	Y/N	Freq	Date																			
Frac. Critical	N	24	10/23/2013																			
Underwater	N																					
Pinned Asbly.	N																					
Spec. Feat.																						
		+ WATERWAY +																				
		Drainage Area (sq. mi.) Waterway Opening (sf.) Navigation Control N - Not applicable, no Pier Protection - Nav. Clr. (ft.) Vert. 0.0 Horiz. 0.0 Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code A - NON Year																				
		+ CAPACITY RATINGS +																				
		Design Load 5 - HS 20 Operating Rating 2 - HS TRUCK 41.1 Inventory Rating 2 - HS TRUCK 21.0 Posting VEH: SEMI: DBL: Rating Date 1/31/2006 Overweight Permit Codes A N - N/A B N - N/A C N - N/A																				
+ STRUCTURE +	+ RDWY DIMENSIONS +																					
Service On 5 - Highway-pedestrian Service Under 2 - Railroad Main Span Type 3 - Steel Main Span Design 01 - Beam Span Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 0 Culvert Type Barrel Length Cantilever ID Number of Spans MAIN: 3 APPR: 0 TOTAL: Main Span Length 109.3 ft. Structure Length 342.7 ft. Deck Width (Out-to-Out) 68.6 ft. Deck Material 1 - Concrete Cast-in-Place Wear Surf Type 4 - Low Slump Concrete Wear Surf Install Year 1985 Wear Course/Fill Depth 0.17 ft. Deck Membrane 0 - None Deck Rebars 1 - Epoxy Coated Reinforcing Deck Rebars Install Year 1985 Structure Area (Out-to-Out) 23509 sq. ft. Roadway Area (Curb-to-Curb) 17825 sq. ft. Sidewalk Width 50A. Lt 6.00 ft. 50B. Rt 6.00 ft. Curb Height Lt 0.83 ft. Rt 0.83 ft. Rail Type Lt 21 Rt 21	If Divided NB-EB SB-WB Roadway Width 52.00 ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. 51.9 ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 52.0 ft. Bridge Roadway Width 52.0 ft. Median Width On Bridge ft.																					
	+ MISC. BRIDGE DATA +																					
	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID 4 - Bolted Abutment Foundation (Material/Type) 3 - FTG PILE Pier Foundation (Material/Type) 3 - FTG PILE Historic Status 5 - Not eligible																					
	+ PAINT +																					
	Year Painted 1986 Unsound Paint % 0 Painted Area sq. ft. Primer Type D - Organic Zinc - 3309 Finish Type H - Vinyl																					
	+ BRIDGE SIGNS +																					
	Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 0 - Not Required Vertical N - Not Applicable																					

MINNESOTA BRIDGE INSPECTION REPORT

12/15/2016

Inspector: CO Bridge

BRIDGE 62541 COMO AVE OVER BNSF RR

County: Ramsey	Location: AT WESTERN AVE	Length: 342.7 ft.
City: St Paul	Route: 04 - CSAH 32 Ref. Pt.: 004+00.501	Deck Width: 68.6 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 17825 sq. ft. / %
Section: 25 Township: 029N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / 0%
Span Type: 3 - Steel 2 - Stringer/Multi-beam or Girder	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:
NBI Deck: 6 Super: 6 Sub: 6 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	

Appraisal Ratings - Approach: 8 Waterway: N	Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Unofficial Sufficiency Rating 95.3
Traffic: 0 - Not Required	
Vertical: N - Not Applicable	

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
----------	--------------	-------------	------------	----------	----------	----------	----------	----------

12	Reinforced Concrete Deck	Routine	10/20/2016	23509 SF	23471	23	15	0
		Migrated Values		23509 SF	23471	23	15	0

Notes: Minor isolated delamination's are scattered. 2010-16
 Efflorescence is present. Little to no build up. 2011-16
 [2013] Underside of Span #2 (at center of span) has 15 SF of spall (exposed rebar with section loss - Photo 3) and 10 SF of delamination. Loose concrete above the railroad was chipped off in 2013.
 There are scattered delamination's on the underside of the deck throughout the bridge.
 Approx. 38 SF of delams / spalls at the under deck. 2015-16

510	Wearing Surfaces	Routine	10/20/2016	17825 SF	17422	403	0	0
		Migrated Values		17825 SF	17422	403	0	0

Notes: Low Slump Overlay with Epoxy on Top Mat Only Notes:
 Only the top mat of deck reinforcement is epoxy coated (the bottom mat is not epoxy coated) - see plan sheets 3 & 12 (of 39).
 There are numerous longitudinal and transverse sealed cracks in the deck. 2004-05
 The older sealed joints in the wearing course have deteriorated. 2006-16
 Resealing of cracks needed. 2011-16
 Unsealed cracks less than .012". 2016
 Sealed and unsealed cracks from .012" to .05" wide. CS-2 2016

BRIDGE 62541 COMO AVE OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
102	Steel Closed Web/Box Girder	Routine	10/20/2016	138 LF	138	0	0	0
		Migrated Values		138 LF	138	0	0	0
<p>Notes: The steel pier caps are constructed of ASTM A-588 weathering steel - the exterior surfaces were painted in 1986, but the internal surface were never painted. The steel caps should be considered to be part of the "superstructure". There are backer bars along the top flange/web welds inside the cap.</p> <p>Pier #1 (Exterior): [2009/2013] The cap faces have extensive pigeon debris throughout, with minor corrosion. The cap faces and bottom flange have flaking rust at the ends (4 LF at each end) - Photo 5. The cap faces and bottom flange have flaking rust between the 2nd & 3rd beams from the south (10 LF section - Photo 6) and at the 2nd beam from the north (4 LF section - Photo 7).</p> <p>Pier #1 (Interior): [2000/2013] North end of cap (11 ft. section from entrance hatch to the interior stiffener of the 2nd bearing from the north) has extensive flaking rust (minor section loss) on the bottom flange. The flaking his extends approximately 3-5" up the web plates and internal stiffeners (Photos 8 & 9). [2009/2013] At the center of the cap (east face at top flange/web weld), the backer bar has a 1 ft. section that appears to have some leakage (Photo 10). No weld flaws are evident on the exterior at this location. [2000/2013] South end of cap (11 ft. section from entrance hatch to the interior stiffener of the 2nd bearing from the south) has minor surface corrosion (failure of protective layer) on the bottom flange.</p> <p>Pier #2 (Exterior):[2009/2013] The cap faces have extensive pigeon debris throughout, with minor corrosion. The cap faces and bottom flange have flaking rust at the ends - 10 LF at the north end (Photo 11) and 20 LF at the south end (Photo 12).</p> <p>Pier #2 (Interior): [2000/2013] North end of cap (11 ft. section from entrance hatch to the interior stiffener of the 2nd bearing from the north) has extensive flaking rust (minor section loss) on the bottom flange (Photos 13, 14 & 15). The flaking his extends approximately 6-8" up the web plates and internal stiffeners. [2000/2013] South end of cap (20 ft. section from entrance hatch to the interior stiffener of the 3rd bearing from the south) has extensive flaking rust (minor section loss) on the bottom flange (Photos 16 & 17). The flaking his extends approximately 3" up the web plates and internal stiffeners. Moisture is present on the underside of the top flange at the east end (Photo 18).</p> <p>[2015 FC] The pier caps have been painted inside and out. There are small micro pits in the surface at the interior of the cap, but no measureable loss of thickness. The north end diaphragms on both piers are starting to show showing minor surface corrosion in the interiors, especially in the corners. Pier 1 on the north end has blast residue up to 1/2" deep extending 10' into the cap from the north access door. (Photos 8 - 11) Removed by the contractor in 2015. (2016)</p>								
515	Steel Protective Coating	Routine	10/20/2016	2553 SF	2553	0	0	0
		Migrated Values		2553 SF	2553	0	0	0
<p>Notes: Weathering Steel looks good. 2016</p>								
107	Steel Open Girder/Beam	Routine	10/20/2016	2646 LF	2600	46	0	0
		Migrated Values		2646 LF	2600	46	0	0
<p>Notes: [1986] Beam ends at abutments and piers painted with zinc/vinyl system (the remainder is unpainted weathering steel). Some section loss has occur at the beam ends of all fascia beams prior to repainting. 2014 [2015 FC] The beam ends have been repainted at the joints on the piers and abutments with a zinc/vinyl system . Pack Rust Notes: All beam ends, bearings and steel pier caps were painted in 2015 with a zinc/vinyl system.</p>								
515	Steel Protective Coating	Routine	10/20/2016	39753 SF	39753	0	0	0
		Migrated Values		39753 SF	39753	0	0	0
<p>Notes: The beam ends were repainted in 2015.</p>								
205	Reinforced Concrete Column	Routine	10/20/2016	4 EA	0	0	4	0
		Migrated Values		4 EA	0	0	4	0
<p>Notes: All four pier columns have cracking at the top. (with leaching and rust staining.) 2010-15 [2015 FC] No change. Minor map cracking is present - cracks at the top are of moderate width. 2016</p>								

BRIDGE 62541 COMO AVE OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
215	Reinforced Concrete Abutment	Routine	10/20/2016	178 LF	154	22	2	0
		Migrated Values		178 LF	154	22	2	0
<p>Notes: 2 sq.ft. spall from fire damage at the south abutment inside parapet face. 2005-08 There are rust stains on the ends of the face of the abutments under the fascia beams. 2008-16 There is 8 LF of staining at each end of the east abut. and 8 LF of staining on the south end of the west abut. (8 LF of spall at W.abut, S.end) 2011-15 Cracking present at S.side west abut. 2011-15</p> <p>2 SF spall on the W. abut. - S. end. Deeper than 1" and greater than 6" in diameter. 2016 There are gaps at the wing walls and adjacent retaining walls. 2011-16 The NW.side gap is 4" +/- 2011</p> <p>Cork joint filler is falling out. 2010-16 Gap at wing wall foamed. 2012 Monitor movement. 2012-15 - No change in 2016</p>								
300	Strip Seal Expansion Joint	Routine	10/20/2016	384 LF	384	0	0	0
		Migrated Values		384 LF	384	0	0	0
<p>Notes: There are a total of 6 strip seal joints (Type 3) - there are strip seal joints at both abutments, and two strip seal joints above each steel pier cap. The plan quantity is 384 ft. (64 LF at each joint). [2015 FC] The joints have all been replaced.</p>								
301	Pourable Joint Seal	Routine	10/20/2016	138 LF	138	0	0	0
		Migrated Values		138 LF	138	0	0	0
<p>Notes: All poured sealant was redone in 2015.</p>								
310	Elastomeric Bearing	Routine	10/20/2016	4 EA	4	0	0	0
		Migrated Values		4 EA	4	0	0	0
<p>Notes: The steel pier caps bear upon elastomeric pads on top of each column (4 ft. diameter, 2-3/4" thick) - see plan sheet 25 of 39. These are actually fixed bearings, with four anchor bolts (3-1/2" diameter and 5 ft. long) at each bearing (see plan sheet 11 of 39). [2013] The elastomeric pads have slight bulging along the edges - the coverings have some rust staining, but this appears to be coming down from the steel pier cap.</p>								
313	Fixed Bearing	Routine	10/20/2016	16 EA	16	0	0	0
		Migrated Values		16 EA	16	0	0	0
<p>Notes: The beams have fixed bearings at abutments - the fascia bearings do not have anchor bolts, but are designated as "fixed" on the plans (see plans sheets 2, 10 & 26 (of 39). Repainted in 2015.</p>								
314	Pot Bearing	Routine	10/20/2016	32 EA	0	32	0	0
		Migrated Values		32 EA	0	32	0	0
<p>Notes: There are a total of 32 pot bearings supporting the steel beams where they bear upon the steel pier caps (16 at each pier cap). There is an elastomeric pad inside the cylinders. 24 of these are guided expansion pot bearings - the 8 pot bearings on the west side of Pier #2 are fixed - see plan sheets 10, 25 & 26 (of 39). Freckled rust is present-2016 [2009/2013] All of the pot bearings have surface corrosion and are covered with pigeon debris. Scrape marks along the guide keys seem to indicate recent movement (Photo 1). Gap measurements taken on the north fascia bearings also show some slight movement. All bearings were painted in 2015 with a zinc/vinyl system.</p>								
321	Reinforced Concrete Approach Slab	Routine	10/20/2016	2080 SF	2053	26	1	0
		Migrated Values		2080 SF	2053	26	1	0
<p>Notes: (2009) N.W. approach sinking, 2.5" +/- Sealed longitudinal cracking at both approaches. 2016 New hot sealant placed at cold joints. 2012 and 2015 6 SF concrete patch at the W. approach - N. end. 2016 1 SF temporary patch at the W. approach - S. end. 2016 Pop outs from 1/4" to 1/2" deep are present. 2016</p>								

BRIDGE 62541 COMO AVE OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
330	Metal Bridge Railing	Routine	10/20/2016	682 LF	682	0	0	0
		Migrated Values		682 LF	682	0	0	0
Notes: Steel chain link fence (galvanized). 2016								
515 -	Steel Protective Coating	Routine	10/20/2016	4092 SF	0	4092	0	0
		Migrated Values		4092 SF	0	4092	0	0
Notes: Anchor bolts and nuts are rusty. 2016 Minor coating deterioration. 2016								
331	Reinforced Concrete Bridge Railing	Routine	10/20/2016	682 LF	682	0	0	0
		Migrated Values		682 LF	682	0	0	0
Notes: NW parapet out, 1" west. 2010-15 Minor vertical cracks are present. 2016								
800	Critical Deficiencies or Safety Hazards	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: No critical findings observed. 2010-16								
810	Concrete Decks - Cracking & Sealing	Routine	10/20/2016	4578 LF	2977	1144	457	0
		Migrated Values		4578 LF	2977	1144	457	0
Notes: [2013]-2015 There are unsealed transverse cracks in the overlay (mainly in the traffic lanes) - they should be sealed to prevent further deterioration on the underside of the deck (Photo 2). Many cracks have been previously routed and sealed, most of the sealant has failed. 2016 Unsealed cracks present from .012" to .05" wide. 2016								
855	Secondary Members (Superstructure)	Routine	10/20/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: This element includes the steel diaphragms connection the steel beams. 2016 [2013] Some of the steel diaphragms located adjacent to the steel pier caps have flaking rust (minor section loss) due to deck joint leakage (Photo 4).								
856	Secondary Members (Substructure)	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Crash struts. 2016								
881	Steel Section Loss	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: [2013] There is minor section loss on the steel pier caps - mainly inside the steel caps at the ends (on the bottom flange, base of web plates, and base of the internal stiffeners). All beam ends, bearings and steel pier caps were painted in 2015 with a zinc/vinyl system.								
884	Substructure Settlement & Movement	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: NW wing wall movement. Monitor.								
892	Slopes & Slope Protection	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: The 3-ply waterproofing is almost completely missing or pulled away, only about 15 ft. is still functional. 2013-16 Concrete slope protection is in good condition. 2011-16 Abut. joint waterproofing needs replacing. 2011-16								
893	Guardrail	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Steep drop at bridge approach shoulders. FHWA Item #36-D (Guardrail Terminations) Recorded to " 0-Substandard". 2011-13 Posted speed does NOT exceed 40 MPH. 2014-16 [2011] West approach has 3-cable guardrail. (does not meet current standards for bridge approach)								

BRIDGE 62541 COMO AVE OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
894	Deck & Approach Drainage	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to rate the condition, function, and adequacy of the drainage system.								
895	Sidewalk, Curb, & Median	Routine	10/20/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: The sidewalks have several cracks. sealed 2012 Small pop out are present through out. 2016 1 SF spall at the NE corner. 2016 Moderate cracking and isolated spalling is present. 2016								
899	Miscellaneous Items	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: There are three bridge rail-mounted deck lights - one on the south rail and two on the north rail (there are original). An active 20" watermain runs along the south side of the bridge. 2010-16 The watermain prevents snooper access from the S.side of the bridge. 2011 St. Paul Regional Water contacts : Emergency-Dispatch Desk 651-266-6868 Questions about watermain call Brad Eilts 651-266-6830 [2013] The bridge was originally striped with four 12 ft. vehicular lanes. Around 2005, the bridge was re-striped to carry two vehicular lanes, a center median, and two 6 ft. bicycle lanes on each shoulder.								
900	Protected Species	Routine	10/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure. None found in 2016.								

General Notes: Fracture Critical Inspection by MnDOT on Oct. 15, 2009 (final report dated Aug. 30, 2010)
Fracture Critical Inspection by MnDOT on Nov. 30, 2011 (final report dated Mar. 15th 2012)
Fracture Critical Inspection by MnDOT on Oct. 23, 2013
Fracture Critical Inspection by MnDOT on Oct. 20 2015, The exterior of Cap 1 was not inspected due to no available railroad flagger.

BNSF Railway contacts: Mike Anderson 763-782-3310 or 612-749-3401 michael.anderson5@bnsf.com
Lane Gilliland (612) 219-4219

Element: 966 (Fracture Critical)
Quantity: 1 EACH
Q1: 1
Q2: 0
Q3: 0
Q4: 0
Q5: 1

Notes: The two steel box pier caps are classified as "Fracture Critical".

58. Deck NBI: [2013] Rating lowered from 7 to 6 due to delamination and spalling on the underside of the deck (exposed reinforcement has section loss).

36A. Brdg Railings NBI:

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail Terminal NBI:

59. Superstructure NBI: [2011] Rating lowered from 7 to 6 due to (minor section loss) on the steel pier caps.

60. Substructure NBI: [2011] Rating lowered from 7 to 6 due due staining and cracking on the pier columns and abutment. Both west wingwalls are separating from the adjacent retaining walls.

61. Channel NBI:

62. Culvert NBI:

71. Waterway Adeq NBI:

BRIDGE 62541 COMO AVE OVER BNSF RR

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
-------------	--------------	-------------	------------	----------	-------------	-------------	-------------	-------------

72. Appr Roadway [2013] Approach roadway alignment is straight - no speed reduction required.
Alignment NBI:

Inventory Notes: Year Painted: Should be 2015; beam ends and pier caps were repainted.

Joseph Lee
Inspector's Signature

Glenn Pagel
Reviewer's Signature



1. JMF002 Pier 1 S Column.jpg



2. JMF006 Pier 2 S Column.jpg



3. 003 Pier 2 north Column 1.5 If Crack.jpg



4. 029 Pier 1 Joint Looking South.jpg



5. 030 Pier 2 Joint Looking South.jpg



6. JMF005 Pier 1 Steel Cap.jpg



7. 028 Pier 1 South Access Door.jpg



8. 016 Minor Corrosion in the End Diaphragm at the North End.jpg



9. 017 Minor Corrosion in the End Diaphragm at the North End.jpg



10. 018 Minor Corrosion in the End Diaphragm at the North End.jpg



11. 027 Pier 1 Cracked Paint at Beam 1.jpg



12. 023 Pier 1 Paint Puddled at Beam 5.jpg



13. 026 Pier 1 Paint Puddled at Beam 7.jpg



14. 024 Pier 1 Cap Near the North End.jpg



15. JMF003 Pier 2 Steel Cap.jpg



16. 002 Beam 4 Connection to Pier 2 Repainted.jpg



17. 004 Pier 2 North Door.jpg



18. 005 Pier 2 Interior at North End New Paint.jpg



19. 014 Minor Corrosion in the End Diaphragm Corners at the South End.jpg



20. 015 Minor Corrosion in the End Diaphragm Corners at the South End.jpg



21. 006 Pier 2 Interior at North End New Paint.jpg



22. 007 Pier 2 Interior at North End New Paint.jpg



23. 009 Pier 2 Interior at North End New Paint.jpg



24. 011 Pier 2 Paint Pooled at Beam 5.jpg



25. 010 Pier 2 Paint Pooled at Beam 6.jpg



26. 012 Pier 2 South End.jpg



27. 013 Pier 2 South End.jpg



28. N Sidewalk near E end.JPG



29. NW end (1).JPG



30. NW end (2).JPG



31. SE opening (1).JPG



32. SE opening (2).JPG



33. SE opening (3).JPG



34. SE opening (4).JPG




35. SW opening (1).JPG



36. SW opening (2).JPG



37. SW opening (3).JPG



38. SW opening (4).JPG



39. W Abutment, S end.JPG



40. W Approach, EB lane.JPG



41. W Approach, SW corner.JPG