

**2016 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 62588
CSAH 44 NB over CP RAIL**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: St Anthony

STATE: Minnesota

Date of Inspection: 10/07/2016

Equipment Used:

Owner: County Highway Agency

Inspected By: Bodelson, Dan

Report Written By: Dan Bodelson

Report Reviewed By: Nicklaus Fischer

Final Report Date: 10/25/2016




Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
STRUCTURE INVENTORY	3
ROUTINE INSPECTION DATA	4
ELEMENTS	8
PICTURES	12
MAINTENANCE	14
STRUCTURAL ASSESSMENT REPORT - ROUTINE	15

Minnesota Structure Inventory Report

Bridge ID: 62588

CSAH 44 NB

over CP RAIL

Date: 10/25/2016

GENERAL	
Agency Br. No.	
District Metro	
Maint. Area	Crew
County 062 - Ramsey	
City St Anthony	
Township	
Desc. Loc. 0.1 MI N OF JCT CSAH 19	
Sect., Twp., Range 31 - 030N - 23W	
Latitude Deg 45 Min 2 Sec 12.80	
Longitude Deg 93 Min 13 Sec 6.07	
Custodian 02 - County Highway Agency	
Owner 02 - County Highway Agency	
BMU Agreement	
Year Built	2001
MN Year Reconstructed	
FHWA Year Reconstructed	
MN Temporary Status	
Bridge Plan Location 3 - COUNTY	
Date Opened to Traffic	
On-Off System 1 - ON	
Legislative District 50A	
ABC Suitable	

STRUCTURE	
Service On 1 - Highway	
Service Under 2 - Railroad	
Main Span Type	
2 - Concrete Continuous 09 - Slab Span	
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew 16 L	
Culvert Type	
Barrel Length	ft.
Cantilever ID	

NUMBER OF SPANS	
MAIN: 3 APPR: 0 TOTAL: 3	
Main Span Length 55.8 ft.	
Structure Length 139.6 ft.	
Deck Width (Out-to-Out) 84.6 ft.	
Deck Material 1 - Concrete Cast-in-Place	
Wear Surf Type 4 - Low Slump Concrete	
Wear Surf Install Year 2001	
Wear Course/Fill Depth 0.25 ft.	
Deck Membrane 0 - None	
Deck Rebars 1 - Epoxy Coated Reinforcing	
Deck Rebars Install Year 2001	
Structure Area (Out-to-Out) 11981 sq. ft.	
Roadway Area (Curb-to-Curb) 9870 sq. ft.	
Sidewalk Width Lt 0.00 ft. Rt 0.00 ft.	
Curb Height Lt 0.00 ft. Rt 0.00 ft.	
Rail Type Lt 28 Rt 28	

ROADWAY	
Bridge Match ID (TIS) 0	
Roadway O/U Key Route On Structure	
Route Sys 04 - CSAH Number 44	
Roadway Name or Description	
CSAH 44	
Level of Service 1 - MAINLINE	
Roadway Type 2 - 2-way traffic	
Control Section (TH Only)	
Reference Point 000+00.091	
Detour Length 2.0 mi	
Lanes On 4 Under 0	
ADT 22609 Year 2008	
HCACT 0 ADTT 0 %	
Functional Class 16 - Urban - Minor Arterial	

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	38.10 ft.	27.60	ft.
Vertical Clearance	ft.	ft.	ft.
Max. Vert. Clear.	ft.	ft.	ft.
Horizontal Clear.	69.7 ft.	ft.	ft.
Lateral Clearance	ft.	ft.	ft.
Appr. Surface Width	66.0 ft.		
Bridge Roadway Width	65.7 ft.		
Median Width On Bridge	3.90 ft.		

MISC. BRIDGE DATA	
Structure Flared 0 - No flare	
Parallel Structure N - No parallel structure	
Field Conn. ID	
Abutment Foundation 1 - CONC	
(Material/Type) 3 - FTG PILE	
Pier Foundation 1 - CONC	
(Material/Type) 3 - FTG PILE	
Historic Status 5 - Not eligible	

PAINT	
Year Painted	
Unsound Paint %	
Painted Area sq. ft.	
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load 0 - Not Required	
Traffic 0 - Not Required	
Horizontal 0 - Not Required	
Vertical N - Not Applicable	

INSPECTION	
Userkey 102	
Unofficial Structurally Deficient N	
Unofficial Functionally Obsolete N	
Unofficial Sufficiency Rating 92.7	
Routine Inspection Date 10/07/2016	
Routine Inspection Frequency 24	
Inspector Name CO Bridge	
Status A - Open	

NBI CONDITION RATINGS	
Deck 6 - Satisfactory Condition	
Unsound Deck %	
Superstructure 6 - Satisfactory Condition	
Substructure 8 - Very Good Condition	
Channel N - Not Applicable	
Culvert N - Not Applicable	

NBI APPRAISAL RATINGS	
Structure Evaluation 6	
Deck Geometry 7	
Underclearances 4	
Water Adequacy N - Not Applicable	
Approach Alignment 7 - Better than present minir	

SAFETY FEATURES	
Bridge Railing 1 - MEETS STANDARDS	
GR Transition 0 - SUBSTANDARD	
Appr. Guardrail 0 - SUBSTANDARD	
GR Termini 0 - SUBSTANDARD	

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical	N		
Underwater	N		
Pinned Asbly.	N		
Spec. Feat.			

WATERWAY	
Drainage Area (sq. mi.)	
Waterway Opening	sq. ft.
Navigation Control N - Not applicable, no waterw	
Pier Protection	
Nav. Clr. (ft.) Vert. ft. Horiz. ft.	
Nav. Vert. Lift Bridge Clear. (ft.)	
MN Scour Code A - NON WATER' Year 2001	

CAPACITY RATINGS	
Design Load 9 - HS 25 (OR GREATER)	
Operating Rating 1 - LF (LF) HS 53.9	
Inventory Rating 1 - LF (LF) HS 25.0	
Posting VEH: SEMI: DBL:	
Rating Date 2/11/2000	
Minnesota Permit Codes	
A: N - N/A	
B: N - N/A	
C: N - N/A	

Minnesota Structure Inventory Report

Bridge ID: 62588

CSAH 44 NB over CP RAIL

Date: 10/05/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
Agency Br. No. Crew District 05 Maint. Area County 062 - Ramsey City St Anthony Township Desc. Loc. 0.1 MI N OF JCT CSAH 19 Sect., Twp., Range 31 - 030N - 23W Latitude 45 ° 2' 12.80 " Longitude 93 ° 13' 6.07 " Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 2001 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 3 - COUNTY Date Opened to Traffic On - Off System 1 - ON Legislative District 50A Potential ABC 2 - N/A	Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 04 - CSAH Number 44 Roadway Name or Description CSAH 44 Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point 000+00.091 Detour Length 2.0 mi. Lanes ON 4 UNDER 0 ADT 22609 YEAR 2008 HCA DT ADTT % Functional Class 16 - Urban - Minor Arterial	Userkey 102 Structurally Deficient N Functionally Obsolete N Sufficiency Rating 92.7 Routine Inspection Date 10/07/2016 Routine Inspection Frequency 24 Inspector Name Bodelson, Dan Status A - Open																				
		+ NBI CONDITION RATINGS +																				
		Deck 6 Unsound Deck % Superstructure 6 Substructure 8 Channel N Culvert N																				
		+ NBI APPRAISAL RATINGS +																				
		Structure Evaluation 6 Deck Geometry 7 Underclearances 4 Waterway Adequacy N Approach Alignment 7																				
		+ SAFETY FEATURES +																				
		Bridge Railing 1 - MEETS STANDARDS GR Transition 0 - SUBSTANDARD Appr. Guardrail 0 - SUBSTANDARD GR Termini 0 - SUBSTANDARD																				
		+ IN DEPTH INSP. +																				
		<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Underwater</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Pinned Asbly.</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	Frac. Critical	N			Underwater	N			Pinned Asbly.	N			Spec. Feat.			
	Y/N	Freq	Date																			
Frac. Critical	N																					
Underwater	N																					
Pinned Asbly.	N																					
Spec. Feat.																						
		+ WATERWAY +																				
		Drainage Area (sq. mi.) Waterway Opening (sf.) Navigation Control N - Not applicable, no Pier Protection - Nav. Clr. (ft.) Vert. 0.0 Horiz. 0.0 Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code A - NON Year 2001																				
		+ CAPACITY RATINGS +																				
		Design Load 9 - HS 25 (OR GREATER) Operating Rating 2 - HS TRUCK 53.9 Inventory Rating 2 - HS TRUCK 25.0 Posting VEH: SEMI: DBL: Rating Date 2/11/2000 Overweight Permit Codes A N - N/A B N - N/A C N - N/A																				
+ STRUCTURE +	+ RDWY DIMENSIONS +																					
Service On 1 - Highway Service Under 2 - Railroad Main Span Type 2 - Concrete Continuous Main Span Design 09 - Slab Span Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 16 LEFT Culvert Type Barrel Length Cantilever ID Number of Spans MAIN: 3 APPR: 0 TOTAL: Main Span Length 55.8 ft. Structure Length 139.6 ft. Deck Width (Out-to-Out) 84.6 ft. Deck Material 1 - Concrete Cast-in-Place Wear Surf Type 4 - Low Slump Concrete Wear Surf Install Year 2001 Wear Course/Fill Depth 0.25 ft. Deck Membrane 0 - None Deck Rebars 1 - Epoxy Coated Reinforcing Deck Rebars Install Year 2001 Structure Area (Out-to-Out) 11981 sq. ft. Roadway Area (Curb-to-Curb) 9870 sq. ft. Sidewalk Width 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. Curb Height Lt 0.00 ft. Rt 0.00 ft. Rail Type Lt 28 Rt 28	If Divided NB-EB SB-WB Roadway Width 38.10 ft. 27.60 ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. 69.7 ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 66.0 ft. Bridge Roadway Width 65.7 ft. Median Width On Bridge 3.90 ft.																					
	+ MISC. BRIDGE DATA +																					
	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID Abutment Foundation (Material/Type) 1 - CONC 3 - FTG PILE Pier Foundation (Material/Type) 1 - CONC 3 - FTG PILE Historic Status 5 - Not eligible																					
	+ PAINT +																					
	Year Painted Unsound Paint % Painted Area sq. ft. Primer Type Finish Type																					
	+ BRIDGE SIGNS +																					
	Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 0 - Not Required Vertical N - Not Applicable																					

MINNESOTA BRIDGE INSPECTION REPORT

10/25/2016

BRIDGE 62588 CSAH 44 NB OVER CP RAIL

ROUTINE INSP. DATE: 10/07/2016

County: Ramsey	Location: 0.1 MI N OF JCT CSAH 19	Length: 139.6 ft.
City: St Anthony	Route: 04 - CSAH 44 Ref. Pt.: 000+00.091	Deck Width: 84.6 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 9870 sq. ft. / %
Section: 31 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 2 - Concrete Continuous 1 - Slab	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:
NBI Deck: 6 Super: 6 Sub: 8 Chan: N Culv: N		

	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 7 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 92.7

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
----------	--------------	-----	-------------	------------	----------	----------	----------	----------	----------	----------

205	Reinforced Concrete Column	1	Routine	10/07/2016	14 EA	0	14	0	0	N/A
			Routine	10/10/2014	14 EA	0	14	0	0	N/A

Notes: [2008-2014] Minor spalls are present.
 [2003-2014] There is graffiti on the columns. [2006] Graffiti has been painted over.

215	Reinforced Concrete Abutment	1	Routine	10/07/2016	171 LF	161	10	0	0	N/A
			Routine	10/10/2014	171 LF	161	10	0	0	N/A

Notes: [2014] The south abutment has 5 minor vertical cracks. The north abutment has 7 minor vertical cracks.
 [2006-2012] The south abutment has 5 minor vertical cracks. The north abutment has 5 minor vertical cracks.
 [2008] The south abutment has a moderate crack @ construction joint.
 [2003-2006] Vertical crack through each abutment @ centerline + 2 other vertical cracks in each abutment.
 [2003-2012] Graffiti on north abutment.

300	Strip Seal Deck Joint	1	Routine	10/07/2016	180 LF	0	180	0	N/A	N/A
			Routine	10/10/2014	180 LF	0	180	0	N/A	N/A

Notes: [2010-2014] Evidence of minor leakage. Expansion joint may need to be cleaned & flushed for further inspection.
 [2008] Debris in the joint may be causing problems, but no sign of leakage.
 [2002-2006] Expansion joint has no deterioration but needs to be cleaned & flushed for further inspection.

301	Poured Deck Joint	1	Routine	10/07/2016	180 LF	0	180	0	N/A	N/A
			Routine	10/10/2014	180 LF	0	180	0	N/A	N/A

Notes: [2008-2014] Moderate adhesion & cohesion failure of joint seal.
 [2002-2006] Minor adhesion & cohesion failure of joint seal.

310	Elastomeric (Expansion) Bearing	1	Routine	10/07/2016	14 EA	14	0	0	N/A	N/A
			Routine	10/10/2014	14 EA	14	0	0	N/A	N/A

Notes: [2012-2014] Minor deterioration is present. Bearing seat is in good condition. [2001-2010] No deterioration.

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
321	Concrete Approach Slab-Concrete Wearing Surface	1	Routine	10/07/2016	2 EA	0	2	0	0	N/A
			Routine	10/10/2014	2 EA	0	2	0	0	N/A
<p>Notes: [2012-2014] There is some settlement of the bituminous approach roadway resulting on impact on the approach slabs. South Approach Slab. [2006-2014] The east 1/2 of the south approach slab has 27 LF of transverse cracks. The west 1/2 of the south approach slab has 39 LF of longitudinal cracks + 24 LF of transverse cracks. [2002-2014] Longitudinal crack in south approach slab on west side at the storm sewer MH. North Approach Slab [2008-2014] The west 1/2 of the north approach slab has 65 LF of longitudinal & transverse cracks. [2002-2006] Minor crack in NW approach slab. Minor spalling in NE approach slab.</p>										
333	Masonry, Other or Combination Material Railing	1	Routine	10/07/2016	479 LF	0	479	0	N/A	N/A
			Routine	10/10/2014	479 LF	0	479	0	N/A	N/A
<p>Notes: [2006-2014] There is moderate vertical cracking with efflorescence extending through the deck at the west fascia. [2003-2012] There are 2 areas of delamination on the west railing near the NW corner. [2001-2014] There is moderate vertical & horizontal cracking with w/moderate spalling & efflorescence @ both sides. Spalling is due to mix design. [2008-2014] The ornamental metal railing has some chalking. The railing consists of a combination concrete parapet & ornamental metal railing.</p>										
358	Concrete Deck Cracking Smart Flag	1	Routine	10/07/2016	1 EA	0	1	0	0	N/A
			Routine	10/10/2014	1 EA	0	1	0	0	N/A
<p>Notes: [2008-2014] Minor to moderate longitudinal and transverse deck cracking. Minor spalls are present. [2002-2006] Minor longitudinal and transverse deck cracking with no spalls.</p>										
359	Underside of Concrete Deck Smart Flag	1	Routine	10/07/2016	1 EA	0	1	0	0	0
			Routine	10/10/2014	1 EA	0	1	0	0	0
<p>Notes: SPAN #1 [2010-2014] There is longitudinal cracking with efflorescence at the centerline joint. Also near centerline contains two 10' transverse cracks with efflorescence and a 10' longitudinal crack at bearing #5. There is a longitudinal crack with efflorescence entire length at bearing #2. SPAN #2 [2008-2014] There is 35 LF of longitudinal cracking near column #3. [2008-2014] Span #2 also has 35 LF transverse cracking with efflorescence near centerline. SPAN#14] There is 12' longitudinal cracking with efflorescence @ bearing #6. There are 4' & 6' transverse cracks at column #4.</p>										
362	Traffic Impact Smart Flag	1	Routine	10/07/2016	1 EA	0	1	0	N/A	N/A
			Routine	10/10/2014	1 EA	0	1	0	N/A	N/A
<p>Notes: [2002-2014] Minor surface damage. No structural damage to the concrete railing. Could use paint @ traffic impact. [2002] Traffic impact has occurred to bridge rail 1/4 north of SE corner of bridge. 10' section of the ornamental metal railing was replaced in 2002.</p>										
378	Low Slump O/L (Concrete Slab with Epoxy Rebar)	1	Routine	10/07/2016	11980 SF	0	11980	0	0	0
			Routine	10/10/2014	11980 SF	0	11980	0	0	0
<p>Notes: [2010-2014] There are moderate spalls throughout the deck. Distress is around 2%- still in condition state #2. [2008] There is moderate spalling on the west side and minor spalling on the east side. [2010-2014] Each side has over 100 LF of longitudinal & transverse cracking. [2006] The east 1/2 has 24 LF of longitudinal & transverse cracks @ median. The west 1/2 has 40 LF of longitudinal & transverse cracks.</p>										

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
387	Reinforced Concrete Wingwall	1	Routine	10/07/2016	4 EA	0	4	0	0	N/A
			Routine	10/10/2014	4 EA	0	4	0	0	N/A
Notes: [2014] SE wingwall has a 2' and a 3' crack w/efflorescence. SW wingwall has a 2' crack w/efflorescence. [2006-2012] SW wingwall has minor horizontal & vertical cracking. NW wingwall has horizontal & vertical cracking with efflorescence. [2008-2012] The SE wingwall has minor spalls present. [2003-2012] NE abutment wing has 2 minor horizontal cracks and 2 minor vertical cracks w/efflorescence.										
964	Critical Finding Smart Flag	2	Routine	10/07/2016	1 EA	1	0	N/A	N/A	N/A
			Routine	10/10/2014	1 EA	1	0	N/A	N/A	N/A
Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.										
983	Plowstraps	1	Routine	10/07/2016	1 EA	0	1	0	N/A	N/A
			Routine	10/10/2014	1 EA	0	1	0	N/A	N/A
Notes: [2012-2014] There is a plowstrap missing at the NW quadrant. [2002-2010] Plowstraps are in place & show no sign of deterioration.										
984	Deck & Approach Drainage	1	Routine	10/07/2016	1 EA	1	0	0	N/A	N/A
			Routine	10/10/2014	1 EA	1	0	0	N/A	N/A
Notes: [2002-2014] Drainage system is operating properly.										
985	Slopes & Slope Protection	1	Routine	10/07/2016	1 EA	0	1	0	N/A	N/A
			Routine	10/10/2014	1 EA	0	1	0	N/A	N/A
Notes: [2002-2014] Some aggregate was dug out near top on the right at the south end. Some aggregate is loose. [2006-2014] There is some minor settlement on the south side. Slope protection is asphaltic coated crushed aggregate.										
986	Curb & Sidewalk	1	Routine	10/07/2016	1 EA	0	1	0	N/A	N/A
			Routine	10/10/2014	1 EA	0	1	0	N/A	N/A
Notes: [2008-2014] There are numerous minor transverse cracking on the west side. [2006-2014] There are numerous moderate cracks on the east side almost the entire length of the sidewalk. Curb at the NW corner is beat up by snowplow @ approach panel. [2001-2014] Minor - moderate spalling on sidewalk both sides. [2003-2006] Spalling caused by soft aggregate in mix. [2001-2014] There is minor settlement @ SW corner of the bridge.										

General Notes: [2016] Bridge safety inspection was conducted by Dan Bodelson & Brian Essler 10/07/2016.
[2014] Bridge safety inspection was conducted by D. Bodelson & B. Essler 10/10/2014.
[2010] Bridge safety inspection was conducted by B. Wieman on 10/27/2010.
[2008] Bridge safety inspection was conducted by B. Wieman & B. Essler 10/30/2008.
Bridge safety inspection was conducted by Bret Wieman & Brian Essler. 11/17/2006.
Bridge #62588 is 12m, 17m & 12m continuous concrete slab spans built in 2000.

58. Deck NBI: Concrete deck has moderate cracking, leaching & scaling with minor spalls.

36A. Brdg Railings NBI: Vehicular railing meets current standards

36B. Transitions NBI: No guardrail

36C. Appr Guardrail NBI: No guardrail

36D. Appr Guardrail NBI: No guardrail
Terminal NBI:

59. Superstructure NBI: Concrete has moderate scaling & cracking with minor spalling & delamination.

60. Substructure NBI: Concrete has minor cracking & scaling.

61. Channel NBI: CSAH # 44 over CP Rail - no water

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
-------------	--------------	-----	-------------	------------	----------	-------------	-------------	-------------	-------------	-------------

62. Culvert NBI: CSAH # 44 over CP Rail - no water

71. Waterway Adeq NBI: CSAH # 44 over CP Rail - no water

72. Appr Roadway Alignment NBI: Minor sight distance problem with vertical curve over bridge, no speed reduction required.

Inventory Notes:

Dan Bodelson

Inspector's Signature

Nicklaus Fischer

Reviewer's Signature

MINNESOTA BRIDGE INSPECTION REPORT

10/25/2016

Inspector: CO Bridge

BRIDGE 62588 CSAH 44 NB OVER CP RAIL

County: Ramsey	Location: 0.1 MI N OF JCT CSAH 19	Length: 139.6 ft.
City: St Anthony	Route: 04 - CSAH 44 Ref. Pt.: 000+00.091	Deck Width: 84.6 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 9870 sq. ft. / %
Section: 31 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 2 - Concrete Continuous 1 - Slab	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:
NBI Deck: 6 Super: 6 Sub: 8 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 7 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 92.7

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
38	Reinforced Concrete Slab	Routine	10/07/2016	11981 SF	11741	0	240	0
		Migrated Values		11981 SF	11741	0	240	0

Notes: SPAN #1
 [2010-2016] There is longitudinal cracking with efflorescence at the centerline joint. Also near centerline contains two 10' transverse cracks with efflorescence and a 10' longitudinal crack at bearing #5.
 There is a longitudinal crack with efflorescence entire length at bearing #2.
 SPAN #2
 [2008-2016] There is 35 LF of longitudinal cracking near column #3.
 [2008-2016] Span #2 also has 35 LF transverse cracking with efflorescence near centerline.
 [2014-2016] There is 12' longitudinal cracking with efflorescence @ bearing #6. There are 4' & 6' transverse cracks at column #4.

510 - Wearing Surfaces	Routine	10/07/2016	9870 SF	9673	0	197	0
	Migrated Values		9870 SF	9673	0	197	0

Notes: Concrete Slab with Cathodic Protection System Notes:
 [2010-2014] There are moderate spalls throughout the deck. Distress is around 2%- still in condition state #2.
 [2016] Numerous cracks on west facia.
 [2008] There is moderate spalling on the west side and moderate spalling on the east side.
 [2010-2016] Each side has over 100 LF of longitudinal & transverse cracking.
 [2006] The east 1/2 has 24 LF of longitudinal & transverse cracks @ median. The west 1/2 has 40 LF of longitudinal & transverse cracks.

205	Reinforced Concrete Column	Routine	10/07/2016	14 EA	0	14	0	0
		Migrated Values		14 EA	0	14	0	0

Notes: [2016] Minor paint failure.
 [2008-2016] Minor spalls are present.
 [2003-2016] There is graffiti on the columns. [2006] Graffiti has been painted over.

215	Reinforced Concrete Abutment	Routine	10/07/2016	290 LF	240	50	0	0
		Migrated Values		290 LF	240	50	0	0

Notes: [2016] Minor paint failure.
 [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:0 CS2:40 CS3:0 CS4:0).
 [2016] Wingwalls are 21' each x 4 = 84' + 101' south abut. + 105' north abut. = 290 LF (measurements taken from plans)
 [2014-2016] The south abutment has 5 minor vertical cracks. The north abutment has 7 minor vertical cracks.
 [2006-2016] The south abutment has 5 minor vertical cracks. The north abutment has 5 minor vertical cracks.
 [2008-2016] The south abutment has a moderate crack @ construction joint.
 [2003-2016] Vertical crack through each abutment @ centerline + 2 other vertical cracks in each abutment.
 [2003-2016] Graffiti on north abutment.

Wingwall notes: [2014-2016] SE wingwall has a 2' and a 3' crack w/efflorescence. SW wingwall has a 2' crack w/efflorescence.
 [2006-2016] SW wingwall has minor horizontal & vertical cracking. NW wingwall has horizontal & vertical cracking with efflorescence.
 [2008-2016] The SE wingwall has minor spalls present.
 [2003-2016] NE abutment wing has 2 minor horizontal cracks and 4 minor vertical cracks w/efflorescence.

BRIDGE 62588 CSAH 44 NB OVER CP RAIL

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
300	Strip Seal Expansion Joint	Routine	10/07/2016	180 LF	0	180	0	0
		Migrated Values		180 LF	0	180	0	0
Notes: [2010-2016] Evidence of minor leakage. Expansion joint may need to be cleaned & flushed for further inspection. [2008] Debris in the joint may be causing problems, but no sign of leakage. [2002-2006] Expansion joint has no deterioration but needs to be cleaned & flushed for further inspection.								
301	Pourable Joint Seal	Routine	10/07/2016	180 LF	0	180	0	0
		Migrated Values		180 LF	0	180	0	0
Notes: [2008-2016] Moderate adhesion & cohesion failure of joint seal. [2002-2006] Minor adhesion & cohesion failure of joint seal.								
310	Elastomeric Bearing	Routine	10/07/2016	14 EA	14	0	0	0
		Migrated Values		14 EA	14	0	0	0
Notes: [2012-2016] Minor deterioration is present. Bearing seat is in good condition. [2001-2010] No deterioration.								
321	Reinforced Concrete Approach Slab	Routine	10/07/2016	5984 SF	0	5919	65	0
		Migrated Values		5984 SF	0	5919	65	0
Notes: [2016] Bridge approach slabs are 44' long x 28' wide x 2 = 2464 SF & 44' long x 40' wide (left turn lanes) x 2 = 3520 SF - 5984 total. [2016] Migrator assumed an approach slab length of 20FT and used the inventory quantity of 66FT for the width. [2012-2016] There is moderate settlement of the bituminous on the north approach roadway resulting on impact on the approach slabs. South Approach Slab. [2006-2016] The east 1/2 of the south approach slab has 27 LF of transverse cracks. The west 1/2 of the south approach slab has 39 LF of longitudinal cracks + 24 LF of transverse cracks. [2002-2016] 40' of longitudinal crack in south approach slab on west side at the storm sewer MH. North Approach Slab [2008-2016] The west 1/2 of the north approach slab has 65 LF of moderate longitudinal & transverse cracks. (65' in condition state 3) [2002-2006] Minor crack in NW approach slab. Minor spalling in NE approach slab.								
330	Metal Bridge Railing	Routine	10/07/2016	479 LF	0	479	0	0
		Migrated Values		479 LF	0	479	0	0
Notes: [2016] Migrator assumed concrete/metal combination type rail. [2006-2016] There is moderate vertical cracking with efflorescence extending through the deck at the west fascia. [2003-2012] There are 2 areas of delamination on the west railing near the NW corner. [2001-2016] There is moderate vertical & horizontal cracking with w/moderate spalling & efflorescence @ both sides. Spalling is due to mix design. [2008-2016] The ornamental metal railing has some chalking. The railing consists of a combination concrete parapet & ornamental metal railing.								
515	Steel Protective Coating	Routine	10/07/2016	797 SF	0	797	0	0
		Migrated Values		797 SF	0	797	0	0
Notes: [2016] Migrator assumed CS1 and a quantity of 999 SF. [2016] Metal railing is 374' long x 2.13' high = 797 SF [2016] There is moderate rust on caps & bolts of all posts. [2008-2016] The ornamental metal railing has some chalking.								
331	Reinforced Concrete Bridge Railing	Routine	10/07/2016	479 LF	0	479	0	0
		Migrated Values		479 LF	0	479	0	0
Notes: [2016] Migrator assumed concrete/metal combination type rail. [2016] 1' x 1' major spall on east side of east rail - 20' from north end. [2016] Moderate paint failure on both railings. [2006-2016] There is moderate vertical cracking with efflorescence extending through the deck at the west fascia. [2003-2016] There are 2 areas of delamination on the west railing near the NW corner. [2001-2016] There is moderate vertical & horizontal cracking with w/moderate spalling & efflorescence @ both sides. Spalling is due to mix design. The railing consists of a combination concrete parapet & ornamental metal railing.								
800	Critical Deficiencies or Safety Hazards	Routine	10/07/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION.								

BRIDGE 62588 CSAH 44 NB OVER CP RAIL

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
810	Concrete Decks - Cracking & Sealing	Routine	10/07/2016	475 LF	0	475	0	0
		Migrated Values		475 LF	0	475	0	0
Notes: [2016] 265' minor cracking on southbound & 210' minor cracking northbound. = 475' total. [2008-2016] Minor to moderate longitudinal and transverse deck cracking with effluence. Minor spalls are present. [2002-2006] Minor longitudinal and transverse deck cracking with no spalls.								
815	Plow Fingers	Routine	10/07/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2012-2016] There is a plowstrap missing at the NW quadrant. [2002-2010] Plowstraps are in place & show no sign of deterioration.								
880	Impact Damage	Routine	10/07/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2002-2016] Minor surface damage. No structural damage to the concrete railing. Could use paint @ traffic impact. [2002] Traffic impact has occurred to bridge rail 1/4 north of SE corner of bridge. 10' section of the ornamental metal railing was replaced in 2002.								
892	Slopes & Slope Protection	Routine	10/07/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2002-2016] Some aggregate was dug out near top on the right at the south end. Some aggregate is loose. [2006-2014] There is some minor settlement on the south side. Slope protection is asphaltic coated crushed aggregate.								
894	Deck & Approach Drainage	Routine	10/07/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: [2002-2016] Drainage system is operating properly.								
895	Sidewalk, Curb, & Median	Routine	10/07/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2008-2016] There are numerous minor transverse cracking on the west side. [2006-2016] There are numerous moderate cracks on the east side almost the entire length of the sidewalk. Curb at the NW corner is beat up by snowplow @ approach panel. [2001-2016] Minor - moderate spalling on sidewalk both sides. [2003-2006] Spalling caused by soft aggregate in mix. [2001-2016] There is minor settlement @ SW corner of the bridge.								
900	Protected Species	Routine	10/07/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure. [2016] No protective species found.								

General Notes: [2016] Bridge safety inspection was conducted by Dan Bodelson & Brian Essler 10/07/2016.
[2014] Bridge safety inspection was conducted by D. Bodelson & B. Essler 10/10/2014.
[2010] Bridge safety inspection was conducted by B. Wieman on 10/27/2010.
[2008] Bridge safety inspection was conducted by B. Wieman & B. Essler 10/30/2008.
Bridge safety inspection was conducted by Bret Wieman & Brian Essler. 11/17/2006.
Bridge #62588 is 12m, 17m & 12m continuous concrete slab spans built in 2000.

58. Deck NBI: Concrete deck has moderate cracking, leaching & scaling with minor spalls.

36A. Brdg Railings NBI: Vehicular railing meets current standards

36B. Transitions NBI: No guardrail

36C. Appr Guardrail NBI: No guardrail

36D. Appr Guardrail Terminal NBI: No guardrail

59. Superstructure NBI: Concrete has moderate scaling & cracking with minor spalling & delamination.

60. Substructure NBI: Concrete has minor cracking & scaling.

61. Channel NBI: CSAH # 44 over CP Rail - no water

BRIDGE 62588 CSAH 44 NB OVER CP RAIL

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
-------------	--------------	-------------	------------	----------	-------------	-------------	-------------	-------------

62. Culvert NBI: CSAH # 44 over CP Rail - no water

71. Waterway Adeq NBI: CSAH # 44 over CP Rail - no water

72. Appr Roadway Alignment NBI: Minor sight distance problem with vertical curve over bridge, no speed reduction required.

Inventory Notes:

Dan Bodelson
Inspector's Signature

Nicklaus Fischer
Reviewer's Signature

Pictures



Photo 1 -



Photo 2 -

Pictures



Photo 3 -



Photo 4 -

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------

BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the Minnesota Bridge Office upon receipt of the 7 Day FC Report; however, it is an **OPTIONAL** tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62588	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 10/07/2016	STRUCTURE TYPE: Concrete Continuous lab
FACILITY CARRIED: CSAH 44 NB	FEATURES INTERSECTED: CP RAIL
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> COMPLEX:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- | | |
|---|---|
| <input type="checkbox"/> Repair/Maintenance | <input type="checkbox"/> Monitoring Plan |
| <input type="checkbox"/> Complex | <input type="checkbox"/> Increased Inspection Frequency |

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer