

**2016 ROUTINE  
BRIDGE INSPECTION REPORT**



**BRIDGE # 62590  
CSAH 96 over SUCKER CREEK UNSTABLE MA**


**DISTRICT:** Metro                      **COUNTY:** Ramsey                      **CITY/TOWNSHIP:** Vadnais Heights  
**STATE:** Minnesota

**Date of Inspection:** 09/08/2016  
**Equipment Used:** Chain Drag

**Owner:** County Highway Agency

**Inspected By:** Bodelson, Dan

**Report Written By:** Dan Bodelson  
**Report Reviewed By:** Nicklaus Fischer  
**Final Report Date:** 10/20/2016



# Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
STRUCTURE INVENTORY	2
ELEMENTS	3
PICTURES	6

# Minnesota Structure Inventory Report

Bridge ID: 62590

CSAH 96 over SUCKER CREEK  
UNSTABLE MA

Date: 09/08/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +			
<b>Agency Br. No.</b> Crew <b>District</b> 05 <b>Maint. Area</b> <b>County</b> 062 - Ramsey <b>City</b> Vadnais Heights <b>Township</b> <b>Desc. Loc.</b> 0.5 MI E OF JCT CSAH 54 <b>Sect., Twp., Range</b> 19 - 030N - 22W <b>Latitude</b> 45 ° 4 ' 44.68 " <b>Longitude</b> 93 ° 5 ' 55.38 " <b>Custodian</b> 02 - County Highway Agency <b>Owner</b> 02 - County Highway Agency <b>BMU Agreement</b> <b>Year Built</b> 1999 <b>MN Year Reconstructed</b> <b>FHWA Year Reconstructed</b> <b>MN Temporary Status</b> <b>Bridge Plan Location</b> 3 - COUNTY <b>Date Opened to Traffic</b> <b>On - Off System</b> 1 - ON <b>Legislative District</b> 54B <b>Potential ABC</b> 2 - N/A	<b>Bridge Match ID (TIS)</b> 0 <b>Roadway O/U Key</b> Route On Structure <b>Route Sys</b> 04 - CSAH <b>Number</b> 96 <b>Roadway Name or Description</b> CSAH 96 <b>Level of Service</b> 1 - MAINLINE <b>Roadway Type</b> 2 - 2-way traffic <b>Control Section (TH Only)</b> <b>Reference Point</b> 004+00.777 <b>Detour Length</b> 1.0 mi. <b>Lanes</b> ON 4 UNDER 0 <b>ADT</b> 20916 <b>YEAR</b> 2008 <b>HCADT</b> <b>ADTT</b> % <b>Functional Class</b> 16 - Urban - Minor Arterial	<b>Userkey</b> 102 <b>Structurally Deficient</b> N <b>Functionally Obsolete</b> N <b>Sufficiency Rating</b> 98.0 <b>Routine Inspection Date</b> 09/08/2016 <b>Routine Inspection Frequency</b> 24 <b>Inspector Name</b> Bodelson, Dan <b>Status</b> A - Open			
		+ NBI CONDITION RATINGS +			
		<b>Deck</b>	6	<b>Unsound Deck %</b>	
		<b>Superstructure</b>	6		
		<b>Substructure</b>	7		
		<b>Channel</b>	N		
		<b>Culvert</b>	N		
		+ NBI APPRAISAL RATINGS +			
		<b>Structure Evaluation</b>	6		
		<b>Deck Geometry</b>	9		
		<b>Underclearances</b>	N		
		<b>Waterway Adequacy</b>	N		
		<b>Approach Alignment</b>	8		
		+ SAFETY FEATURES +			
		<b>Bridge Railing</b>	N - NOT REQUIRED		
		<b>GR Transition</b>	N - NOT REQUIRED		
		<b>Appr. Guardrail</b>	N - NOT REQUIRED		
		<b>GR Termini</b>	N - NOT REQUIRED		
		+ IN DEPTH INSP. +			
			Y/N	Freq	Date
		<b>Frac. Critical</b>	N		
		<b>Underwater</b>	N		
		<b>Pinned Asbly.</b>	N		
		<b>Spec. Feat.</b>			
		+ WATERWAY +			
		<b>Drainage Area (sq. mi.)</b>			
		<b>Waterway Opening (sf.)</b>			
		<b>Navigation Control</b>	N - Not applicable, no		
		<b>Pier Protection</b>			
		<b>Nav. Clr. (ft.)</b>	Vert.	0.0	Horiz.
		<b>Nav. Vert. Lift Bridge Clear. (ft.)</b>			
		<b>MN Scour Code</b>	A - NON	Year	
		+ CAPACITY RATINGS +			
		<b>Design Load</b>	9 - HS 25 (OR GREATER)		
		<b>Operating Rating</b>	2 - HS TRUCK	36.4	
		<b>Inventory Rating</b>	2 - HS TRUCK	21.8	
		<b>Posting VEH:</b>	<b>SEMI:</b>	<b>DBL:</b>	
		<b>Rating Date</b>	10/25/2013		
		Overweight Permit Codes			
		<b>A</b>	N - N/A	<b>B</b>	N - N/A
		<b>C</b>	N - N/A		
+ STRUCTURE +	+ RDWY DIMENSIONS +	+ NBI APPRAISAL RATINGS +			
<b>Service On</b> 1 - Highway <b>Service Under</b> 0 - Other <b>Main Span Type</b> 2 - Concrete Continuous <b>Main Span Design</b> 09 - Slab Span <b>Main Span Detail</b> <b>Appr. Span Type</b> <b>Appr. Span Design</b> <b>Appr. Span Detail</b> <b>Skew</b> 0 <b>Culvert Type</b> <b>Barrel Length</b> <b>Cantilever ID</b>  <b>Number of Spans</b> <b>MAIN:</b> 15 <b>APPR:</b> 0 <b>TOTAL:</b> <b>Main Span Length</b> 30.0 ft. <b>Structure Length</b> 434.7 ft. <b>Deck Width (Out-to-Out)</b> 68.1 ft. <b>Deck Material</b> 1 - Concrete Cast-in-Place <b>Wear Surf Type</b> 1 - Monolithic Concrete <b>Wear Surf Install Year</b> <b>Wear Course/Fill Depth</b> 0.00 ft. <b>Deck Membrane</b> 0 - None <b>Deck Rebars</b> 1 - Epoxy Coated Reinforcing <b>Deck Rebars Install Year</b> 1999 <b>Structure Area (Out-to-Out)</b> 29603 sq. ft. <b>Roadway Area (Curb-to-Curb)</b> 29084 sq. ft. <b>Sidewalk Width</b> 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. <b>Curb Height</b> Lt 0.33 ft. Rt 0.33 ft. <b>Rail Type</b> Lt NN Rt NN	<b>If Divided</b> <b>NB-EB</b> <b>SB-WB</b> <b>Roadway Width</b> 66.90 ft. ft. <b>Vertical Clearance</b> ft. ft. <b>Max. Vert. Clear.</b> ft. ft. <b>Horizontal Clear.</b> ft. ft. <b>Lateral Clearance</b> ft. ft. <b>Appr. Surface Width</b> 67.0 ft. <b>Bridge Roadway Width</b> 66.9 ft. <b>Median Width On Bridge</b> ft.				
		+ MISC. BRIDGE DATA +			
		<b>Structure Flared</b>	0 - No flare		
		<b>Parallel Structure</b>	N - No parallel structure		
		<b>Field Conn. ID</b>			
		<b>Abutment Foundation (Material/Type)</b>	1 - CONC 4 - PILE BENT		
		<b>Pier Foundation (Material/Type)</b>	1 - CONC 4 - PILE BENT		
		<b>Historic Status</b>	5 - Not eligible		
		+ PAINT +			
		<b>Year Painted</b>			
		<b>Unsound Paint %</b>			
		<b>Painted Area</b>	sq. ft.		
		<b>Primer Type</b>			
		<b>Finish Type</b>			
		+ BRIDGE SIGNS +			
		<b>Posted Load</b>	0 - Not Required		
		<b>Traffic</b>	0 - Not Required		
		<b>Horizontal</b>	0 - Not Required		
		<b>Vertical</b>	N - Not Applicable		

# MINNESOTA BRIDGE INSPECTION REPORT

10/20/2016

Inspector: CO Bridge

## BRIDGE 62590 CSAH 96 OVER SUCKER CREEK UNSTABLE MA

County: Ramsey	Location: 0.5 MI E OF JCT CSAH 54	Length: 434.7 ft.
City: Vadnais Heights	Route: 04 - CSAH 96 Ref. Pt.: 004+00.777	Deck Width: 68.1 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 29084 sq. ft. / %
Section: 19 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 2 - Concrete Continuous 1 - Slab	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:

NBI Deck: 6 Super: 6 Sub: 7 Chan: N Culv: N  
 Open, Posted, Closed: A - Open  
 MN Scour Code: A - NON WATERWAY

Appraisal Ratings - Approach: 8 Waterway: N  
 Required Bridge Signs - Load Posting: 0 - Not Required Traffic: 0 - Not Required  
 Horizontal: 0 - Not Required Vertical: N - Not Applicable

Unofficial Structurally Deficient N  
 Unofficial Functionally Obsolete N  
 Unofficial Sufficiency Rating 98.0

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
38	Reinforced Concrete Slab	Routine	09/08/2016	29603 SF	0	26695	2908	0
		Migrated Values		29603 SF	0	26695	2908	0
Notes: Concrete Slab with Bituminous Overlay Notes: [2016] Migrator assumed CS1. [2016] Structure is an at-grade bridge with concrete wearing surface.								
510	- Wearing Surfaces	Routine	09/08/2016	29084 SF	0	26176	2908	0
		Migrated Values		29084 SF	0	26176	2908	0
Notes: Concrete Slab with Bituminous Overlay Notes: [2016] Cracks are sealed & bridge was diamond ground in 2014. - CONCRETE WEARING SURFACE [2014] Crack sealed bridge deck in 2014 [2012] Numerous minor- moderate longitudinal & transverse cracks occurring. Moderate spalls are present. Distress area is between 2% and 10% of total deck area. [2003-2004] Numerous but tight longitudinal and transverse cracks.								
215	Reinforced Concrete Abutment	Routine	09/08/2016	135 LF	135	0	0	0
		Migrated Values		135 LF	135	0	0	0
Notes: [2002-2016] Unable to see under land bridge. No sign of movement or deterioration. Structure is an at-grade bridge. Bridge consists of 132.5m supported slab spans.								
300	Strip Seal Expansion Joint	Routine	09/08/2016	135 LF	0	67	0	68
		Migrated Values		135 LF	0	67	0	68
Notes: [2016] Strip seal has been flushed & cleaned, 50% in condition state #2 & #3. 50% has severe deterioration. [2014] 1" opening should be cleaned out [2010-2012] 50% in condition state #2 & #3. 50% has severe deterioration. Strip seal should be replaced. [2006-2008] 100% in condition state #2. Strip seal should be replaced. [2003-2008] There is a 6' puncture at the SE corner. 50% in condition 2. [2003-2008] Signs of deterioration. Needs to be cleaned and flushed at both ends for further inspection. [2010] The west expansion joint has a gap of 0.12' at 56 degrees. [2010] The east expansion joint has a gap of 0.16' @56 degrees.								

**BRIDGE 62590 CSAH 96 OVER SUCKER CREEK UNSTABLE MA**

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
321	Reinforced Concrete Approach Slab	Routine	09/08/2016	4020 SF	0	2010	2010	0
		Migrated Values		4020 SF	0	2010	2010	0
<p>Notes: [2016] 67' x 30' = 2010 SF x 2 = 4020 SF of Approach Slab.                      [2016] Migrator assumed an approach slab length of 20FT and used the inventory quantity of 67FT for the width.                      [2016] East Approach has 0.5' x 1.5', 1' x 1' &amp; 0.5' x 0.5' moderate spalls                      [2016] West Approach has 1.0' x 0.5' &amp; 0.5' x 0.5' moderate spalls.                      [2014] Diamond ground surface for noise &amp; grade difference, sealed cracks in deck &amp; approach panels in 2014                      [2014-2016] 0.5' x 7.0' spall in NW corner                      [2003-2016] There is settlement of concrete pavement at east &amp; west approach slabs resulting in impact on approach panels.                      [2010-2012] The west approach slab has a 30' of moderate longitudinal cracking north side, 20' of minor cracking at centerline of the west approach and a 13' diagonal crack at the SW corner. [2012] The west concrete approach slab also has moderate settlement at the west end.                      [2008-2012] The east approach has a 12' diagonal crack @ SE corner. [2008] There is an 8' area of delamination at the NW corner of the east approach.                      [2006-2012] There is a 3' X 0.5' area of major delamination at the SE corner with some settlement.                      [2002-2012] Both slabs contain minor to moderate cracking. [2003-                      [2003-2012] There is deterioration of Styrofoam expansion joints (E8S joint) at both ends. Hot pour has cohesion failure.</p>								
800	Critical Deficiencies or Safety Hazards	Routine	09/08/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION.</p>								
810	Concrete Decks - Cracking & Sealing	Routine	09/08/2016	7552 LF	0	7552	0	0
		Migrated Values		7552 LF	0	7552	0	0
<p>Notes: [2014-2016] Sealed cracks in 2014                      [2003-2012] Numerous unsealed moderate longitudinal, transverse &amp; diagonal deck cracking.</p>								
892	Slopes & Slope Protection	Routine	09/08/2016	1 EA	0	0	1	0
		Migrated Values		1 EA	0	0	1	0
<p>Notes: Use this element to rate the condition of slopes and slope protection.                      [2016] There is moderate to major settlement on both north &amp; south sides of bridge behind curb.</p>								
894	Deck & Approach Drainage	Routine	09/08/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
<p>Notes: [2014-2016] Grade has major settlement behind all 4 LP-4 catch basins                      [2014] Should seal in front of NE catch basin (between curb &amp; top) &amp; angle plate should be reattached on NW LP-4                      [2006-2012] Moderate settlement of CB @ SE corner bridge &amp; approach slab.</p>								
895	Sidewalk, Curb, & Median	Routine	09/08/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
<p>Notes: [2016] 7.0' of damaged curb on SW corner of bridge.                      [2014-2016] Moderate settlement behind north curb, Major settlement behind south curb                      [2014] Curb has been replaced on all 4 corners of bridge                      [2008-2012] There are 2 areas of deterioration of the curb @ SW corner. [2008-2012] There is deterioration of curb located at the 4- LP-4's.                      [2012] Curb OK at the SE corner- has been repaired.                      [2012] There is moderate- major settlement behind the curb on both sides. Need fill behind curb at the NE CB. The settlement is 2' low X 2.5' W X 18' length.</p>								
900	Protected Species	Routine	09/08/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
<p>Notes: Use this element to track the presence of protected species living on this structure.                      [2016] No protective species found.</p>								
<p>General Notes: [2016] The bridge safety inspection was completed by Dan Bodelson &amp; Brian Essler on 9/08/2016.                      [2014] The bridge safety inspection was completed by D. Bodelson &amp; B. Essler on 9/18/2014.                      [2012] The bridge safety inspection was completed by B. Wieman &amp; D. Bodelson on 9/24/2012.                      Land Bridge was built in 1999. There is a settlement problem of detached bike path adjacent to the south side of bridge.                      Bike path was repaired in 2002.                      There are 2 culverts running perpendicular underneath the land bridge. [2010] Inspection was completed by B. Wieman 10/19/2010.                      [2008] Inspection was completed by B. Wieman 8/26/2008.                      Inspection was completed by Bret Wieman 10/19/2006.                      [2008] There is settlement of approach roadway @ both ends. [2008] There is 2.5' of settlement behind the curb @ NE LP-4.                      [2003-2008] There is deterioration of Styrofoam expansion joints (E8S joint) at both ends. Hot pour has cohesion failure.</p>								

**BRIDGE 62590 CSAH 96 OVER SUCKER CREEK UNSTABLE MA**

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
	[2006] There is major settlement behind the curb on the north side. Boulevard requires fill. Land Bridge was built in 1999. There is a settlement problem of detached bike path adjacent to the south side of bridge. Bike path was repaired in 2002. There are 2 culverts running perpendicular underneath the land bridge.							
	58. Deck NBI:	Concrete has moderate cracking & wear.						
	36A. Brdg Railings NBI:	No Guardrail						
	36B. Transitions NBI:	No Guardrail						
	36C. Appr Guardrail NBI:	No Guardrail						
	36D. Appr Guardrail Terminal NBI:	No Guardrail						
	59. Superstructure NBI:	Concrete has moderate cracking with minor spalling.						
	60. Substructure NBI:	Concrete has minor cracking with isolated spalls.						
	61. Channel NBI:	Structure is an at-grade bridge.						
	62. Culvert NBI:	Structure is an at-grade bridge.						
	71. Waterway Adeq NBI:	Structure is an at-grade bridge.						
	72. Appr Roadway Alignment NBI:	No speed reduction required.						
	Inventory Notes:							

Dan Bodelson  
Inspector's Signature

Nicklaus Fischer  
Reviewer's Signature

# Pictures



Photo 1 -



Photo 2 -



# Pictures



Photo 3 - curb north side-2.JPG



Photo 4 - curb south side.JPG



## Pictures



Photo 5 - curb south side-2.JPG



Photo 6 - east E-8 joint.JPG

# Pictures



Photo 7 - looking east.JPG



Photo 8 - looking east-2.JPG



# Pictures



Photo 9 - looking west.JPG



Photo 10 - looking west-2.JPG

## Pictures



Photo 11 - west E-8 joint.JPG