

**2015 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 62623
CSAH 16 over WEST VADNAIS SWAMP**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: Vadnais Heights

Date(s) of Inspection: 10/09/2015

Equipment Used:

Owner: County Highway Agency

Inspected By: Essler, Brian

Report Written By: Brian Essler

Report Reviewed By: Nicklaus Fischer

Final Report Date: 01/05/2016

MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	9
THUMBNAIL PICTURES	20
CULVERT	21
CHANNEL	22
SCOUR POA	24
CHANNEL X-SECTION	25
MAINTENANCE	26
STRUCTURAL ASSESSMENT REPORT - ROUTINE	27

MnDOT Structure Inventory Report

Bridge ID: 62623

CSAH 16

over WEST VADNAIS SWAMP

Date: 01/05/2016

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City Vадnais Heights			
Township			
Desc. Loc. 0.1 MI E OF RICE ST			
Sect., Twp., Range	33	- 030N	- 22W
Latitude Deg	45	Min 2	Sec 48.21
Longitude Deg	93	Min 6	Sec 16.94
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		2008	
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 3 - COUNTY			
Date Opened to Traffic			
On-Off System 1 - ON			
Legislative District 54B			

STRUCTURE	
Service On	1 - Highway
Service Under	0 - Other
Main Span Type	
5 - Prestress or Precast 01 - Beam Span	
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	0
Culvert Type	
Barrel Length	ft.
Canterver ID	

NUMBER OF SPANS			
MAIN:	5	APPR:	0
TOTAL:	5		
Main Span Length	77.5	ft.	
Structure Length	374.8	ft.	
Deck Width (Out-to-Out)	37.3	ft.	
Deck Material	1 - Concrete Cast-in-Place		
Wear Surf Type	4 - Low Slump Concrete		
Wear Surf Install Year	2008		
Wear Course/Fill Depth	0.17	ft.	
Deck Membrane	0 - None		
Deck Rebars	1 - Epoxy Coated Reinforcing		
Deck Rebars Install Year	2008		
Structure Area (Out-to-Out)	19998	sq. ft.	
Roadway Area (Curb-to-Curb)	18113	sq. ft.	
Sidewalk Width	Lt 0	ft.	Rt 0
Curb Height	Lt 0.00	ft.	Rt 0.00
Rail Type	Lt 21	Rt 21	

ROADWAY			
Bridge Match ID (TIS) 0			
Roadway O/U Key Route On Structure			
Route Sys	04 - CSAH	Number	16
Roadway Name or Description			
CSAH 16			
Level of Service	1 - MAINLINE		
Roadway Type	2 - 2-way traffic		
Control Section (TH Only)			
Reference Point	000+00.051		
Detour Length	0.0	mi	
Lanes	On 2	Under 0	
	ADT 3900	Year 2012	
HCACT	0	ADTT 0 %	
Functional Class 16 - Urban - Minor Arterial			

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	34.0	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.	34.0	ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	32.0	ft.	
Bridge Roadway Width	34.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	1 - Flared
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	1 - CONC
(Material/Type)	3 - FTG PILE
Pier Foundation	1 - CONC
(Material/Type)	3 - FTG PILE
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	0 - Not Required

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	97.0
Routine Inspection Date	10/09/2015
Routine Inspection Frequency	12
Inspector Name	County, Ramsey
Status	A - Open

NBI CONDITION RATINGS	
Deck	7 - Good Condition
Unsound Deck %	
Superstructure	8 - Very Good Condition
Substructure	8 - Very Good Condition
Channel	N - Not Applicable
Culvert	N - Not Applicable

NBI APPRAISAL RATINGS	
Structure Evaluation	8
Deck Geometry	5
Underclearances	N
Water Adequacy	8 - Bridge Above Approach
Approach Alignment	5 - Somewhat better than m

SAFETY FEATURES	
Bridge Railing	1 - MEETS STANDARDS
GR Transition	0 - SUBSTANDARD
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	1 - MEETS STANDARDS

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical			
Underwater			
Pinned Asbly.			
Spec. Feat.			

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening		sq. ft.	
Navigation Control	N - Not applicable, no waterw		
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code	A - NON WATER' Year		

CAPACITY RATINGS			
Design Load	A - HL 93		
Operating Rating	1 - LF (LF)	HS 38.4	
Inventory Rating	1 - LF (LF)	HS 20.6	
Posting VEH:	SEMI:	DBL:	
Rating Date	04/03/2015		

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 62623

CSAH 16 over WEST VADNAIS SWAMP

Date: 01/05/2016

MnDOT BRIDGE INSPECTION REPORT

01/05/2016

Inspector: County, Ramsey

BRIDGE 62623 CSAH 16 OVER WEST VADNAIS SWAMP

ROUTINE INSP. DATE: 10/09/2015

County: Ramsey	Location: 0.1 MI E OF RICE ST	Length: 374.8 ft.
City: Vadnais Heights	Route: 04 - CSAH 16 Ref. Pt.: 000+00.051	Deck Width: 37.3 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 18113 sq. ft. / %
Section: 33 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 5 - Prestressed Concrete 02 -	Local Agency Bridge Nbr.:	Culvert: N/A
List: Stringer/Multi-beam or Girder		Postings:
NBI Deck: 7 Super: 8 Sub: 8 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	

Appraisal Ratings - Approach: 5 Waterway: 8		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: 0 - Not Required	Unofficial Sufficiency Rating 97.0

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
109	Prestressed Concrete Girder or Beam	2	Routine	10/09/2015	2144 LF	1608	536	0	0	N/A
			Routine	10/13/2014	2144 LF	1608	536	0	0	N/A

Requires Monitoring Monitored

Notes: [2011-2015] 75% ARE IN C.S. 1 & 25% ARE IN C.S. 2. THERE IS SOME RUSTING AT ENDS OF PRESTRESSED BEAM AT PIER #3.
 [2009-2015] THERE IS SOME MINOR - MODERATE SPALLS PRESENT LOCATED AT UNDERNEATH SIDE OF UPPER I-BEAMS (TOP FLANGE).

215	Reinforced Concrete Abutment	2	Routine	10/09/2015	103 LF	103	0	0	0	N/A
			Routine	10/13/2014	103 LF	103	0	0	0	N/A

Requires Monitoring Monitored

Notes: [2010-2015] SOME MINOR VERTICAL CRACKING WITH MINOR SPALLS PRESENT NORTH ABUTMENT. ALSO ON THE BACKWALL OF ABUT.
 [2014-2015] SOME MINOR CRACKING PRESENT ON THE SOUTH ABUTMENT.

234	Reinforced Concrete Pier Cap	2	Routine	10/09/2015	215 LF	185	30	0	0	N/A
			Routine	10/13/2014	215 LF	215	0	0	0	N/A

Requires Monitoring Monitored

Notes: [2015] There is a 3' vertical on the east fascia & 10' horizontal cracks on each side of pier cap 3 east end with efflorescence.
 [2015] There is graffiti on pier 2.
 [2014] There is a 10' horizontal cracks on each side of pier cap 3 east end.
 [2013-2014] THERE IS A 3' VERTICAL CRACK ON EAST FASCIA OF PIER CAP 3.
 [2011-2014] CRACKING AT PIER #3 EAST FASCIA. THERE IS CRACKING THE ENTIRE LENGTH OF PIER CAP #3. ALSO SOME SPALLS PRESENT.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
300	Strip Seal Deck Joint	2	Routine	10/09/2015	96 LF	96	0	0	N/A	N/A
			Routine	10/13/2014	96 LF	96	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2013-2015] SRTIP SEAL FILLED WITH DEBRIS , NEED TO BE CLEANED AND FLUSHED.
 [2009-2013] THERE IS NO DETERIORATION OF STRIP SEAL WATERPROOF GLAND. EXPANSION JOINT DEVICE TYPE 5.

310	Elastomeric (Expansion) Bearing	2	Routine	10/09/2015	10 EA	10	0	0	N/A	N/A
			Routine	10/13/2014	10 EA	10	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2009-2015] BEARINGS ARE IN GOOD CONDITION AND FUNCTIONING PROPERLY.
 [2012] NO BULGING OF THE ELASTOMERIC BEARINGS.

313	Fixed Bearing	2	Routine	10/09/2015	46 EA	46	0	0	N/A	N/A
			Routine	10/13/2014	46 EA	46	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2009-2015] THE FIXED BEARINGS ARE FREE OF DEBRIS AND ARE WITHOUT CORROSION. THE BEARINGS ARE FUNCTIONING AS INTENDED.

321	Concrete Approach Slab-Concrete Wearing Surface	2	Routine	10/09/2015	2 EA	0	2	0	0	N/A
			Routine	10/13/2014	2 EA	0	2	0	0	N/A

 Requires Monitoring Monitored

Notes: [2012-2015] THE SOUTH APPROACH SLAB HAS 5- 15" LONGITUDINAL CRACKS AT THE EXPANSION JOINT.
 [2009-2015] THERE IS A MAJOR 6" SPALL AT SW CORNER OF SOUTH APPROACH SLAB.
 [2012-2015] THE NW APPROACH SLAB HAS 23- 15" LONGITUDINAL CRACKS AT THE EXPANSION JOINT. THERE IS MINOR DELAMINATION NEAR THE CB AT THE NW CORNER. [2010-2015] MODERATE SPALLING AT WEST END OF NORTH APPROACH SLAB.

331	Reinforced Concrete Bridge Railing	2	Routine	10/09/2015	816 LF	408	408	0	0	N/A
			Routine	10/13/2014	816 LF	408	408	0	0	N/A

 Requires Monitoring Monitored

Notes: [2010-2015] 50 % IN CONDITION STATE 2. THERE IS MINOR TO MODERATE VERTICAL CRACKING W/EFFLORESCENCE BETWEEN JOINTS. THERE ARE NUMEROUS MINOR SPALLS PRESENT BOTH SIDES. BRIDGE RAIL CONSISTS OF TYPE P-4 RAILING WITH SPECIAL SURFACE FINISH #33522.

358	Concrete Deck Cracking Smart Flag	2	Routine	10/09/2015	1 EA	1	0	0	0	N/A
			Routine	10/13/2014	1 EA	1	0	0	0	N/A

 Requires Monitoring Monitored

Notes: [2013-2015] THERE ARE 330 LF OF MINOR CRACKS IN SB LANE AND 380 LF OF MINOR CRACKS IN NB LANE.
 [2009-2015] THERE ARE NUMEROUS BUT MINOR OR INSIGNIFICANT CRACKING AT EAST SIDE PIER #1 AND THE MEDIAN CRACKS ARE EXTENDING INTO THE DECK.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
359	Underside of Concrete Deck Smart Flag	2	Routine	10/09/2015	1 EA	0	1	0	0	0
			Routine	10/13/2014	1 EA	0	1	0	0	0

 Requires Monitoring Monitored

Notes: [2011-2015] THERE IS A 12' MINOR- MODERATE CRACK WITH EFFLORESCENCE AT CENTERLINE PIER #2.
 [2011-2015] THERE ARE 100 LF OF MINOR DIAGONAL & TRANSVERSE CRACKING W/EFFLORESCENCE.
 [2009-2010] THERE ARE 20 LF OF DIAGONAL CRACKING W/EFFLORESCENCE AT EAST SIDE PIER #1. THERE ARE 30 LF OF TRANSVERSE CRACKING NORTH SIDE OF JOINT AT PIER #1.

377	Low Slump O/L (Concrete Deck with Epoxy Rebar)	2	Routine	10/09/2015	19998 SF	0	19998	0	0	0
			Routine	10/13/2014	19998 SF	0	19998	0	0	0

 Requires Monitoring Monitored

Notes: [2015] THERE IS SOME OCCASIONAL MINOR TO MODERATE SPALLING THROUGHOUT.
 [2010-2015] THERE IS A 4" SPALL SOUTH SIDE OF PIER #1 WESTBOUND.
 [2009-2015] THERE ARE 50 LF OF MINOR DIAGONAL, LONGITUDINAL & TRANSVERSE CRACKING AT EAST SIDE OF PIER #1.
 [2009-2015] MODERATE SPALL AT EASTBOUND SPAN #1.
 [2009-2014] THERE IS SOME OCCASIONAL MINOR SPALLING THROUGHOUT. [2009-2015] THERE ARE MINOR TRANSVERSE CRACKS EXTENDING INTO THE DECK FROM MEDIAN CRACKS THROUGHOUT. THE 2" 3U17A WEARING COURSE WAS INSTALLED IN 2008.

380	Secondary Structural Elements	2	Routine	10/09/2015	1 EA	1	0	0	0	N/A
			Routine	10/13/2014	1 EA	1	0	0	0	N/A

 Requires Monitoring Monitored

Notes: [2010-2015] STEEL DIAPHRAGMS (2860 TOTAL) HAVE NO DETERIORATION AND IN PROPER ALIGNMENT.

382	Cast-In-Place (CIP) Piling	2	Routine	10/09/2015	26 EA	26	0	0	0	N/A
			Routine	10/13/2014	26 EA	26	0	0	0	N/A

 Requires Monitoring Monitored

Notes: [2011-2015] THERE IS SOME CHIPPING OF PAINT ON PILING #7 LOCATED AT THE EAST SIDE.
 [2009-2011] NO DETERIORATION OF PAINTED STEEL PILING 2009-2011. PILINGS WERE PAINTED FEDERAL COLOR #10075 OR 595B.

387	Reinforced Concrete Wingwall	2	Routine	10/09/2015	4 EA	3	1	0	0	N/A
			Routine	10/13/2014	4 EA	3	1	0	0	N/A

 Requires Monitoring Monitored

Notes: [2012-2015] SOME MODERATE SPALLS PRESENT NEAR CRASH ATTENUATOR ON NW WING WALL.
 [2009-2015] NO SIGNIFICANT DETERIORATION PRESENT ON SW, SE & NE WING WALLS.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
409	Chain Link Fence	2	Routine	10/09/2015	816 LF	816	0	0	0	0
			Routine	10/13/2014	816 LF	816	0	0	0	0

 Requires Monitoring Monitored

Notes: [2009-2015] CONDITION STATE #1. CHAIN LINK FENCE HAS LITTLE DETERIORATION. BLACK VINYL COATED TYPE W-1. SOME TIES ARE MISSING ON THE EAST SIDE.

964	Critical Finding Smart Flag	2	Routine	10/09/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	10/13/2014	1 EA	1	0	N/A	N/A	N/A

 Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

965	Concrete Shear Cracking Smart Flag	2	Routine	10/09/2015	1 EA	1	0	0	0	N/A
			Routine	10/13/2014	1 EA	1	0	0	0	N/A

 Requires Monitoring Monitored

Notes:

981	Signing	2	Routine	10/09/2015	1 EA	1	0	0	0	0
			Routine	10/13/2014	1 EA	1	0	0	0	0

 Requires Monitoring Monitored

Notes: [2009-2015] ALL REQUIRED SIGNING IS PRESENT AND IS IN GOOD CONDITION.

982	Approach Guardrail	2	Routine	10/09/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/13/2014	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2015] SPACER BLOCKS ARE TWISTED AT THE SE CORNER. GUARDRAIL IS IN GOOD CONDITION.
 [2013-2014] GUARDRAIL HAS BEEN REPAIRED AT SE CORNER. GUARDRAIL IS IN GOOD CONDITION.
 [2012] THERE IS SEVERE COLLISION DAMAGE AT THE SE CORNER- REPAIRS ARE RECOMMENDED.
 [2011] NEED SOME MINOR REPAIR TO GUARDRAIL SYSTEM AT SE CORNER OF BRIDGE. THE GUARDRAIL IS LOOSE AT THE SE CORNER.
 [2009-2011] GUARDRAIL IS IN GOOD CONDITION. CRASH ATTENUATOR IS IN PLACE AT NW CORNER OF BRIDGE.

984	Deck & Approach Drainage	2	Routine	10/09/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/13/2014	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2009-2015] DRAINAGE SYSTEM IS FUNCTIONING PROPERLY.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
985	Slopes & Slope Protection	2	Routine	10/09/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/13/2014	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2013-2015] THERE IS SOME SETTLEMENT AT THE SOUTH ABUTMENT AND AT THE NE CORNER.
[2009-2015] THERE IS SOME SETTLEMENT AT THE NORTH ABUTMENT AND AT THE SE CORNER.

986	Curb & Sidewalk	2	Routine	10/09/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/13/2014	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: [2014-2015] There is numerous moderate transverse cracks in the median.
[2009-2015] THERE IS A MAJOR SPALL ON MEDIAN CURB AT NW CORNER. THE REST OF THE CURB IS IN GOOD CONDITION.

General Notes: [2015] 2015 bridge safety inspection was completed by Brian Essler and Dan Bodelson on 10-9-2015.
[2014] 2014 bridge safety inspection was completed by Brian Essler and Dan Bodelson on 10-13-2014.
Inspection dated 10-02-2013 by Brian Essler and Dan Bodelson and was entered by MnDOT Bridge Office.
[2013] 2013 BRIDGE SAFETY INSPECTION WAS COMPLETED BY Brian Essler and Dan Bodelson on 10/02/2013.

58. Deck NBI: Minor cracking and leaching

36A. Brdg Railings NBI: Type P-4

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail design speed 30 MPH Tangent terminal and Quadguard impact attenuator
Terminal NBI:

59. Superstructure NBI: Minor Spalls and rusting of beams

60. Substructure NBI: Minor cracking and spalls

61. Channel NBI: No waterway

62. Culvert NBI: Bridge

71. Waterway Adeq NBI: No waterway

72. Appr Roadway Minor speed reduction due to grade at bridge.
Alignment NBI:

Inventory Notes:

Brian Essler
Inspector's Signature

Nicklaus Fischer
Reviewer's Signature

Pictures



Photo 1 - NW Atten



Photo 2 - NW Cor

Pictures



Photo 3 - Pier 1



Photo 4 - West Appr

Pictures



Photo 5 - West Side



Photo 6 - attenuater

Pictures



Photo 7 - east side



Photo 8 - EB1

Pictures



Photo 9 - EB2



Photo 10 - SW Corner South Approach Slab

Pictures



Photo 11 - Overlay South side Pier #1 WB



Photo 12 - WB1

Pictures



Photo 13 - WB2



Photo 14 - WB3

Pictures



Photo 15 - West Bridge Rail



Photo 16 - West Bridge Rail

Pictures



Photo 17 - west side



Photo 18 - west side1

Pictures



Photo 19 - west side3



Photo 20 - west side4

Pictures



Photo 21 - west side6



1. 62623 NW Atten.JPG



2. 62623 NW Cor.JPG



3. 62623 Pier 1.JPG



4. 62623 West Appr.JPG



5. 62623 West Side.JPG



6. attenuater.JPG



7. east side.JPG



8. EB1.JPG



9. EB2.JPG



10. SW Corner South Approach Slab.JPG



11. Overlay South side Pier #1 WB.JPG



12. WB1.JPG



13. WB2.JPG



14. WB3.JPG



15. West Bridge Rail.JPG



16. West Bridge Rail.JPG



17. west side.JPG



18. west side1.JPG



19. west side3.JPG



20. west side4.JPG



21. west side6.JPG

Culvert

Bridge No.: 62623

Culvert

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Culvert Overall:	NBI Item 62	<u>N</u>	Bridge

MnDOT Scour Code: A - NON WATERWAY

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.		Is there a significant build-up of debris?
2.		Is there erosion of the embankment around the headwalls?
3.		Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.		Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.		Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.		Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.		Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.		Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.		Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.		If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 62623

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	N	No waterway

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	<u>A - NON WATERWAY</u>		

Underwater Inspection

Underwater Inspection By Divers: _____

No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____	High Water Elev.: _____	Current Water Elev.: _____
Pile Tip Elev.: _____	Low Water Elev.: _____	Current Streambed Elev.: _____
	Scour Hole Elev.: _____	Current Scour Hole Elev.: _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 62623

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62623	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 10/09/2015	STRUCTURE TYPE: Prestressed Concrete Stringer/Multi-beam or Girder
FACILITY CARRIED: CSAH 16	FEATURES INTERSECTED: WEST VADNAIS SWAMP
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE	
<input type="checkbox"/> FRACTURE CRITICAL	
<input type="checkbox"/> PINNED ASSEMBLY:	
<input type="checkbox"/> SPECIAL:	
<input type="checkbox"/> DAMAGE:	
<input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path	Connection Type: <input type="checkbox"/> Riveted
<input type="checkbox"/> Structural	<input type="checkbox"/> Bolted
<input type="checkbox"/> Internal	<input type="checkbox"/> Welded
	<input type="checkbox"/> Other:

- Was a critical finding identified during this inspection or upon structural review? Yes No
 - If selected "Yes" above, state briefly the finding(s):
- If a critical finding was identified, what is the current status? Pending Resolved N/A
 - Briefly state actions taken:
- Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance Monitoring Plan
 Other Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer