

**2014 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 62J07
CSAH 96 over PED PATH**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: Shoreview

Date(s) of Inspection: 10/16/2014

Equipment Used:

Owner: City or Municipal Highway Agency

Inspected By: Ascheman, Cory

Report Written By: Cory Ascheman

Report Reviewed By: Jeffrey A Johnson

Final Report Date: 02/11/2015

**MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128**



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	7
THUMBNAIL PICTURES	12
CULVERT	13
CHANNEL	14
SCOUR POA	16
CHANNEL X-SECTION	17
MAINTENANCE	18
STRUCTURAL ASSESSMENT REPORT - ROUTINE	19

MnDOT Structure Inventory Report

Bridge ID: 62J07

CSAH 96

over PED PATH

Date: 02/11/2015

GENERAL			
Agency Br. No.			
District	Metro		
Maint. Area	Crew		
County	062 - Ramsey		
City	Shoreview		
Township			
Desc. Loc.	0.2 MI E OF VICTORIA ST		
Sect., Twp., Range	14	-	030N - 23W
Latitude	Deg 45	Min 4	Sec 42
Longitude	Deg 93	Min 7	Sec 54
Custodian	04 - City or Municipal Highway Agency		
Owner	04 - City or Municipal Highway Agency		
BMU Agreement			
Year Built	1997		
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location	3 - COUNTY		
Date Opened to Traffic			
On-Off System	0 - OFF		
Legislative District	53A		

STRUCTURE	
Service On	1 - Highway
Service Under	3 - Pedestrian - bicycle
Main Span Type	5 - Prestress or Precast 13 - Box Culvert
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	15 R
Culvert Type	PCST 1210
Barrel Length	137 ft.
Cantilever ID	

NUMBER OF SPANS			
MAIN:	1	APPR:	0
TOTAL:	1		
Main Span Length	12.4	ft.	
Structure Length	13.7	ft.	
Deck Width (Out-to-Out)	0.0	ft.	
Deck Material	N - Not Applicable		
Wear Surf Type	6 - Bituminous		
Wear Surf Install Year			
Wear Course/Fill Depth	5.20	ft.	
Deck Membrane	0 - None		
Deck Rebars	N - Not Applicable (no deck)		
Deck Rebars Install Year			
Structure Area (Out-to-Out)	0	sq. ft.	
Roadway Area (Curb-to-Curb)		sq. ft.	
Sidewalk Width	Lt 0.00	ft.	Rt 0.00
Curb Height	Lt 0.00	ft.	Rt 0.00
Rail Type	Lt NN		Rt NN

ROADWAY			
Bridge Match ID (TIS)	0		
Roadway O/U Key	Route On Structure		
Route Sys	04 - CSAH	Number	96
Roadway Name or Description	CSAH 96		
Level of Service	1 - MAINLINE		
Roadway Type	2 - 2-way traffic		
Control Section (TH Only)			
Reference Point	002+00.778		
Detour Length	1.0	mi	
Lanes	On 4	Under 0	
	ADT 21115	Year 2008	
HCACT	0	ADTT 0	%
Functional Class	16 - Urban - Minor Arterial		

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	35.40	ft.	35.40
Vertical Clearance		ft.	
Max. Vert. Clear.		ft.	
Horizontal Clear.		ft.	
Lateral Clearance		ft.	
Appr. Surface Width	90.0	ft.	
Bridge Roadway Width	0.0	ft.	
Median Width On Bridge	20.00	ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	N - N/A
(Material/Type)	N - N/A
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	193
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	81.6
Routine Inspection Date	10/16/2014
Routine Inspection Frequency	24
Inspector Name	SEH
Status	A - Open

NBI CONDITION RATINGS	
Deck	N - Not Applicable
Unsound Deck %	
Superstructure	N - Not Applicable
Substructure	N - Not Applicable
Channel	N - Not Applicable
Culvert	7 - Shrinkage cracks, light scali

NBI APPRAISAL RATINGS	
Structure Evaluation	7
Deck Geometry	N
Underclearances	N
Water Adequacy	N - Not Applicable
Approach Alignment	8 - Equal to present desirabl

SAFETY FEATURES	
Bridge Railing	N - NOT REQUIRED
GR Transition	0 - SUBSTANDARD
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	N - NOT REQUIRED

IN DEPTH INSP.		
Y/N	Freq	Date
Frac. Critical		
Underwater		
Pinned Asbly.		
Spec. Feat.		

WATERWAY	
Drainage Area (sq. mi.)	
Waterway Opening	sq. ft.
Navigation Control	N - Not applicable, no waterw
Pier Protection	
Nav. Clr. (ft.)	Vert. ft. Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)	
MN Scour Code	A - NON WATER' Year

CAPACITY RATINGS		
Design Load	9 - HS 25 (OR GREATER)	
Operating Rating	5 - NRAP	36.0
Inventory Rating	5 - NRAP	24.0
Posting VEH:	SEMI:	DBL:
Rating Date	2/15/2001	

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 62J07

CSAH 96 over PED PATH

Date: 02/11/2015

MnDOT BRIDGE INSPECTION REPORT

02/11/2015

Inspector: SEH

BRIDGE 62J07 CSAH 96 OVER PED PATH

ROUTINE INSP. DATE: 10/16/2014

County: Ramsey	Location: 0.2 MI E OF VICTORIA ST	Length: 13.7 ft.
City: Shoreview	Route: 04 - CSAH 96 Ref. Pt.: 002+00.778	Deck Width: 0.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 14 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: PCST 1210
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: N Culv: 7	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 8 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 81.6

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
241	Reinforced Concrete Culvert	1	Routine	10/16/2014	128 LF	128	0	0	0	N/A
			Routine	10/05/2012	128 LF	128	0	0	0	N/A

Requires Monitoring Monitored

Notes: [2008] Interior culvert painted, joints caulked. Paint cracking at several joints. Asphalt path cracked at two joints.
 [2010] Asphalt cracked across at 6 joints.
 [2014] The paint is cracked at all the joints. The asphalt is cracked between 6 joints. The paint is flaking off 7' of the SW culvert wall due to sun exposure. The culvert sections are sound.

334	Metal Bridge Railing (Coated or Painted)	1	Routine	10/16/2014	95 LF	0	95	0	0	0
			Routine	10/05/2012	95 LF	95	0	0	0	0

Requires Monitoring Monitored

Notes: [2012] Minor paint rusting along south rail.
 [2014] Minor paint flaking and light rust spots on the N and S railings.

388	Culvert Headwall, Wingwall or Other End Treatment	1	Routine	10/16/2014	4 EA	0	4	0	0	N/A
			Routine	10/05/2012	4 EA	4	0	0	0	N/A

Requires Monitoring Monitored

Notes: [2008] Paint sealant peeling in several areas on S end. Both corners on S end have 1½ foot cracks diagonal from culvert corners. N end has 1½ foot crack in NE corner and 1½ foot crack in top curved section. At the top of S headwall, the caulked joints are failing leaving gaps down wall joint.
 [2014] Approx. 50% of the paint on the S face has faded away. The S face has multiple hairline cracks around the arch (a 7' crack at the west corner, a couple of 3' cracks along the west half, a couple of 1.5' cracks along the east half and a 5' crack at the east corner). The N face has a 3.5' (0.04") crack at the east corner and a 2' (0.02") crack west of CL. The caulked joints in the NE, SE and SW have areas where the caulk has separated.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
964	Critical Finding Smart Flag	2	Routine	10/16/2014	1 EA	1	0	N/A	N/A	N/A
			Routine	10/05/2012	1 EA	1	0	N/A	N/A	N/A

Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

984	Deck & Approach Drainage	2	Routine	10/16/2014	1 EA	1	0	0	N/A	N/A
			Routine	10/05/2012	1 EA	1	0	0	N/A	N/A

Requires Monitoring Monitored

Notes: [2008] 10 foot long metal grate drain before N entrance.
[2014] The drainage system is in good condition and functioning as intended.

987	Roadway over Culvert	2	Routine	10/16/2014	1 EA	1	0	0	N/A	N/A
			Routine	10/05/2012	1 EA	1	0	0	N/A	N/A

Requires Monitoring Monitored

Notes: [2014] The WB lanes have minor cracking but no settlement. The south sidewalk has a 9' (0.25") crack through 2 panels used by pedestrians. The north sidewalk above the NE corner of the culvert has a panel that's tipped 1.5" but it is not in the traveled portion of the walk.

988	Miscellaneous Items	2	Routine	10/16/2014	1 EA	1	0	0	N/A	N/A
			Routine	10/05/2012	1 EA	1	0	0	N/A	N/A

Requires Monitoring Monitored

Notes: [2008] Lighting and conduit installed inside culvert.
[2012] Broken light cover 3rd light in from the north end, west side.
[2014] The rigid conduit install along the east and west sides of the culvert are secure. The light cover is still broken.

General Notes: [2008] Insp by CS and JJ.
[2010] Insp by CS and JJ.
[2012] Insp by CS and JJ.
[2014] Insp by Cory Ascherman (SEH, Inc.)

58. Deck NBI:

36A. Brdg Railings NBI:

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail Terminal NBI:

59. Superstructure NBI:

60. Substructure NBI:

61. Channel NBI:

62. Culvert NBI: [2014] The culvert has minor weathering and cracking.

71. Waterway Adeq NBI:

72. Appr Roadway Alignment NBI: [2014] No speed reduction required.

Inventory Notes:

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
-------------	--------------	-----	-------------	------------	----------	-------------	-------------	-------------	-------------	-------------

Cory Ascherman
Inspector's Signature

Jeffrey A Johnson
Reviewer's Signature

Pictures



Photo 1 - Elevation View
Looking SW



Photo 2 - Elevation View
Looking North

Pictures



Photo 3 - Alignment View
Looking West



Photo 4 - Culvert
Looking South

Pictures



Photo 5 - Crack in east corner of north headwall
Looking South



Photo 6 - Crack on west portion of north headwall
Looking South

Pictures



Photo 7 - Hairline crack in west corner of south headwall
Looking North




Photo 8 - Crack in south sidewalk
Looking West


Pictures



Photo 9 - Tipped panel in north sidewalk
Looking East



1. IMG_1288.JPG




2. IMG_1297.JPG



3. IMG_1310.JPG



4. IMG_1289.JPG



5. IMG_1278.JPG



6. IMG_1282.JPG



7. IMG_1300.JPG



8. IMG_1302.JPG



9. IMG_1306.JPG

Culvert

Bridge No.: 62J07

Culvert

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Culvert Overall:	NBI Item 62	<u>7</u>	[2014] The culvert has minor weathering and cracking.

MnDOT Scour Code: A - NON WATERWAY

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there erosion of the embankment around the headwalls?
3.	_____	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	_____	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	_____	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	_____	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	_____	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	_____	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 62J07

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	N	

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	A - NON WATERWAY	_____	_____

Underwater Inspection

Underwater Inspection By Divers: _____

No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point:	_____	High Water Elev.:	_____	Current Water Elev.:	_____
Pile Tip Elev.:	_____	Low Water Elev.:	_____	Current Streambed Elev.:	_____
		Scour Hole Elev.:	_____	Current Scour Hole Elev.:	_____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 62J07

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62J07	BRIDGE OWNER: City or Municipal Highway Agency
DATE INSPECTED: 10/16/2014	STRUCTURE TYPE: Concrete Culvert (includes frame culverts)
FACILITY CARRIED: CSAH 96	FEATURES INTERSECTED: PED PATH
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

- Was a critical finding identified during this inspection or upon structural review? Yes No
 - If selected "Yes" above, state briefly the finding(s):
- If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - Briefly state actions taken:
- Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- | | |
|---|---|
| <input type="checkbox"/> Repair/Maintenance | <input type="checkbox"/> Monitoring Plan |
| <input type="checkbox"/> Other | <input type="checkbox"/> Increased Inspection Frequency |

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer