

**2015 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 90389
CSAH 12(CR F) over SUCKER CREEK**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: Vadnais Heights

Date(s) of Inspection: 10/05/2015

Equipment Used:

Owner: County Highway Agency

Inspected By: Bodelson, Dan

Report Written By: Dan Bodelson

Report Reviewed By: Nicklaus Fischer

Final Report Date: 01/05/2016

**MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128**



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	7
THUMBNAIL PICTURES	14
CULVERT	15
CHANNEL	16
SCOUR POA	18
CHANNEL X-SECTION	19
MAINTENANCE	20
STRUCTURAL ASSESSMENT REPORT - ROUTINE	21

MnDOT Structure Inventory Report

Bridge ID: 90389

CSAH 12(CR F)

over SUCKER CREEK

Date: 01/05/2016

GENERAL			
Agency Br. No.			
District	Metro		
Maint. Area	Crew		
County	062 - Ramsey		
City	Vadnais Heights		
Township			
Desc. Loc.	0.6 MI E OF JCT CSAH 54		
Sect., Twp., Range	30	- 030N	- 22W
Latitude	Deg 45	Min 3	Sec 53.25
Longitude	Deg 93	Min 5	Sec 41.29
Custodian	02 - County Highway Agency		
Owner	02 - County Highway Agency		
BMU Agreement			
Year Built	1930		
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location	0 - NO PLAN		
Date Opened to Traffic			
On-Off System	0 - OFF		
Legislative District	54B		

STRUCTURE	
Service On	1 - Highway
Service Under	5 - Waterway
Main Span Type	5 - Prestress or Precast 13 - Box Culvert
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	0
Culvert Type	W76D
Barrel Length	70 ft.
Cantilever ID	

NUMBER OF SPANS		
MAIN: 2	APPR: 0	TOTAL: 2
Main Span Length	7.0	ft.
Structure Length	16.8	ft.
Deck Width (Out-to-Out)	0.0	ft.
Deck Material	N - Not Applicable	
Wear Surf Type	6 - Bituminous	
Wear Surf Install Year		
Wear Course/Fill Depth	12.00	ft.
Deck Membrane	0 - None	
Deck Rebars	N - Not Applicable (no deck)	
Deck Rebars Install Year		
Structure Area (Out-to-Out)	0	sq. ft.
Roadway Area (Curb-to-Curb)		sq. ft.
Sidewalk Width	Lt 0.00	Rt 0.00
Curb Height	Lt 0.00	Rt 0.00
Rail Type	Lt NN	Rt NN

ROADWAY	
Bridge Match ID (TIS)	0
Roadway O/U Key	Route On Structure
Route Sys	04 - CSAH Number 12
Roadway Name or Description	CSAH 12
Level of Service	1 - MAINLINE
Roadway Type	2 - 2-way traffic
Control Section (TH Only)	
Reference Point	006+00.050
Detour Length	1.0 mi
Lanes	On 2 Under 0
	ADT 5378 Year 2008
HCACT	0 ADTT 0 %
Functional Class	16 - Urban - Minor Arterial

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	25.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.		ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	30.0	ft.	
Bridge Roadway Width	0.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	N - N/A
(Material/Type)	N - N/A
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	85.7
Routine Inspection Date	10/05/2015
Routine Inspection Frequency	24
Inspector Name	County, Ramsey
Status	A - Open

NBI CONDITION RATINGS	
Deck	N - Not Applicable
Unsound Deck %	
Superstructure	N - Not Applicable
Substructure	N - Not Applicable
Channel	7 - Needs minor repairs
Culvert	5 - Mod. to major deterioration

NBI APPRAISAL RATINGS	
Structure Evaluation	5
Deck Geometry	N
Underclearances	N
Water Adequacy	5 - Occasional Flooding - Si
Approach Alignment	8 - Equal to present desirabl

SAFETY FEATURES	
Bridge Railing	N - NOT REQUIRED
GR Transition	N - NOT REQUIRED
Appr. Guardrail	1 - MEETS STANDARDS
GR Termini	1 - MEETS STANDARDS

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical			
Underwater			
Pinned Asbly.			
Spec. Feat.			

WATERWAY	
Drainage Area (sq. mi.)	
Waterway Opening	84 sq. ft.
Navigation Control	0 - No nav. control on waterw
Pier Protection	
Nav. Clr. (ft.)	Vert. ft. Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)	
MN Scour Code	E - CULVERT Year

CAPACITY RATINGS	
Design Load	0 - Other/Unknown
Operating Rating	5 - NRAP 24.0
Inventory Rating	5 - NRAP 18.0
Posting VEH:	SEMI: DBL:
Rating Date	01/10/1985

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 90389

CSAH 12(CR F) over SUCKER CREEK

Date: 01/05/2016

MnDOT BRIDGE INSPECTION REPORT

01/05/2016

Inspector: County, Ramsey

BRIDGE 90389 CSAH 12(CR F) OVER SUCKER CREEK

ROUTINE INSP. DATE: 10/05/2015

County: Ramsey	Location: 0.6 MI E OF JCT CSAH 54	Length: 16.8 ft.
City: Vadnais Heights	Route: 04 - CSAH 12 Ref. Pt.: 006+00.050	Deck Width: 0.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 30 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: W76D
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: 7 Culv: 5	Open, Posted, Closed: A - Open	
	MN Scour Code: E - CULVERT	

Appraisal Ratings - Approach: 8 Waterway: 5		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 85.7

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
241	Reinforced Concrete Culvert	2	Routine	10/05/2015	141 LF	0	141	0	0	N/A
			Routine	10/03/2013	141 LF	0	141	0	0	N/A

Requires Monitoring Monitored

Notes: Dan Bodelson & Randy Bussiere walked thru culverts on 11/7/14 - SPWW drained Sucker Creek for repairs to the north. Inside south ends of both culverts have minor spalls & cracks. [2014]
 Can't walk through due to water level and not enough head room to walk through 2005-2013.
 Culvert contains some cracking and leaching with slight separation of joints 2001-2011.

361	Scour Smart Flag	2	Routine	10/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/03/2013	1 EA	0	1	0	N/A	N/A

Requires Monitoring Monitored

Notes: [2013-2015] North side has block retaining wall holding up roadway & walk.
 Minor scour taking place at the south side 2001-2015.
 Riprap is in place 2009-2015.
 The north side has metal sheeting in place along Sucker Creek edge 2007-2015. North side is OK.

388	Culvert Headwall, Wingwall or Other End Treatment	2	Routine	10/05/2015	2 EA	0	1	1	0	N/A
			Routine	10/03/2013	2 EA	0	1	1	0	N/A

Requires Monitoring Monitored

Notes: Major delamination @ center divider, SE wing and east 1/2 of south fascia 2007-2015.
 Approximately 5' of the SE wing has deteriorated and no longer in place since 1983.
 North side headwall fascia has minor cracking & spalling with moderate spall @ center of headwall 2009-2015.
 North side in condition 2 and south side in condition 3 2001-2015.

964	Critical Finding Smart Flag	2	Routine	10/05/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	10/03/2013	1 EA	1	0	N/A	N/A	N/A

Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
981	Signing	2	Routine	10/05/2015	1 EA	1	0	0	0	0
			Routine	10/03/2013	1 EA	1	0	0	0	0

 Requires Monitoring Monitored

Notes: Horizontal clearance signs are in place 2003-2015.

982	Approach Guardrail	2	Routine	10/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/03/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring MonitoredNotes: There are minor collision damage throughout. Damage is mostly on the south side 2003-2015.
Spacer blocks on the north side need to be turned and nailed 2003-2015.
There is a broken timber board backside of guardrail on the north side just west of the bridge 2003-2013.

985	Slopes & Slope Protection	2	Routine	10/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/03/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring MonitoredNotes: There is major erosion of embankment above the south culvert headwall. Recommend maintenance work 2009-2015.
There is some erosion below 12" CMP at SE corner 2015.

987	Roadway over Culvert	2	Routine	10/05/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/03/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Minor settlement with moderate cracks in bituminous 2001-2015.

General Notes: 2015 Bridge safety inspection completed by Dan Bodelson on 10/05/2015
 2013 Bridge safety inspection completed by Dan Bodelson on 10/02/2013
 2009 Bridge safety inspection was completed by B. Wieman 8/04/2009.
 Parks Department installed a 5 ton continental bridge (2000109) south of bridge # 90389
 2007 Bridge safety inspection was completed by B. Wieman 8/29/2007.
 2005 Bridge safety inspection was completed by Bret Wieman 9/14/2005.
 Graffiti on block wall north end 2003-2007.
 Barrels at full capacity 1983-2013. Unable to walk through due to water level of culverts 2005-2013.
 Asphalt spillways should be lengthened 2000-2005. Erosion at south side of embankment above culvert. Needs riprap.
 Sidewalk and modular block wall was installed with fence on top of wall.
 Riprap & metal sheeting used for erosion prevention on the north end both sides of creek. Bank is slumping on east side.
 2003-2005.
 Drainage from east side north end of barrel causing some erosion north of bridge but not affecting the bridge. 2005.

58. Deck NBI: Culvert - no Deck

36A. Brdg Railings NBI: No Railing

36B. Transitions NBI: No Bridge Rail to attach

36C. Appr Guardrail NBI: Meets currant safety standards

36D. Appr Guardrail Meets currant safety standards

Terminal NBI:

59. Superstructure NBI: Culvert

60. Substructure NBI: Culvert

61. Channel NBI: Channel has no notable aggregation, degradation, or lateral movement.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
62.	Culvert NBI:		Culvert has moderate deterioration.							
71.	Waterway Adeq NBI:		Culvert is full - flow is regulated by St. Paul Water.							
72.	Appr Roadway Alignment NBI:		no speed reduction required.							
	Inventory Notes:									

Dan Bodelson
Inspector's Signature

Nicklaus Fischer
Reviewer's Signature

Pictures



Photo 1 -



Photo 2 -

Pictures



Photo 3 -




Photo 4 -

Pictures



Photo 5 -



Photo 6 -

Pictures



Photo 7 -



Photo 8 -

Pictures



Photo 9 -



Photo 10 -

Pictures



Photo 11 -



Photo 12 -

Pictures



Photo 13 -



1. Looking East.JPG



2. Looking West.JPG




3. North End.JPG



4. South End.JPG



5. South End-2.JPG



6. South End-3.JPG



7. east culvert.JPG



8. east culvert-2.JPG



9. north end.JPG



10. spall on south end east culvert.JPG



11. spall on south end west culvert.JPG



12. spall on south end.JPG



13. spall on south end-2.JPG

Culvert

Bridge No.: 90389

Culvert

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Culvert Overall:	NBI Item 62	<u>5</u>	Culvert has moderate deterioration.

MnDOT Scour Code: E - CULVERT

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	<u> </u>	Is there a significant build-up of debris?
2.	<u> </u>	Is there erosion of the embankment around the headwalls?
3.	<u> </u>	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	<u> </u>	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	<u> </u>	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	<u> </u>	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	<u> </u>	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	<u> </u>	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	<u> </u>	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	<u> </u>	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 90389

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	<u>7</u>	Channel has no notable aggregation, degradation, or lateral movement.

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	<u>E - CULVERT</u>		

Underwater Inspection

Underwater Inspection By Divers: _____
No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____ **High Water Elev.:** _____ **Current Water Elev.:** _____
Pile Tip Elev.: _____ **Low Water Elev.:** _____ **Current Streambed Elev.:** _____
Scour Hole Elev.: _____ **Current Scour Hole Elev.:** _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 90389

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 90389	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 10/05/2015	STRUCTURE TYPE: Concrete Culvert (includes frame culverts)
FACILITY CARRIED: CSAH 12(CR F)	FEATURES INTERSECTED: SUCKER CREEK
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance Monitoring Plan
 Other Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer