

**2016 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 90405
BNSF RR over CSAH 51(LEXINGTON)**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: St Paul

STATE: Minnesota

Date of Inspection: 05/14/2016

Equipment Used:

Owner: County Highway Agency

Inspected By: Engel, Michael; Grau, Joe; Sanders, Rick

Report Written By: Joe Grau

Report Reviewed By: Glenn Pagel

Final Report Date: 08/24/2016



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
STRUCTURE INVENTORY	3
ROUTINE INSPECTION DATA	4
ELEMENTS	7
PICTURES	10
THUMBNAIL PICTURES	17
CULVERT	18
CHANNEL	19
SCOUR POA	21
MAINTENANCE	22
STRUCTURAL ASSESSMENT REPORT - ROUTINE	23

Minnesota Structure Inventory Report

Bridge ID: 90405

BNSF RR over CSAH 51
(LEXINGTON)

Date: 08/10/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +		
Agency Br. No. Crew District 05 Maint. Area County 062 - Ramsey City St Paul Township Desc. Loc. 0.2 MI S OF JCT MSAS 122 Sect., Twp., Range 26 - 029N - 23W Latitude 44 ° 58 ' 24.87 " Longitude 93 ° 8 ' 47.62 " Custodian 27 - Railroad Owner 02 - County Highway Agency BMU Agreement Year Built 1907 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 5 - OTHER Date Opened to Traffic On - Off System 0 - OFF Legislative District 66B Potential ABC 2 - N/A	Bridge Match ID (TIS) Roadway O/U Key Route Sys Number Roadway Name or Description Railroad over Level of Service Roadway Type Control Section (TH Only) Reference Point Detour Length mi. Lanes ON UNDER 2 ADT YEAR HCA DT ADTT % Functional Class	Userkey 199 Structurally Deficient N Functionally Obsolete N Sufficiency Rating -2 Routine Inspection Date 05/14/2016 Routine Inspection Frequency 12 Inspector Name Grau, Joe Status A - Open		
		+ NBI CONDITION RATINGS +		
		Deck	N	Unsound Deck %
		Superstructure	5	
		Substructure	5	
		Channel	N	
		Culvert	N	
		+ NBI APPRAISAL RATINGS +		
		Structure Evaluation	N	
		Deck Geometry	N	
		Underclearances	2	
		Waterway Adequacy	N	
		Approach Alignment	5	
		+ SAFETY FEATURES +		
		Bridge Railing	N - NOT REQUIRED	
		GR Transition	N - NOT REQUIRED	
		Appr. Guardrail	N - NOT REQUIRED	
		GR Termini	N - NOT REQUIRED	
		+ IN DEPTH INSP. +		
			Y/N	Freq
		Frac. Critical	N	
		Underwater	N	
		Pinned Asbly.	N	
		Spec. Feat.		
		+ WATERWAY +		
		Drainage Area (sq. mi.)		
		Waterway Opening (sf.)		
		Navigation Control	N - Not applicable, no	
		Pier Protection	-	
		Nav. Clr. (ft.)	Vert.	0.0
			Horiz.	0.0
		Nav. Vert. Lift Bridge Clear. (ft.)		
		MN Scour Code	A - NON	Year
		+ CAPACITY RATINGS +		
		Design Load	8 - RAILROAD	
		Operating Rating	7 - RAILROAD	65.0
		Inventory Rating	7 - RAILROAD	65.0
		Posting VEH:	SEMI:	DBL:
		Rating Date		
		Overweight Permit Codes		
		A N - N/A	B N - N/A	C N - N/A
+ STRUCTURE +	+ RDWY DIMENSIONS +	+ NBI APPRAISAL RATINGS +		
Service On 2 - Railroad Service Under 1 - Highway, w/ or w/out ped. Main Span Type 1 - Concrete Main Span Design 12 - Arch Main Span Detail U - SPANRDEL FILLED ARCH Appr. Span Type Appr. Span Design Appr. Span Detail Skew 0 Culvert Type Barrel Length Cantilever ID Number of Spans MAIN: 1 APPR: 0 TOTAL: Main Span Length 50.0 ft. Structure Length 110.0 ft. Deck Width (Out-to-Out) 73.0 ft. Deck Material N - Not Applicable Wear Surf Type N - Not Applicable (applies) Wear Surf Install Year Wear Course/Fill Depth 0.00 ft. Deck Membrane 0 - None Deck Rebars N - Not Applicable (no deck) Deck Rebars Install Year Structure Area (Out-to-Out) 8030 sq. ft. Roadway Area (Curb-to-Curb) sq. ft. Sidewalk Width 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. Curb Height Lt 0.00 ft. Rt 0.00 ft. Rail Type Lt NN Rt NN	If Divided NB-EB SB-WB Roadway Width ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. ft. ft. Lateral Clearance ft. ft. Appr. Surface Width ft. Bridge Roadway Width ft. Median Width On Bridge ft.			
	+ MISC. BRIDGE DATA +			
	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID Abutment Foundation (Material/Type) 1 - CONC Pier Foundation (Material/Type) N - N/A N - N/A Historic Status 5 - Not eligible			
	+ PAINT +			
	Year Painted Unsound Paint % Painted Area sq. ft. Primer Type Finish Type			
	+ BRIDGE SIGNS +			
	Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 0 - Not Required Vertical 2 - Shldr Clr Restr (Arch)			

MINNESOTA BRIDGE INSPECTION REPORT

08/24/2016

BRIDGE 90405 BNSF RR OVER CSAH 51(LEXINGTON)

ROUTINE INSP. DATE: 05/14/2016

County: Ramsey	Location: 0.2 MI S OF JCT MSAS 122	Length: 110.0 ft.
City: St Paul	Route: Ref. Pt.:	Deck Width: 73.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 26 Township: 029N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 11 - Arch - Deck	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:
NBI Deck: N Super: 5 Sub: 5 Chan: N Culv: N	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 5 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: 2 - Shldr Clr Restr (Arch)	Unofficial Sufficiency Rating N

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
144	Reinforced Concrete Arch	2	Routine	05/14/2016	52 LF	0	52	0	0	N/A
			Routine	05/14/2015	52 LF	0	52	0	0	N/A

Notes: Many leakage stained vertical cracks in the arch which are mostly at the lower 6 feet. 2000-08.
 Minor spalling along these cracks.
 South fascia of arch cracked and spalling. 85-13
 South arch is 1-1/2" lower at east and west abutments than north arch. 85-15
 Moderate cracking, leaching, staining and surface scale present. 2013-15
 Minor delaminations and spalls present. 2013-15

215	Reinforced Concrete Abutment	2	Routine	05/14/2016	141 LF	84	47	10	0	N/A
			Routine	05/14/2015	141 LF	84	47	10	0	N/A

Notes: Both abutments have spalling and cracking, especially along bases. 00-13
 Spalling on much of the vertical abutment faces and base. 06-13
 Significant amount of water being transmitted thru the abutment. 2009-13
 Moderate cracking, leaching, staining and surface scale present. 2013-15
 Minor delaminations and spalls present. 2013-15
 CS 3 - has extensive deterioration, spalls and scaling. 2014-15

333	Masonry, Other or Combination Material Railing	2	Routine	05/14/2016	220 LF	0	220	0	N/A	N/A
			Routine	05/14/2015	220 LF	0	220	0	N/A	N/A

Notes: Railing for maintenance crews only. 2014-15

362	Traffic Impact Smart Flag	2	Routine	05/14/2016	1 EA	0	1	0	N/A	N/A
			Routine	05/14/2015	1 EA	0	1	0	N/A	N/A

Notes: Impact damage has occurred, mostly outside lanes. 2013-15

387	Reinforced Concrete Wingwall	2	Routine	05/14/2016	4 EA	0	4	0	0	N/A
			Routine	05/14/2015	4 EA	0	4	0	0	N/A

Notes: Wing wall coping and verticle faces are spalling, especially at the bottom, 85-13
 Moderate cracking, leaching, staining and surface scale present. 2013-15
 Minor delaminations and spalls present. 2013-15

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
964	Critical Finding Smart Flag	2	Routine	05/14/2016	1 EA	1	0	N/A	N/A	N/A
			Routine	05/14/2015	1 EA	1	0	N/A	N/A	N/A

Notes:
Date 2003-10-09 -
Previous comments > DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

981	Signing	2	Routine	05/14/2016	1 EA	1	0	0	0	0
			Routine	05/14/2015	1 EA	1	0	0	0	0

Notes: The north advance sign only reads low clearance. 98-07.
12'-8" at center line of inside N.B. lane and has been hit and damaged. 2007-11
13'-0" at center of S.B. lane
10'-6" at S.G.L. 2014
9'-4" at N.G.L. 2014

New signs. 2012
All required signage is in place. 2015

986	Curb & Sidewalk	1	Routine	05/14/2016	2 EA	2	0	0	N/A	N/A
			Routine	05/14/2015	2 EA	2	0	0	N/A	N/A

Notes: Curb and walk is under bridge , not on bridge. 2012-15

988	Miscellaneous Items	1	Routine	05/14/2016	1 EA	1	0	0	N/A	N/A
			Routine	05/14/2015	1 EA	1	0	0	N/A	N/A

Notes:

General Notes: BNSF RR contact info:

Michael Anderson bridges and structures supervisor (763) 782-3310 cell (612) 749-3401
michael.anderson5@bnsf.com

Lane Gilliland bridge inspector cell (612) 219-4219

58. Deck NBI:

36A. Brdg Railings NBI: Roadway is under bridge.

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail
Terminal NBI:

59. Superstructure NBI:

60. Substructure NBI:

61. Channel NBI:

62. Culvert NBI:

71. Waterway Adeq NBI:

72. Appr Roadway
Alignment NBI:

Inventory Notes:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
-------------	--------------	-----	-------------	------------	----------	-------------	-------------	-------------	-------------	-------------

Joe Grau
Inspector's Signature

Glenn Pagel
Reviewer's Signature

MINNESOTA BRIDGE INSPECTION REPORT

08/24/2016

Inspector: CO Bridge

BRIDGE 90405 BNSF RR OVER CSAH 51(LEXINGTON)

County: Ramsey	Location: 0.2 MI S OF JCT MSAS 122	Length: 110.0 ft.
City: St Paul	Route: Ref. Pt.:	Deck Width: 73.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 26 Township: 029N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 11 - Arch - Deck	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:
NBI Deck: N Super: 5 Sub: 5 Chan: N Culv: N		
	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 5 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: 2 - Shldr Clr Restr (Arch)	Unofficial Sufficiency Rating N

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
144	Reinforced Concrete Arch	Routine	05/14/2016	52 LF	0	52	0	0
		Migrated Values		52 LF	0	52	0	0
	Notes: Many leakage stained vertical cracks in the arch which are mostly at the lower 6 feet. 2000-08. Minor spalling along these cracks. South fascia of arch cracked and spalling. 1985-2016 South arch is 1-1/2" lower at east and west abutments than north arch. 85-15 Moderate cracking, leaching, staining and surface scale present. 2013-16 Minor delaminations and spalls present. 2013-16 Delam over traffic, SB on S. side fascia. 2016 Delam over sidewalk / traffic - NB gutter lane. 2016							
215	Reinforced Concrete Abutment	Routine	05/14/2016	181 LF	65	60	53	3
		Migrated Values		181 LF	65	60	53	3
	Notes: Both abutments have spalling and cracking, especially along bases. 2000-16 Spalling on much of the vertical abutment faces and base. 2006-16 Significant amount of water being transmitted thru the abutment. 2009-16 Moderate cracking, leaching, staining and surface scale present. 2013-16 Minor delamination and spalls present. 2013-16 CS 3 - has extensive deterioration, spalls and scaling. 2014-16 CS 4 - Spalling deeper than 4". 2016 Coping and vertical faces are spalling, especially at the bottom, 2000-16 Moderate cracking, leaching, staining and surface scale present. 2013-16 Minor delamination and spalls present. 2013-16							
800	Critical Deficiencies or Safety Hazards	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
	Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION. None found in 2016.							
880	Impact Damage	Routine	05/14/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
	Notes: Impact damage has occurred, mostly outside lanes. 2013-16							
890	Load Posting or Vertical Clearance Signing	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
	Notes: The north advance sign only reads low clearance. 98-07. 12'-8" at center line of inside N.B. lane and has been hit and damaged. 2007-11 13'-0" at center of S.B. lane 10'-6" at S.G.L. 2014 9'-4" at N.G.L. 2014 New signs. 2012							

BRIDGE 90405 BNSF RR OVER CSAH 51(LEXINGTON)

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
891	Other Bridge Signing	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: All required signage is in place. 2015-16								
892	Slopes & Slope Protection	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to rate the condition of slopes and slope protection.								
894	Deck & Approach Drainage	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to rate the condition, function, and adequacy of the drainage system.								
895	Sidewalk, Curb, & Median	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Curb and walk is under bridge , not on bridge. 2012-15								
899	Miscellaneous Items	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
900	Protected Species	Routine	05/14/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure. None noticed in 2016.								

General Notes: BNSF RR contact info:

Michael Anderson bridges and structures supervisor (763) 782-3310 cell (612) 749-3401
michael.anderson5@bnsf.com

Lane Gilliland bridge inspector cell (612) 219-4219

58. Deck NBI:

36A. Brdg Railings NBI: Roadway is under bridge.

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail Terminal NBI:

59. Superstructure NBI:

60. Substructure NBI:

61. Channel NBI:

62. Culvert NBI:

71. Waterway Adeq NBI:

72. Appr Roadway Alignment NBI:

Inventory Notes:

BRIDGE 90405 BNSF RR OVER CSAH 51(LEXINGTON)

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
-------------	--------------	-------------	------------	----------	-------------	-------------	-------------	-------------

Inspector's Signature

Reviewer's Signature

Pictures




Photo 1 - 6-23-2010 CL_joint



Photo 2 - 6-23-2010 CL_joint_offset

Pictures



Photo 3 - 6-23-2010 eastside arch



Photo 4 - 6-23-2010 SB_elevation view

Pictures



Photo 5 - IMG_20120628_080715



Photo 6 - IMG_20120628_080745

Pictures



Photo 7 - Abutment at sidewalk E side (1)



Photo 8 - Abutment at sidewalk E side (2)

Pictures



Photo 9 - Abutment at sidewalk E side (3)



Photo 10 - Abutment at sidewalk W side (1)

Pictures



Photo 11 - Abutment at sidewalk W side (2)



Photo 12 - Abutment at sidewalk W side (3)


Pictures



Photo 13 - Abutment at sidewalk W side (4)



Photo 14 - NW corner



1. 6-23-2010
CL_joint.JPG



2. 6-23-2010
CL_joint_offset.JPG



3. 6-23-2010 eastside
arch.JPG



4. 6-23-2010
SB_elevation view.JPG



5.
IMG_20120628_080715.
jpg



6.
IMG_20120628_080745.
jpg



7. Abutment at sidewalk
E side (1).JPG



8. Abutment at sidewalk
E side (2).JPG



9. Abutment at sidewalk
E side (3).JPG



10. Abutment at
sidewalk W side (1).JPG



11. Abutment at
sidewalk W side (2).JPG



12. Abutment at
sidewalk W side (3).JPG



13. Abutment at
sidewalk W side (4).JPG



14. NW corner.JPG

Culvert

Bridge No.: 90405

Culvert

Item	Description	Condition	Comments
Culvert Overall:	NBI Item 62	N	

Minnesota Scour Code: A - NON WATERWAY

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there erosion of the embankment around the headwalls?
3.	_____	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	_____	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	_____	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	_____	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	_____	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	_____	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 90405

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	N	

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:			
Downstream Bank Protection:			
Bridge Revetment:			
Minnesota Scour Code:	A - NON WATERWAY		

Underwater Inspection

Underwater Inspection By Divers: _____
 No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____ High Water Elev.: _____ Current Water Elev.: _____
 Pile Tip Elev.: _____ Low Water Elev.: _____ Current Streambed Elev.: _____
 Scour Hole Elev.: _____ Current Scour Hole Elev.: _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.
- Per Minnesota Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 90405

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to Minnesota's Bridge Scour website for other
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------

BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the Minnesota Bridge Office upon receipt of the 7 Day FC Report; however, it is an **OPTIONAL** tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 90405	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 05/14/2016	STRUCTURE TYPE: Concrete Arch - Deck
FACILITY CARRIED: BNSF RR	FEATURES INTERSECTED: CSAH 51(LEXINGTON)
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> COMPLEX:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- | | |
|---|---|
| <input type="checkbox"/> Repair/Maintenance | <input type="checkbox"/> Monitoring Plan |
| <input type="checkbox"/> Complex | <input type="checkbox"/> Increased Inspection Frequency |

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer