

**2016 UPDATE
BRIDGE INSPECTION REPORT**



**BRIDGE # 90415
CR 149 over STREAM**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: WHITE BEAR

STATE: Minnesota

Date of Inspection: 09/20/2016

Reason for Update Report:

Equipment Used: Life Jacket, Probing Rod, Other - Waders

Owner: County Highway Agency

Inspected By: Essler, Brian

Report Written By: Brian Essler

Report Reviewed By: Nicklaus Fischer

Final Report Date: 11/28/2016




Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
STRUCTURE INVENTORY	3
ROUTINE INSPECTION DATA	4
ELEMENTS	6
PICTURES	8
CULVERT	12
CHANNEL	13
SCOUR POA	15

Minnesota Structure Inventory Report

Bridge ID: 90415

CR 149

over STREAM

Date: 11/28/2016

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City			
Township 62001 - WHITE BEAR			
Desc. Loc. 0.8 MI N OF JCT CSAH 5			
Sect., Twp., Range	3	- 030N	- 22W
Latitude Deg	45	Min 6	Sec 55.65
Longitude Deg	93	Min 1	Sec 40.44
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		1939	
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 0 - NO PLAN			
Date Opened to Traffic			
On-Off System 0 - OFF			
Legislative District 53B			
ABC Suitable			

STRUCTURE	
Service On	1 - Highway
Service Under	5 - Waterway
Main Span Type	
1 - Concrete	13 - Box Culvert
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	0
Culvert Type	W62D
Barrel Length	34 ft.
Cantilever ID	

NUMBER OF SPANS			
MAIN:	2	APPR:	0
TOTAL:	2		
Main Span Length	6.5	ft.	
Structure Length	14.2	ft.	
Deck Width (Out-to-Out)	0.0	ft.	
Deck Material	N - Not Applicable		
Wear Surf Type	6 - Bituminous		
Wear Surf Install Year			
Wear Course/Fill Depth	0.50	ft.	
Deck Membrane	N - Not Applicable (applies onl		
Deck Rebars	N - Not Applicable (no deck)		
Deck Rebars Install Year			
Structure Area (Out-to-Out)	0	sq. ft.	
Roadway Area (Curb-to-Curb)	sq. ft.		
Sidewalk Width	Lt 0.00	ft.	Rt 0.00
Curb Height	Lt 0.00	ft.	Rt 0.00
Rail Type	Lt 02	Rt 02	

ROADWAY			
Bridge Match ID (TIS) 0			
Roadway O/U Key Route On Structure			
Route Sys	07 - CNTY	Number	249
Roadway Name or Description			
CNTY 249			
Level of Service	1 - MAINLINE		
Roadway Type	2 - 2-way traffic		
Control Section (TH Only)			
Reference Point	000+00.770		
Detour Length	3.0	mi	
Lanes	On 2	Under 0	
	ADT 1900	Year 2005	
HCACT	0	ADTT 0 %	
Functional Class 19 - Urban - Local			

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	26.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.		ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	32.0	ft.	
Bridge Roadway Width	0.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	N - N/A
(Material/Type)	N - N/A
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	83.8
Routine Inspection Date	08/07/2015
Routine Inspection Frequency	24
Inspector Name	CO Bridge
Status	A - Open

NBI CONDITION RATINGS	
Deck	N - Not Applicable
Unsound Deck %	
Superstructure	N - Not Applicable
Substructure	N - Not Applicable
Channel	5 - Bank eroded; Major damage
Culvert	5 - Mod. to major deterioration

NBI APPRAISAL RATINGS	
Structure Evaluation 5	
Deck Geometry	N
Underclearances	N
Water Adequacy	5 - Occasional Flooding - Si
Approach Alignment	6 - Equal to present minimu

SAFETY FEATURES	
Bridge Railing	0 - SUBSTANDARD
GR Transition	0 - SUBSTANDARD
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	N - NOT REQUIRED

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical	N		
Underwater	N		
Pinned Asbly.	N		
Spec. Feat.			

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening	24	sq. ft.	
Navigation Control	0 - No nav. control on waterw		
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code	E - CULVERT	Year	

CAPACITY RATINGS			
Design Load	4 - H 20		
Operating Rating	B - Assigned ratir	24.0	
Inventory Rating	B - Assigned ratir	18.0	
Posting VEH:	SEMI:	DBL:	
Rating Date 01/10/1985			

Minnesota Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

Minnesota Structure Inventory Report

Bridge ID: 90415

CR 149 over STREAM

Date: 09/20/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
Agency Br. No. Crew District 05 Maint. Area County 062 - Ramsey City Township 62001 - WHITE BEAR Desc. Loc. 0.8 MI N OF JCT CSAH 5 Sect., Twp., Range 3 - 030N - 22W Latitude 45 ° 6 ' 55.65 " Longitude 93 ° 1 ' 40.44 " Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 1939 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 0 - NO PLAN Date Opened to Traffic On - Off System 0 - OFF Legislative District 53B Potential ABC 2 - N/A	Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 07 - CNTY Number 249 Roadway Name or Description CNTY 249 Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point 000+00.770 Detour Length 3.0 mi. Lanes ON 2 UNDER 0 ADT 1900 YEAR 2005 HCA DT ADTT % Functional Class 19 - Urban - Local	Userkey 102 Structurally Deficient N Functionally Obsolete N Sufficiency Rating 83.8 Routine Inspection Date 08/07/2015 Routine Inspection Frequency 24 Inspector Name Essler, Brian Status A - Open																				
		+ NBI CONDITION RATINGS +																				
		Deck N Unsound Deck % Superstructure N Substructure N Channel 5 Culvert 5																				
		+ NBI APPRAISAL RATINGS +																				
		Structure Evaluation 5 Deck Geometry N Underclearances N Waterway Adequacy 5 Approach Alignment 6																				
		+ SAFETY FEATURES +																				
		Bridge Railing 0 - SUBSTANDARD GR Transition 0 - SUBSTANDARD Appr. Guardrail 0 - SUBSTANDARD GR Termini N - NOT REQUIRED																				
		+ IN DEPTH INSP. +																				
		<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Underwater</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Pinned Asbly.</td> <td style="text-align: center;">N</td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	Frac. Critical	N			Underwater	N			Pinned Asbly.	N			Spec. Feat.			
	Y/N	Freq	Date																			
Frac. Critical	N																					
Underwater	N																					
Pinned Asbly.	N																					
Spec. Feat.																						
		+ WATERWAY +																				
		Drainage Area (sq. mi.) Waterway Opening (sf.) 24 Navigation Control 0 - No nav. control on Pier Protection <table style="width: 100%; border-collapse: collapse;"> <tr> <td>Nav. Clr. (ft.)</td> <td>Vert. 0.0</td> <td>Horiz. 0.0</td> </tr> </table> Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code E - CULVERT Year	Nav. Clr. (ft.)	Vert. 0.0	Horiz. 0.0																	
Nav. Clr. (ft.)	Vert. 0.0	Horiz. 0.0																				
		+ CAPACITY RATINGS +																				
		Design Load 4 - H 20 Operating Rating 2 - HS TRUCK 24.0 Inventory Rating 2 - HS TRUCK 18.0 Posting VEH: SEMI: DBL: Rating Date 01/10/1985 Overweight Permit Codes A N - N/A B N - N/A C N - N/A																				
+ STRUCTURE +	+ RDWY DIMENSIONS +																					
Service On 1 - Highway Service Under 5 - Waterway Main Span Type 1 - Concrete Main Span Design 13 - Box Culvert Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 0 Culvert Type W62D Barrel Length 34 Cantilever ID Number of Spans MAIN: 2 APPR: 0 TOTAL: Main Span Length 6.5 ft. Structure Length 14.2 ft. Deck Width (Out-to-Out) 0.0 ft. Deck Material N - Not Applicable Wear Surf Type 6 - Bituminous Wear Surf Install Year Wear Course/Fill Depth 0.50 ft. Deck Membrane N - Not Applicable (applies) Deck Rebars N - Not Applicable (no deck) Deck Rebars Install Year Structure Area (Out-to-Out) 0 sq. ft. Roadway Area (Curb-to-Curb) sq. ft. Sidewalk Width 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. Curb Height Lt 0.00 ft. Rt 0.00 ft. Rail Type Lt 02 Rt 02	If Divided NB-EB SB-WB Roadway Width 26.00 ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 32.0 ft. Bridge Roadway Width 0.0 ft. Median Width On Bridge ft.																					
	+ MISC. BRIDGE DATA +																					
	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID Abutment N - N/A Foundation (Material/Type) N - N/A Pier Foundation (Material/Type) N - N/A N - N/A Historic Status 5 - Not eligible																					
	+ PAINT +																					
	Year Painted Unsound Paint % Painted Area sq. ft. Primer Type Finish Type																					
	+ BRIDGE SIGNS +																					
	Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 0 - Not Required Vertical N - Not Applicable																					

MINNESOTA BRIDGE INSPECTION REPORT

11/28/2016

BRIDGE 90415 CR 149 OVER STREAM

ROUTINE INSP. DATE: 08/07/2015

County: Ramsey	Location: 0.8 MI N OF JCT CSAH 5	Length: 14.2 ft.
City:	Route: 07 - CNTY 249 Ref. Pt.: 000+00.770	Deck Width: 0.0 ft.
Township: 62001 - WHITE BEAR	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 3 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: W62D
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: 5 Culv: 5	Open, Posted, Closed: A - Open	
	MN Scour Code: E - CULVERT	
Appraisal Ratings - Approach: 6 Waterway: 5		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 83.8

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
----------	--------------	-----	-------------	------------	----------	----------	----------	----------	----------	----------

241	Reinforced Concrete Culvert	2	Update	09/20/2016	69 LF	0	69	0	0	N/A
			Routine	08/07/2015	69 LF	0	69	0	0	N/A

Notes: [2015] Culvert contains moderate scaling. Debris on both ends of culvert. Culvert was full of water during inspection.
 [2013] Culvert contains moderate scaling. Some cleanout has been done at both ends, but still contains blockage. Culvert was full of water during inspection.
 [2005-2011] Culvert is filled with debris & water making it difficult to view. Culvert should be cleaned out inside and at both ends to increase efficiency.
 [2001-2013] Minor deterioration with cracking and leaching.
 [2009] West end is full of water. At east end water is 0.5' lower than top of inside culvert.
 [1988-2013] Could use seal treatment.

334	Metal Bridge Railing (Coated or Painted)	2	Update	09/20/2016	30 LF	0	23	7	0	0
			Routine	08/07/2015	30 LF	0	23	7	0	0

Notes: [2013-2015] Railing contains 7 LF of moderate corrosion. Both rails need paint.
 [2001-2011] Coating has deteriorated. Minor corrosion on both rails.

388	Culvert Headwall, Wingwall or Other End Treatment	2	Update	09/20/2016	2 EA	0	2	0	0	N/A
			Routine	08/07/2015	2 EA	0	2	0	0	N/A

Notes: [2013-2015] Major spall at the NE corner of the east headwall. Moderate scaling is present.
 [2007-2015] Moderate spalling on east headwall. Moderate crack at center of west headwall.
 [2001-2005] Minor spalling on east headwall. Scaling is present on both sides with minor corrosion of rebar.

964	Critical Finding Smart Flag	2	Update	09/20/2016	1 EA	1	0	N/A	N/A	N/A
			Routine	08/07/2015	1 EA	1	0	N/A	N/A	N/A

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

981	Signing	1	Update	09/20/2016	1 EA	1	0	0	0	0
			Routine	08/07/2015	1 EA	1	0	0	0	0

Notes: [2003-2015] Horizontal clearance marker signs are in place.

982	Approach Guardrail	1	Update	09/20/2016	1 EA	0	0	1	N/A	N/A
			Routine	08/07/2015	1 EA	0	0	1	N/A	N/A

Notes: [1995-2015] No guardrail, installation is recommended.

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
987	Roadway over Culvert	2	Update	09/20/2016	1 EA	0	1	0	N/A	N/A
			Routine	08/07/2015	1 EA	0	1	0	N/A	N/A

Notes: [2009-2015] There is moderate settlement at both ends. Some deterioration of bituminous over culvert.
[2001-2007] Roadway over culvert has minor settlement. [1992] Overlaid with chip seal.

General Notes: [2016] Bridge Safety Inspection was updated by Brian Essler on 9-20-2016.
[2015] Bridge Safety Inspection was completed by Dan Bodelson & Brian Essler on 8/12/2015.
[2013] Inspection was completed by B. Wieman and R. Bussiere.
[2011] Bridge safety inspection was completed by B. Wieman 9/13/2011.
[2009] Bridge safety inspection was completed by B. Wieman 6/11/2009.
[2007] Bridge safety inspection by B. Wieman & B. Essler 7/24/2007.
[2005] bridge safety inspection was completed by Bret Wieman 8/19/2005.
ALL EXPOSED CONCRETE EPOXIED DURING SUMMER 82. #104 RAILING DAMAGED (EAST) RAIL REPAIRED 1995.
#186 WOOD SILL BLOCK DETERIORATING. 83, 90. COVER WITH BIT. 95.

58. Deck NBI: Culvert

36A. Brdg Railings NBI:

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail
Terminal NBI:

59. Superstructure NBI: Culvert

60. Substructure NBI: Culvert

61. Channel NBI: Debris blocking culvert on both ends.

62. Culvert NBI: Culvert contains moderate scaling with cracking and leaching. Major spall at the NE corner of the east headwall.

71. Waterway Adeq NBI: Less than 1' of freeboarding

72. Appr Roadway
Alignment NBI:

Inventory Notes: There is a 0.85' bituminous overlay over culvert.

Brian Essler

Inspector's Signature

Nicklaus Fischer

Reviewer's Signature

MINNESOTA BRIDGE INSPECTION REPORT

11/28/2016

Inspector: CO Bridge

BRIDGE 90415 CR 149 OVER STREAM

County: Ramsey	Location: 0.8 MI N OF JCT CSAH 5	Length: 14.2 ft.
City:	Route: 07 - CNTY 249 Ref. Pt.: 000+00.770	Deck Width: 0.0 ft.
Township: 62001 - WHITE BEAR	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 3 Township: 030N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: W62D
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: 5 Culv: 5		
	Open, Posted, Closed: A - Open	
	MN Scour Code: E - CULVERT	

Appraisal Ratings - Approach: 6	Waterway: 5	Unofficial Structurally Deficient	N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete	N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating	83.8

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
241	Reinforced Concrete Culvert	Update	09/20/2016	69 LF	0	69	0	0
		Migrated Values		69 LF	0	69	0	0
Notes: [2015] Culvert contains moderate scaling. Debris on both ends of culvert. Culvert was full of water during inspection. [2013] Culvert contains moderate scaling. Some cleanout has been done at both ends, but still contains blockage. Culvert was full of water during inspection. [2005-2011] Culvert is filled with debris & water making it difficult to view. Culvert should be cleaned out inside and at both ends to increase efficiency. [2001-2013] Minor deterioration with cracking and leaching. [2009] West end is full of water. At east end water is 0.5' lower than top of inside culvert. [1988-2013] Could use seal treatment.								

330	Metal Bridge Railing	Update	09/20/2016	30 LF	0	30	0	0
		Migrated Values		30 LF	0	30	0	0
Notes: [2013-2015] Railing contains 7 LF of moderate corrosion. Both rails need paint. [2001-2011] Coating has deteriorated. Minor corrosion on both rails.								
	515 - Steel Protective Coating	Update	09/20/2016	999 SF	999	0	0	0
		Migrated Values		999 SF	999	0	0	0
Notes: [2016] Migrator assumed CS1 and a quantity of 999 SF.								

800	Critical Deficiencies or Safety Hazards	Update	09/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION.								

870	Culvert End Treatment	Update	09/20/2016	2 EA	0	2	0	0
		Migrated Values		2 EA	0	2	0	0
Notes: [2013-2015] Major spall at the NE corner of the east headwall. Moderate scaling is present. [2007-2015] Moderate spalling on east headwall. Moderate crack at center of west headwall. [2001-2005] Minor spalling on east headwall. Scaling is present on both sides with minor corrosion of rebar.								

871	Roadway Over Culvert	Update	09/20/2016	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: [2009-2015] There is moderate settlement at both ends. Some deterioration of bituminous over culvert. [2001-2007] Roadway over culvert has minor settlement. [1992] Overlaid with chip seal.								

891	Other Bridge Signing	Update	09/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: [2003-2015] Horizontal clearance marker signs are in place.								

BRIDGE 90415 CR 149 OVER STREAM

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
892	Slopes & Slope Protection	Update	09/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to rate the condition of slopes and slope protection.								
893	Guardrail	Update	09/20/2016	1 EA	0	0	0	1
		Migrated Values		1 EA	0	0	0	1
Notes: [1995-2015] No guardrail, installation is recommended.								
894	Deck & Approach Drainage	Update	09/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to rate the condition, function, and adequacy of the drainage system.								
900	Protected Species	Update	09/20/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure.								

General Notes: [2016] Bridge Safety Inspection was updated by Brian Essler on 9-20-2016.
 [2015] Bridge Safety Inspection was completed by Dan Bodelson & Brian Essler on 8/12/2015.
 [2013] Inspection was completed by B. Wieman and R. Bussiere.
 [2011] Bridge safety inspection was completed by B. Wieman 9/13/2011.
 [2009] Bridge safety inspection was completed by B. Wieman 6/11/2009.
 [2007] Bridge safety inspection by B. Wieman & B. Essler 7/24/2007.
 [2005] bridge safety inspection was completed by Bret Wieman 8/19/2005.
 ALL EXPOSED CONCRETE EPOXIED DURING SUMMER 82. #104 RAILING DAMAGED (EAST) RAIL REPAIRED 1995.
 #186 WOOD SILL BLOCK DETERIORATING. 83, 90. COVER WITH BIT. 95.

- 58. Deck NBI: Culvert
 - 36A. Brdg Railings NBI:
 - 36B. Transitions NBI:
 - 36C. Appr Guardrail NBI:
 - 36D. Appr Guardrail Terminal NBI:
 - 59. Superstructure NBI: Culvert
 - 60. Substructure NBI: Culvert
 - 61. Channel NBI: Debris blocking culvert on both ends.
 - 62. Culvert NBI: Culvert contains moderate scaling with cracking and leaching. Major spall at the NE corner of the east headwall.
 - 71. Waterway Adeq NBI: Less than 1' of freeboarding
 - 72. Appr Roadway Alignment NBI:
- Inventory Notes: There is a 0.85' bituminous overlay over culvert.

Brian Essler
 Inspector's Signature

Nicklaus Fischer
 Reviewer's Signature

Pictures



Photo 1 -



Photo 2 -

Pictures



Photo 3 -



Photo 4 -

Pictures



Photo 5 -



Photo 6 -

Pictures



Photo 7 -



Photo 8 -

Culvert

Bridge No.: 90415

Culvert

Item	Description	Condition	Comments
Culvert Overall:	NBI Item 62	5	Culvert contains moderate scaling with cracking and leaching. Major spall at the NE corner of the east headwall.

Minnesota Scour Code: E - CULVERT

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there erosion of the embankment around the headwalls?
3.	_____	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	_____	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	_____	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	_____	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	_____	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	_____	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 90415

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	<u>5</u>	Debris blocking culvert on both ends.

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
Minnesota Scour Code:	<u>E - CULVERT</u>		

Underwater Inspection

Underwater Inspection By Divers: _____

No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____	High Water Elev.: _____	Current Water Elev.: _____
Pile Tip Elev.: _____	Low Water Elev.: _____	Current Streambed Elev.: _____
	Scour Hole Elev.: _____	Current Scour Hole Elev.: _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.
- Per Minnesota Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 90415

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to Minnesota's Bridge Scour website for other
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____