

**2015 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 93532
CSAH 15(CR E) over CO DITCH # 2**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: New Brighton

Date(s) of Inspection: 10/06/2015

Equipment Used:

Owner: County Highway Agency

Inspected By: Essler, Brian

Report Written By: Brian Essler

Report Reviewed By: Nicklaus Fischer

Final Report Date: 01/07/2016

**MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128**



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	7
THUMBNAIL PICTURES	11
CULVERT	12
CHANNEL	13
SCOUR POA	15
CHANNEL X-SECTION	16
MAINTENANCE	17
STRUCTURAL ASSESSMENT REPORT - ROUTINE	18

MnDOT Structure Inventory Report

Bridge ID: 93532

CSAH 15(CR E)

over CO DITCH # 2

Date: 01/07/2016

GENERAL	
Agency Br. No.	
District	Metro
Maint. Area	Crew
County	062 - Ramsey
City	New Brighton
Township	
Desc. Loc.	0.1 MI W OF JCT CSAH 77
Sect., Twp., Range	29 - 030N - 23W
Latitude	Deg 45 Min 3 Sec 3.90
Longitude	Deg 93 Min 11 Sec 58.23
Custodian	02 - County Highway Agency
Owner	02 - County Highway Agency
BMU Agreement	
Year Built	1968
MN Year Reconstructed	
FHWA Year Reconstructed	
MN Temporary Status	
Bridge Plan Location	3 - COUNTY
Date Opened to Traffic	
On-Off System	1 - ON
Legislative District	50B

STRUCTURE	
Service On	1 - Highway
Service Under	5 - Waterway
Main Span Type	5 - Prestress or Precast 14 - Pipe Culvert (Round)
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	30 L
Culvert Type	4' DIA
Barrel Length	114 ft.
Cantilever ID	

NUMBER OF SPANS		
MAIN:	4	APPR: 0 TOTAL: 4
Main Span Length	4.6	ft.
Structure Length	24.0	ft.
Deck Width (Out-to-Out)	0.0	ft.
Deck Material	N - Not Applicable	
Wear Surf Type	6 - Bituminous	
Wear Surf Install Year		
Wear Course/Fill Depth	12.00	ft.
Deck Membrane	0 - None	
Deck Rebars	N - Not Applicable (no deck)	
Deck Rebars Install Year		
Structure Area (Out-to-Out)	0	sq. ft.
Roadway Area (Curb-to-Curb)		sq. ft.
Sidewalk Width	Lt 0.00	ft. Rt 0.00
Curb Height	Lt 0.00	ft. Rt 0.00
Rail Type	Lt NN	Rt NN

ROADWAY	
Bridge Match ID (TIS)	0
Roadway O/U Key	Route On Structure
Route Sys	04 - CSAH Number 15
Roadway Name or Description	CSAH 15
Level of Service	1 - MAINLINE
Roadway Type	2 - 2-way traffic
Control Section (TH Only)	
Reference Point	001+00.300
Detour Length	3.0 mi
Lanes	On 2 Under 0
	ADT 6773 Year 2008
HCACT	0 ADTT 0 %
Functional Class	16 - Urban - Minor Arterial

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	30.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.		ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	32.0	ft.	
Bridge Roadway Width	0.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	N - N/A
(Material/Type)	N - N/A
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	85.4
Routine Inspection Date	10/06/2015
Routine Inspection Frequency	24
Inspector Name	County, Ramsey
Status	A - Open

NBI CONDITION RATINGS	
Deck	N - Not Applicable
Unsound Deck %	
Superstructure	N - Not Applicable
Substructure	N - Not Applicable
Channel	3 - Protection failure
Culvert	5 - Mod. to major deterioration

NBI APPRAISAL RATINGS	
Structure Evaluation	5
Deck Geometry	N
Underclearances	N
Water Adequacy	8 - Bridge Above Approach
Approach Alignment	8 - Equal to present desirable

SAFETY FEATURES	
Bridge Railing	N - NOT REQUIRED
GR Transition	N - NOT REQUIRED
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	N - NOT REQUIRED

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical			
Underwater			
Pinned Asbly.			
Spec. Feat.			

WATERWAY	
Drainage Area (sq. mi.)	
Waterway Opening	50 sq. ft.
Navigation Control	0 - No nav. control on waterway
Pier Protection	
Nav. Clr. (ft.)	Vert. ft. Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)	
MN Scour Code	E - CULVERT Year

CAPACITY RATINGS	
Design Load	5 - HS 20
Operating Rating	5 - NRAP 24.0
Inventory Rating	5 - NRAP 18.0
Posting VEH:	SEMI: DBL:
Rating Date	01/08/1985

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 93532

CSAH 15(CR E) over CO DITCH # 2

Date: 01/07/2016

MnDOT BRIDGE INSPECTION REPORT

01/07/2016

Inspector: County, Ramsey

BRIDGE 93532 CSAH 15(CR E) OVER CO DITCH # 2

ROUTINE INSP. DATE: 10/06/2015

County: Ramsey	Location: 0.1 MI W OF JCT CSAH 77	Length: 24.0 ft.
City: New Brighton	Route: 04 - CSAH 15 Ref. Pt.: 001+00.300	Deck Width: 0.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 29 Township: 030N Range: 23W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: 4' DIA
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: 3 Culv: 5	Open, Posted, Closed: A - Open	
	MN Scour Code: E - CULVERT	

Appraisal Ratings - Approach: 8 Waterway: 8		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 85.4

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
241	Reinforced Concrete Culvert	2	Routine	10/06/2015	456 LF	0	0	456	0	N/A
			Routine	10/21/2013	456 LF	0	0	456	0	N/A

Requires Monitoring Monitored

Notes: Culvert #1 is 90% Blocked at apron 2015.
 Riprap is in front of the north end of culvert #2 & #3 2011-2015.
 There is blockage in front of all culverts at the south end 2009-2015.
 Culvert #1 is 1/2 full of debris 2009-2015.
 There is moderate scaling bottom of culverts #2, #3 & #4 2009-2015.
 There is delamination at south end culvert #2 at top inside of culvert 2007-2015.
 There contains moderate settlement with separation of joints. There are 4 sets of culverts 2005-2015.
 There is riprap and debris in culverts #1, #2 & #3. The south end of culvert #1 is severely blocked 2007.
 #1 culvert is not completely blocked @ south end. #1 culvert 1/2 filled with debris 2005.
 Culvert #1 is completely blocked from embankment erosion & debris 2001-2007.
 Spalling at south end of culvert #2 2001-2007.

361	Scour Smart Flag	2	Routine	10/06/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/21/2013	1 EA	0	1	0	N/A	N/A

Requires Monitoring Monitored

Notes: Minor scour at both ends 2001-2015.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
388	Culvert Headwall, Wingwall or Other End Treatment	2	Routine	10/06/2015	2 EA	0	2	0	0	N/A
			Routine	10/21/2013	2 EA	0	2	0	0	N/A

 Requires Monitoring Monitored

Notes: The south end of culverts #1 & #2 contain major spalls 2009-2015.
The south end of culverts #3 & #4 contain moderate spalls 2009-2015.
The north end of all culvert aprons contain moderate spalls 2009-2015.
The south end has debris in front of all 4 culverts restricting flow. 50% flow into Culvert #1 2011-2015.
Minor amount of debris @ south end except at apron #1. Apron #1 has 50% blockage with debris 2005, 2011-2015.
South end of apron #1 needs clean out 2001-2015.
Culvert aprons contain minor cracks with moderate - major spalls 2001-2015.
Apron #1 @ south end has 90% blockage with debris 2007.
North end of apron #1, #2 & #3 need clean out 2007.
North end of apron #1 & #2 need clean out 2005.
Aprons are tied to culverts.

964	Critical Finding Smart Flag	2	Routine	10/06/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	10/21/2013	1 EA	1	0	N/A	N/A	N/A

 Requires Monitoring Monitored

Notes: < none >

982	Approach Guardrail	2	Routine	10/06/2015	1 EA	0	0	1	N/A	N/A
			Routine	10/21/2013	1 EA	0	0	1	N/A	N/A

 Requires Monitoring Monitored

Notes: No twisted end or crash attenuator @ north side -east end. Not required due to low speed as per MNDOT. 2013-2015
Guardrail system on the south side is absent. 1989-2015.
Minor traffic impact to guardrail on north side behind catch basin 2003-2015.
Traffic impact to twisted end @ north side - east end. Requires replacement 2007-2011.
Requires crash attenuator on north side guardrail 2009. Not required due to low speed as per MNDOT.
Need twist down end treatment for north side guardrail 1989 -2007.

985	Slopes & Slope Protection	1	Routine	10/06/2015	1 EA	0	0	1	N/A	N/A
			Routine	10/21/2013	1 EA	0	0	1	N/A	N/A

 Requires Monitoring Monitored

Notes: Bank has eroded to <7' from bituminous and concrete entrance for business 2009-2015.
Bank @ SW corner has slumped in front of culvert #1 2007-2015. Recommend bank restoration and riprap 2009-2015.
The north side has sheet piling, which is holding 2003-2015.
Erosion has taken place above the culverts at the south end 2003-2007.
South end needs 48" RCP extended & erosion control installed. Some erosion work done 1995.

987	Roadway over Culvert	2	Routine	10/06/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/21/2013	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: There is moderate settlement of west bound County Road E 2007-2015.
Minor settlement with pothole developing on the south side 2003-2005. Minor settlement 2001.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
-------------	--------------	-----	-------------	------------	----------	-------------	-------------	-------------	-------------	-------------

General Notes: 2015 Bridge safety inspection conducted by B. Essler & D Bodelson on 10/6/2015.
 2013 Bridge safety inspection conducted by B. Essler & D Bodelson on 10/21/2013.
 2011 Bridge safety inspection conducted by B. Wieman on 10/11/2011.
 2009 Inspection was completed by B. Wieman 7/10/2009.
 Highly recommend slope restoration and riprap @ SW corner 2009-2015.
 Inspection was completed by B. Wieman 7/25/2007.
 Bank @ SW corner has slumped in front of apron #1. #1 culvert has 90% blockage 2007-2009, 2015
 All aprons need protective fill 1983-1997. 3rd from east missing tie for apron 1989-2000. Apron #1 severely blocked 1987.
 Totally blocked 1989-2001.
 South slope badly eroded. Caused by catch basin at top. Needs cleaning 1983-1985. Channel, south side needs cleanup of
 major blockage 1983-1994. Some cleanup done 1997.
 Unreported as a bridge prior to 1981. Existing drainage system drains into top of culvert #1 @ north curb line from catch basin.

58. Deck NBI: Culvert

36A. Brdg Railings NBI: Culvert

36B. Transitions NBI: Not connected to the culvert

36C. Appr Guardrail NBI: Does not meet standards

36D. Appr Guardrail Terminal NBI: Twisted end treatment installed with speed limit less than 40 MPH

59. Superstructure NBI: Culvert

60. Substructure NBI: Culvert

61. Channel NBI: Bank has eroded to less than 7' from bituminous and concrete pavement above culvert. bank has slumped in front of culvert 1. South channel filled with debris. North channel debris 20' to 100' in channel north of aprons.

62. Culvert NBI: Moderate scaling. Moderate settling with separating of joints. Moderate to major spalls

71. Waterway Adeq NBI: greater than 3' of freeboard

72. Appr Roadway Alignment NBI: No speed reduction required

Inventory Notes:

Brian Essler

Inspector's Signature

Nicklaus Fischer

Reviewer's Signature

Pictures



Photo 1 - North Culvert 1



Photo 2 - North End

Pictures



Photo 3 - North End1



Photo 4 - Roadway East

Pictures



Photo 5 - Roadway West



Photo 6 - South Culvert 1

Pictures



Photo 7 - South End



Photo 8 - South End1



1. North Culvert 1.JPG




2. North End.JPG



3. North End1.JPG



4. Roadway East.JPG



5. Roadway West.JPG



6. South Culvert 1.JPG



7. South End.JPG



8. South End1.JPG

Culvert

Bridge No.: 93532

Culvert

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Culvert Overall:	NBI Item 62	<u>5</u>	Moderate scaling. Moderate settling with separating of joints. Moderate to major spalls

MnDOT Scour Code: E - CULVERT

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there erosion of the embankment around the headwalls?
3.	_____	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	_____	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	_____	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	_____	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	_____	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	_____	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 93532

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	<u>3</u>	Bank has eroded to less than 7' from bituminous and concrete pavement above culvert. bank has slumped in front of culvert 1. South channel filled with debris. North channel debris 20' to 100' in channel north of aprons.

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	<u>E - CULVERT</u>		

Underwater Inspection

Underwater Inspection By Divers: _____

No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____	High Water Elev.: _____	Current Water Elev.: _____
Pile Tip Elev.: _____	Low Water Elev.: _____	Current Streambed Elev.: _____
	Scour Hole Elev.: _____	Current Scour Hole Elev.: _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 93532

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 93532	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 10/06/2015	STRUCTURE TYPE: Concrete Culvert (includes frame culverts)
FACILITY CARRIED: CSAH 15(CR E)	FEATURES INTERSECTED: CO DITCH # 2
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:
- Repair/Maintenance
 - Monitoring Plan
 - Other
 - Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer