

**2015 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 93625
CSAH 58(EDGERTON) over CO DITCH # 16**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: Little Canada

Date(s) of Inspection: 10/28/2015

Equipment Used:

Owner: County Highway Agency

Inspected By: Essler, Brian

Report Written By: Brian Essler

Report Reviewed By: Nicklaus Fischer

Final Report Date: 01/07/2016

MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	7
THUMBNAIL PICTURES	9
CULVERT	10
CHANNEL	11
SCOUR POA	13
CHANNEL X-SECTION	14
MAINTENANCE	15
STRUCTURAL ASSESSMENT REPORT - ROUTINE	16

MnDOT Structure Inventory Report

Bridge ID: 93625

CSAH 58(EDGERTON)

over CO DITCH # 16

Date: 01/07/2016

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City Little Canada			
Township			
Desc. Loc. 0.2 MI N OF JCT CSAH 21			
Sect., Twp., Range 5 - 029N - 22W			
Latitude		Sec	
Deg 45	Min 1	24.90	
Longitude		Sec	
Deg 93	Min 4	35.29	
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		1973	
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 3 - COUNTY			
Date Opened to Traffic 7/1/1973			
On-Off System 0 - OFF			
Legislative District 54B			

STRUCTURE	
Service On	1 - Highway
Service Under	5 - Waterway
Main Span Type	
5 - Prestress or Precast 15 - Pipe Arch	
Main Span Detail	
Appr. Span Type	
Appr. Span Detail	
Skew	0
Culvert Type	102"X62"
Barrel Length	82 ft.
Canterlever ID	

NUMBER OF SPANS		
MAIN:	2	TOTAL: 2
APPR:	0	
Main Span Length	8.5	ft.
Structure Length	19.9	ft.
Deck Width (Out-to-Out)	0.0	ft.
Deck Material	N - Not Applicable	
Wear Surf Type	6 - Bituminous	
Wear Surf Install Year		
Wear Course/Fill Depth	8.47	ft.
Deck Membrane	0 - None	
Deck Rebars	N - Not Applicable (no deck)	
Deck Rebars Install Year		
Structure Area (Out-to-Out)	0	sq. ft.
Roadway Area (Curb-to-Curb)		sq. ft.
Sidewalk Width	Lt 0.00	Rt 0.00
	ft.	ft.
Curb Height	Lt 0.00	Rt 0.00
	ft.	ft.
Rail Type	Lt NN	Rt NN

ROADWAY	
Bridge Match ID (TIS) 0	
Roadway O/U Key Route On Structure	
Route Sys 04 - CSAH	Number 58
Roadway Name or Description	
CSAH 58	
Level of Service 1 - MAINLINE	
Roadway Type 2 - 2-way traffic	
Control Section (TH Only)	
Reference Point 004+00.434	
Detour Length	1.0 mi
Lanes	On 2 Under 0
	ADT 7370 Year 2008
HCACT	0 ADTT 0 %
Functional Class 16 - Urban - Minor Arterial	

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	42.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.		ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	42.0	ft.	
Bridge Roadway Width	0.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	N - N/A
(Material/Type)	N - N/A
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	85.5
Routine Inspection Date	10/28/2015
Routine Inspection Frequency	24
Inspector Name	County, Ramsey
Status	A - Open

NBI CONDITION RATINGS	
Deck	N - Not Applicable
Unsound Deck %	
Superstructure	N - Not Applicable
Substructure	N - Not Applicable
Channel	7 - Needs minor repairs
Culvert	5 - Mod. to major deterioration

NBI APPRAISAL RATINGS	
Structure Evaluation 5	
Deck Geometry	N
Underclearances	N
Water Adequacy	8 - Bridge Above Approache
Approach Alignment	8 - Equal to present desirabl

SAFETY FEATURES	
Bridge Railing	N - NOT REQUIRED
GR Transition	0 - SUBSTANDARD
Appr. Guardrail	0 - SUBSTANDARD
GR Termini	N - NOT REQUIRED

IN DEPTH INSP.			
	Y/N	Freq	Date
Frac. Critical			
Underwater			
Pinned Asbly.			
Spec. Feat.			

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening	69	sq. ft.	
Navigation Control	0 - No nav. control on waterw		
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code	E - CULVERT	Year	

CAPACITY RATINGS		
Design Load	5 - HS 20	
Operating Rating	5 - NRAP	24.0
Inventory Rating	5 - NRAP	18.0
Posting VEH:	SEMI:	DBL:
Rating Date 01/16/1985		

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 93625

CSAH 58(EDGERTON) over CO DITCH # 16

Date: 01/07/2016

MnDOT BRIDGE INSPECTION REPORT

01/07/2016

Inspector: County, Ramsey

BRIDGE 93625 CSAH 58(EDGERTON) OVER CO DITCH # 16

ROUTINE INSP. DATE: 10/28/2015

County: Ramsey	Location: 0.2 MI N OF JCT CSAH 21	Length: 19.9 ft.
City: Little Canada	Route: 04 - CSAH 58 Ref. Pt.: 004+00.434	Deck Width: 0.0 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: sq. ft. / %
Section: 5 Township: 029N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 19 - Culvert (includes frame culverts)	Local Agency Bridge Nbr.:	Culvert: 102"X62"
List:		Postings:
NBI Deck: N Super: N Sub: N Chan: 7 Culv: 5	Open, Posted, Closed: A - Open	
	MN Scour Code: E - CULVERT	

Appraisal Ratings - Approach: 8	Waterway: 8	Unofficial Structurally Deficient	N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete	N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating	85.5

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
241	Reinforced Concrete Culvert	2	Routine	10/28/2015	164 LF	0	82	82	0	N/A
			Routine	10/14/2013	164 LF	0	82	82	0	N/A

Requires Monitoring Monitored

Notes: Moderate spalling throughout may be caused by lack of re-bar clearance 2011-2015.
 #1 culvert - sections #1, #2 & #8 have a major spall on the bottom 2009-2015.
 Culvert #2 - #1 & #5 sections have a major spall on the bottom 2009-2015.
 There is moderate scaling both culverts @ flow line 2009-2015.
 Both culverts have moderate spalling (all sections) with exposed re-inforcing & corrosion present 2009-2015.
 Slight movement of all sections 2005-2015.
 South culvert #1 has a 1.0' X 6" major spall at joint between #1 & #2 sections. Section #8 has a 1.0' X 1.0' major spalled area 2007-2013.
 Some patching was done 2007.
 All joints could use grouting 2001-2013. Lift holes show signs of stress cracks. There are slight separation of joints. All sections are tied on the outside.

361	Scour Smart Flag	2	Routine	10/28/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/14/2013	1 EA	0	1	0	N/A	N/A

Requires Monitoring Monitored

Notes: There is some minor - moderate scour 2011-2015.
 Some blockage @ NE corner due to bank slumping 2001-2015. May also be caused by fill placed by property owner 2005-2007.

388	Culvert Headwall, Wingwall or Other End Treatment	2	Routine	10/28/2015	2 EA	0	1	1	0	N/A
			Routine	10/14/2013	2 EA	0	1	1	0	N/A

Requires Monitoring Monitored

Notes: The NW apron has moderate spalls and a crack at top with corrosion present 2009-2015.
 Southwest apron has a major spall with exposed reinforcing steel on top 1.0 X 3". Also has 6" of exposed reinforcing steel @ bottom 2007-2015.
 Minor - moderate cracking and spalling 2009-2015. North barrel 1st joint west end - concrete delamination (loose grout).
 Trash guards on west end are rusting 2003-2015.
 Debris at trash guards 2005-2007.
 Evidence of corrosion and spalling @ aprons 2003.
 Recommend filling & grouting all joints 1985-2005. Patching was done 2007.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
964	Critical Finding Smart Flag	2	Routine	10/28/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	10/14/2013	1 EA	1	0	N/A	N/A	N/A

 Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

981	Signing	1	Routine	10/28/2015	1 EA	0	0	1	0	0
			Routine	10/14/2013	1 EA	0	0	1	0	0

 Requires Monitoring Monitored

Notes: No horizontal clearance signs in place. Signing is recommended 2001-2015.

982	Approach Guardrail	1	Routine	10/28/2015	1 EA	0	0	1	N/A	N/A
			Routine	10/14/2013	1 EA	0	0	1	N/A	N/A

 Requires Monitoring Monitored

Notes: No guardrail in place. Guardrail is recommended 2001-2015.

985	Slopes & Slope Protection	1	Routine	10/28/2015	1 EA	1	0	0	N/A	N/A
			Routine	10/14/2013						

 Requires Monitoring MonitoredNotes: Minor erosion in all corners. 2015
Private cast in place wall is tied into apron @ SE corner 2003

987	Roadway over Culvert	2	Routine	10/28/2015	1 EA	0	1	0	N/A	N/A
			Routine	10/14/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Moderate settlement 2001-2015.

General Notes: 2015 Bridge Safety inspection was conducted by B. Essler & D. Bodelson on 10/28/2015.
2013 Bridge Safety inspection was conducted by B. Essler & D. Bodelson on 10/14/2013.
2011 Bridge Safety inspection was conducted by B. Wieman on 10/18/2011.
2009 Bridge Safety inspection was completed by B. Wieman 7/30/2009.
2005 Bridge Safety inspection was completed by Bret Wieman 9/14/2005.
New grouted rock wall @ SE corner. 2005-2007
New bituminous roadway over culvert 1984. Bridge consists of 2 - 102" W X 62" H X 82' L Conc. Arch Pipe.
Barrel joints slightly open due to settlement 1985 - 2005. South barrel showing signs of settlement. 2001-2005.
Private cast in place wall is tied into apron @ SE corner. 2003. See picture in file.
Debris is blocking apron #4 at east end 2003-2005

58. Deck NBI: Culvert

36A. Brdg Railings NBI: No railing, Culvert

36B. Transitions NBI: No guardrail

36C. Appr Guardrail NBI: No guardrail

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
36D.	Appr Guardrail Terminal NBI:		No guardrail, 30 MPH road							
59.	Superstructure NBI:		Culvert							
60.	Substructure NBI:		Culvert							
61.	Channel NBI:		Minor erosion on banks, Minor debris in channel, Minor to moderate scour							
62.	Culvert NBI:		Moderate scaling, Moderate spalling, slight misalignment							
71.	Waterway Adeq NBI:		More than 3' of freeboard							
72.	Appr Roadway Alignment NBI:		No speed reduction required							
	Inventory Notes:									

 Brian Essler
 Inspector's Signature

 Nicklaus Fischer
 Reviewer's Signature

Pictures



Photo 1 - East end



Photo 2 - Roadway north

Pictures



Photo 3 - Roadway south



Photo 4 - West end



1. East end.JPG



2. Roadway north.JPG



3. Roadway south.JPG



4. West end.JPG

Culvert

Bridge No.: 93625

Culvert

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Culvert Overall:	NBI Item 62	<u>5</u>	Moderate scaling, Moderate spalling, slight misalignment

MnDOT Scour Code: E - CULVERT

Waterway Inspection

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there erosion of the embankment around the headwalls?
3.	_____	Is there any indication of cracking or settlement of the culvert barrel or headwalls?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Do scour measurements indicate that the streambed is below the bottom of the cutoff walls at the ends of the culvert?
6.	_____	Is there evidence of distress in the roadway or approaches such as cracks in the pavement and sags in the guardrail or roadway? Also, is there cracking, erosion, or failure of the side slopes at or adjacent to the culvert?
7.	_____	Is there an indication of "piping" of water along the outside of the culvert such as cavities adjacent to the barrel?
8.	_____	Is the culvert without a bottom and scour measurements indicate that the streambed is below the plan streambed elevations?
9.	_____	Has the riprap or other scour protection been damaged or otherwise made ineffective?
10.	_____	If the culvert was designed to be buried (fill inside the culvert), is the material still in the barrel?

Notes:

- Streambed sounding data is to be documented.
- Soundings of the streambed should be done at each end of the culvert. If Items #5 or #8 are "Yes", then a streambed profile of the scoured area should be done.
- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Channel

Bridge No.: 93625

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	<u>7</u>	Minor erosion on banks, Minor debris in channel, Minor to moderate scour

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	<u>E - CULVERT</u>		

Underwater Inspection

Underwater Inspection By Divers: _____

No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point: _____	High Water Elev.: _____	Current Water Elev.: _____
Pile Tip Elev.: _____	Low Water Elev.: _____	Current Streambed Elev.: _____
	Scour Hole Elev.: _____	Current Scour Hole Elev.: _____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 93625

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 93625	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 10/28/2015	STRUCTURE TYPE: Concrete Culvert (includes frame culverts)
FACILITY CARRIED: CSAH 58(EDGERTON)	FEATURES INTERSECTED: CO DITCH # 16
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- | | |
|---------------------------------------------|---------------------------------------------------------|
| <input type="checkbox"/> Repair/Maintenance | <input type="checkbox"/> Monitoring Plan |
| <input type="checkbox"/> Other | <input type="checkbox"/> Increased Inspection Frequency |

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer