

**2015 ROUTINE
BRIDGE INSPECTION REPORT**



**BRIDGE # 62563
CSAH 23(CR C) over REC TRAIL**

DISTRICT: Metro

COUNTY: Ramsey

CITY/TOWNSHIP: Maplewood

Date(s) of Inspection: 09/16/2015

Equipment Used:

Owner: County Highway Agency

Inspected By: Bodelson, Dan

Report Written By: Dan Bodelson

Report Reviewed By: Kathy Jaschke

Final Report Date: 12/08/2015

**MnDOT Bridge Office
3485 Hadley Avenue North
Oakdale, MN 55128**



Table of Contents

<u>SECTION</u>	<u>PAGE</u>
COVER	1
SI&A	2
ADDITIONAL ROADWAYS	3
ROUTINE INSPECTION DATA	4
PICTURES	8
THUMBNAIL PICTURES	13
CULVERT	14
CHANNEL	15
SCOUR POA	17
CHANNEL X-SECTION	18
MAINTENANCE	19
STRUCTURAL ASSESSMENT REPORT - ROUTINE	20

MnDOT Structure Inventory Report

Bridge ID: 62563

CSAH 23(CR C)

over REC TRAIL

Date: 12/08/2015

GENERAL			
Agency Br. No.			
District Metro			
Maint. Area		Crew	
County 062 - Ramsey			
City Maplewood			
Township			
Desc. Loc. 0.6 MI E OF JCT TH 61			
Sect., Twp., Range 10 - 029N - 22W			
Latitude		Sec	
Deg 45	Min 1	15.19	
Longitude		Sec	
Deg 93	Min 2	24.53	
Custodian 02 - County Highway Agency			
Owner 02 - County Highway Agency			
BMU Agreement			
Year Built		1993	
MN Year Reconstructed			
FHWA Year Reconstructed			
MN Temporary Status			
Bridge Plan Location 3 - COUNTY			
Date Opened to Traffic			
On-Off System 1 - ON			
Legislative District 55A			

STRUCTURE			
Service On 5 - Highway-pedestrian			
Service Under 3 - Pedestrian - bicycle			
Main Span Type			
1 - Concrete	09 - Slab Span		
Main Span Detail			
Appr. Span Type			
Appr. Span Detail			
Skew 10		R	
Culvert Type			
Barrel Length		ft.	
Canterlever ID			

NUMBER OF SPANS			
MAIN: 1	APPR: 0	TOTAL: 1	
Main Span Length		46.7 ft.	
Structure Length		51.8 ft.	
Deck Width (Out-to-Out)		52.8 ft.	
Deck Material 1 - Concrete Cast-in-Place			
Wear Surf Type 4 - Low Slump Concrete			
Wear Surf Install Year 1993			
Wear Course/Fill Depth		0.17 ft.	
Deck Membrane 0 - None			
Deck Rebars 1 - Epoxy Coated Reinforcing			
Deck Rebars Install Year 1993			
Structure Area (Out-to-Out)		2735 sq. ft.	
Roadway Area (Curb-to-Curb)		2282 sq. ft.	
Sidewalk Width		Lt 0.00 ft. Rt 6.00 ft.	
Curb Height		Lt 0.50 ft. Rt 0.67 ft.	
Rail Type		Lt 28 Rt 28	

ROADWAY			
Bridge Match ID (TIS) 0			
Roadway O/U Key Route On Structure			
Route Sys 04 - CSAH		Number 23	
Roadway Name or Description			
CSAH 23			
Level of Service 1 - MAINLINE			
Roadway Type 2 - 2-way traffic			
Control Section (TH Only)			
Reference Point 007+00.685			
Detour Length		1.0 mi	
Lanes		On 2 Under 0	
ADT 4731		Year 2008	
HCACT		0 ADTT 0 %	
Functional Class 16 - Urban - Minor Arterial			

RDWY DIMENSIONS			
If Divided	NB-EB	SB-WB	
Roadway Width	44.00	ft.	ft.
Vertical Clearance		ft.	ft.
Max. Vert. Clear.		ft.	ft.
Horizontal Clear.	43.9	ft.	ft.
Lateral Clearance		ft.	ft.
Appr. Surface Width	44.0	ft.	
Bridge Roadway Width	44.0	ft.	
Median Width On Bridge		ft.	

MISC. BRIDGE DATA	
Structure Flared	0 - No flare
Parallel Structure	N - No parallel structure
Field Conn. ID	
Abutment Foundation	1 - CONC
(Material/Type)	3 - FTG PILE
Pier Foundation	N - N/A
(Material/Type)	N - N/A
Historic Status	5 - Not eligible

PAINT	
Year Painted	
Unsound Paint %	
Painted Area	sq. ft.
Primer Type	
Finish Type	

BRIDGE SIGNS	
Posted Load	0 - Not Required
Traffic	0 - Not Required
Horizontal	0 - Not Required
Vertical	N - Not Applicable

INSPECTION	
Userkey	102
Unofficial Structurally Deficient	N
Unofficial Functionally Obsolete	N
Unofficial Sufficiency Rating	99.6
Routine Inspection Date	09/16/2015
Routine Inspection Frequency	24
Inspector Name	County, Ramsey
Status	A - Open

NBI CONDITION RATINGS	
Deck	7 - Good Condition
Unsound Deck %	
Superstructure	7 - Good Condition
Substructure	7 - Good Condition
Channel	N - Not Applicable
Culvert	N - Not Applicable

NBI APPRAISAL RATINGS	
Structure Evaluation 7	
Deck Geometry 7	
Underclearances N	
Water Adequacy N - Not Applicable	
Approach Alignment 7 - Better than present minir	

SAFETY FEATURES	
Bridge Railing	1 - MEETS STANDARDS
GR Transition	1 - MEETS STANDARDS
Appr. Guardrail	1 - MEETS STANDARDS
GR Termini	1 - MEETS STANDARDS

IN DEPTH INSP.		
	Y/N	Date
Frac. Critical		
Underwater		
Pinned Asbly.		
Spec. Feat.		

WATERWAY			
Drainage Area (sq. mi.)			
Waterway Opening	sq. ft.		
Navigation Control	N - Not applicable, no waterw		
Pier Protection			
Nav. Clr. (ft.)	Vert.	ft.	Horiz. ft.
Nav. Vert. Lift Bridge Clear. (ft.)			
MN Scour Code	A - NON WATER'	Year	

CAPACITY RATINGS		
Design Load	9 - HS 25 (OR GREATER)	
Operating Rating	1 - LF (LF)	HS 45.0
Inventory Rating	1 - LF (LF)	HS 25.0
Posting VEH:	SEMI:	DBL:
Rating Date 10/29/1992		

MnDOT Permit Codes	
A:	N - N/A
B:	N - N/A
C:	N - N/A

MnDOT Structure Inventory Report

Additional Roadways

Bridge ID: 62563

CSAH 23(CR C) over REC TRAIL

Date: 12/08/2015

MnDOT BRIDGE INSPECTION REPORT

12/08/2015

Inspector: County, Ramsey

BRIDGE 62563 CSAH 23(CR C) OVER REC TRAIL

ROUTINE INSP. DATE: 09/16/2015

County: Ramsey	Location: 0.6 MI E OF JCT TH 61	Length: 51.8 ft.
City: Maplewood	Route: 04 - CSAH 23 Ref. Pt.: 007+00.685	Deck Width: 52.8 ft.
Township:	Control Section:	Rdwy. Area/ Pct. Unsnd: 2282 sq. ft. / %
Section: 10 Township: 029N Range: 22W Maint. Area:		Paint Area/ Pct. Unsnd: sq. ft. / %
Span Type: 1 - Concrete 01 - Slab	Local Agency Bridge Nbr.:	Culvert: N/A
List:		Postings:
NBI Deck: 7 Super: 7 Sub: 7 Chan: N Culv: N	Open, Posted, Closed: A - Open	
	MN Scour Code: A - NON WATERWAY	
Appraisal Ratings - Approach: 7 Waterway: N		Unofficial Structurally Deficient N
Required Bridge Signs - Load Posting: 0 - Not Required	Traffic: 0 - Not Required	Unofficial Functionally Obsolete N
Horizontal: 0 - Not Required	Vertical: N - Not Applicable	Unofficial Sufficiency Rating 99.6

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
215	Reinforced Concrete Abutment	2	Routine	09/16/2015	108 LF	0	97	11	0	N/A
			Routine	09/19/2013	108 LF	0	97	11	0	N/A

Requires Monitoring Monitored

Notes: There are 4 moderate 1" - 2" spalls w/ rust present on the NE corner of east abutment 2015.
 The south end of east abutment has 3' moderate horizontal crack up by the SE corner of parapet -2013-2015.
 The south end of west abutment has 2' minor horizontal crack up by the SW corner of parapet - 2013-2015.
 There is a full height crack on both abutments at construction joints 2011-2015.
 The west abutment has minor spalls present 2009-2015.
 Debris on both abutments - need to be cleaned for further inspection.
 There is graffiti on the west abutment 2005-2015.
 There is minor vertical cracking of backwall of west abutment at SW corner 2007-2015.
 There are 4-14' minor vertical cracks on west abutment and 5-14' minor vertical cracks on east abutment + 5 LF of horizontal cracking east abutment for a total of 131 LF of cracks 2009-2015.
 The north 1/2 of east abutment contains alligator cracks. The east abutment contains spalls with re-bar corrosion present @ SE & NE corners 2007-2015.
 There is moderate - major horizontal cracking of backwall of east abutment at SE corner 2007-2015.
 Also SW corner of west abutment.
 Minor area of cracking with spalls present. 7' vertical crack @ SE corner + 2-14' vertical cracks on east abutment and 3-14' vertical cracks on west abutment for a total of 77 LF of vertical cracks 2001-2015.

[2007-2009] 10% in condition state 3.

300	Strip Seal Deck Joint	2	Routine	09/16/2015	108 LF	0	108	0	N/A	N/A
			Routine	09/19/2013	108 LF	0	108	0	N/A	N/A

Requires Monitoring Monitored

Notes: Expansion device should be cleaned & flushed for inspection. Some leakage is present with debris in joints 2001-2015.

310	Elastomeric (Expansion) Bearing	2	Routine	09/16/2015	16 EA	0	16	0	N/A	N/A
			Routine	09/19/2013	16 EA	0	16	0	N/A	N/A

Requires Monitoring Monitored

Notes: Minor deterioration of elastomeric bearings. Debris around assemblies. Need to be cleaned for further inspection.
 Alignment is within tolerance 2009-2015.
 No deterioration. Quantity was changed to 16 each 2003-2013.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
321	Concrete Approach Slab-Concrete Wearing Surface	2	Routine	09/16/2015	2 EA	0	2	0	0	N/A
			Routine	09/19/2013	2 EA	0	2	0	0	N/A

 Requires Monitoring Monitored

Notes: There are 74 LF of longitudinal cracking in the west approach slab & 58 LF of longitudinal cracking in the east approach slab 2011-2015.

Cracks are unsealed minor- moderate 2015.

There are 65 LF of longitudinal cracking in the west approach slab & 54 LF of longitudinal cracking in the east approach slab 2009-2015.

Cracks are unsealed minor- moderate 2015.

There are 45 LF of longitudinal cracking in the west approach slab & 42 LF of longitudinal cracking in the east approach slab 2005-2007.

Slight movement at NW corner. Bit approach roadway needs patching at both approach slabs. 2003-2011.

Some deterioration at both ends of approach panels due to settlement of bit. approach roadway 2009-2011.

There is deterioration of hot poured joints @ approach slabs both sides 2003-2011.

The west approach has been diamond ground shortly after construction.

333	Masonry, Other or Combination Material Railing	2	Routine	09/16/2015	236 LF	0	236	0	N/A	N/A
			Routine	09/19/2013	236 LF	0	236	0	N/A	N/A

 Requires Monitoring Monitored

Notes: The south rail has 10 vertical cracks full height 2015.

The north rail has 15 vertical cracks full height. The south rail has 9 vertical cracks full height 2013-2015.

Paint is peeling on north railing - 2013-2015

Minor - moderate numerous vertical cracking and spalling both sides 2003-2015.

The north rail has 10 vertical cracks full height. The south rail has 8 vertical cracks full height 2011-2015.

There is some chalking of the galvanized metal railing 2011-2015.

Railing is Type "F" with ornamental galvanized

359	Underside of Concrete Deck Smart Flag	1	Routine	09/16/2015	1 EA	0	1	0	0	0
			Routine	09/19/2013	1 EA	0	1	0	0	0

 Requires Monitoring Monitored

Notes: 1' of re-bar corrosion present in center of deck (under 2% of total deck area) - 2013-2015

There is minor cracking at the south fascia. There are numerous minor cracks with efflorescence at north fascia 2009-2015.

There are some voids at centerline east end due to consolidation problem during construction 2007-2015.

Minor cracking with minor spalling present 2005-2007.

378	Low Slump O/L (Concrete Slab with Epoxy Rebar)	2	Routine	09/16/2015	2734 SF	0	2734	0	0	0
			Routine	09/19/2013	2734 SF	0	2734	0	0	0

 Requires Monitoring Monitored

Notes: Minor hairline cracking & spalls less than 2% of total deck area. 100% of concrete slab is in condition state 2 2009-2015.

There is some diagonal cracking @ NE corner. There is shrinkage cracking WB between the wheel tracks 2007-2015.

Some minor but numerous longitudinal cracking with spalls present 2009-2013.

Some minor but numerous longitudinal cracking is present but no spalls 2001-2007.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
387	Reinforced Concrete Wingwall	2	Routine	09/16/2015	4 EA	0	4	0	0	N/A
			Routine	09/19/2013	4 EA	0	4	0	0	N/A

 Requires Monitoring Monitored

Notes: Minor cracking and spalls on all wingwalls 2015.
The NE wingwall has a 10' mior - moderate horizontal crack 2001-2015.

964	Critical Finding Smart Flag	2	Routine	09/16/2015	1 EA	1	0	N/A	N/A	N/A
			Routine	09/19/2013	1 EA	1	0	N/A	N/A	N/A

 Requires Monitoring Monitored

Notes: DO NOT DELETE THIS CRITICAL FINDING SMART FLAG.

981	Signing	2	Routine	09/16/2015	1 EA	1	0	0	0	0
			Routine	09/19/2013	1 EA	1	0	0	0	0

 Requires Monitoring Monitored

Notes: Horizontal clearance signs are in place 2013-2015.
Horizontal clearance signs are in place 2011. Element added 2011.

982	Approach Guardrail	2	Routine	09/16/2015	1 EA	0	1	0	N/A	N/A
			Routine	09/19/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Minor damage to guardrail system - 2013-2015
Minor damage to guardrail system - 2011
There is no crash attenuator @ SW corner 2007-2011. Not required due to low speed as per MNDOT.
Guardrail is in place and functioning 2003-2005.

984	Deck & Approach Drainage	2	Routine	09/16/2015	1 EA	1	0	0	N/A	N/A
			Routine	09/19/2013	1 EA	1	0	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Water runs off the bridge. No problems 2005-2015.

986	Curb & Sidewalk	2	Routine	09/16/2015	1 EA	0	1	0	N/A	N/A
			Routine	09/19/2013	1 EA	0	1	0	N/A	N/A

 Requires Monitoring Monitored

Notes: Expansion plate @ SE corner has been repaired - 2015
Expansion plate @ SE corner was damaged by snow plow & needs to be fastened to walk - 2013
Expansion plate @ SE corner is sticking up and should be bent downward 2005-2011. Debris needs to be cleaned out at expansion plate 2011.
Curb & sidewalk has significant cracking and spalling 2009-2015.
Slight settlement of sidewalk at SW corner 2005-2015.
Expansion plate @ SE corner is OK, must have been repaired 2009.
Curb has exposed aggregate on north side 2001-2011.

Structure Unit:

ELEM NBR	ELEMENT NAME	ENV	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QTY CS 5
-------------	--------------	-----	-------------	------------	----------	-------------	-------------	-------------	-------------	-------------

General Notes: 2015 Bridge safety inspection was conducted by Dan Bodelson on 9/16/15.
 2013 Bridge safety inspection was conducted by Dan Bodelson & Brian Essler on 9/18/13.
 2011 Bridge safety inspection was conducted by B. Wieman and D. Bodelson on 9/23/2011.
 2009 Inspection was completed by B. Wieman 9/21/2009.
 2007 Inspection was completed by B. Wieman and B. Essler 8/08/2007.
 2005 Inspection was completed by Bret Wieman 9/8/2005.
 Railroad tracks were removed in 1988.

58. Deck NBI: Minor hairline cracking & spalls

36A. Brdg Railings NBI: Vehicular railings meet currant standards

36B. Transitions NBI: Guardrail transitions meet current standards

36C. Appr Guardrail NBI: Approach guardrail meets currant standards

36D. Appr Guardrail
Terminal NBI: Guardrail terminations meet current standards

59. Superstructure NBI: Minor cracking & delamination

60. Substructure NBI: Minor cracking in abutments

61. Channel NBI:

62. Culvert NBI:

71. Waterway Adeq NBI:

72. Appr Roadway Alignment NBI: no speed recuction required

Inventory Notes:

Dan Bodelson

Inspector's Signature

Kathy Jaschke

Reviewer's Signature

Pictures



Photo 1 -



Photo 2 -

Pictures



Photo 3 -



Photo 4 -

Pictures



Photo 5 -



Photo 6 -

Pictures



Photo 7 -



Photo 8 -

Pictures



Photo 9 -



1. Crack in SE Parapet.JPG



2. Crack in SW Parapet.JPG



3. Looking East.JPG



4. Looking North.JPG



5. Looking South.JPG




6. Looking West.JPG



7. North Side 2.JPG



8. North Side.JPG



9. South Side.JPG

Channel

Bridge No.: 62563

Channel

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Channel Overall:	NBI Item 61	N	

Bank Protection/Revetment

<i>Item</i>	<i>Description</i>	<i>Condition</i>	<i>Comments</i>
Upstream Bank Protection:	_____	_____	_____
Downstream Bank Protection:	_____	_____	_____
Bridge Revetment:	_____	_____	_____
MnDOT Scour Code:	A - NON WATERWAY	_____	_____

Underwater Inspection

Underwater Inspection By Divers: _____

No. of Piers To Be Inspected: _____

Waterway Characteristics

Reference Point:	_____	High Water Elev.:	_____	Current Water Elev.:	_____
Pile Tip Elev.:	_____	Low Water Elev.:	_____	Current Streambed Elev.:	_____
		Scour Hole Elev.:	_____	Current Scour Hole Elev.:	_____

Waterway Inspection: (Not applicable for culverts)

Item No.	Yes, No, NA or Not Visible	Description
1.	_____	Is there a significant build-up of debris?
2.	_____	Is there a change in the horizontal alignment of the handrail or structure members such as beams?
3.	_____	Is there any indication of vertical movement of the superstructure?
4.	_____	Is there shifting of the channel alignment or erosion of the stream banks? Also are there cracks in the soil of the banks parallel to the stream?
5.	_____	Is there a significant change in the alignment of the exterior bearings?
6.	_____	Are there cracks or other signs of distress in the approach pavement?
7.	_____	Is the water currently on the superstructure?
8.	_____	Are the slopes unstable?
9.	_____	Do scour measurements indicate: (place a check by all that apply.)
	<input type="checkbox"/>	A. that the streambed is two or more feet below the bottom of pier footings which are supported on piles?
	<input type="checkbox"/>	B. scour below the bottom of spread footings?
	<input type="checkbox"/>	C. scour below the bottom of high abutment footings?
	<input type="checkbox"/>	D. that the streambed has scoured five feet or more below the original streambed elevation at pier bents?

10. _____ Have the scour countermeasures been damaged or otherwise made ineffective?

Notes:

- Streambed sounding data is to be documented.

- Per MnDOT Bridge Inspection Manual Section 2.2.5, at bridges that require x-sections, take channel x-sections, along the upstream and/or downstream face of the bridge.

- If "Yes" is the answer to any items on the checklist, notify the Program Administrator for further instructions.

Comments:

Completed On _____ By _____

Scour POA

Bridge No.: 62563

Scour POA

1. Is POA on File? _____
2. Date of most recent POA: _____
3. Here is a link to MnDOT's Bridge Scour website for other resources:
 - <http://www.dot.state.mn.us/bridge/hydraulics/scour.html>
 - The Scour POA should be kept in the bridge file and/or uploaded to SIMS using the "Inspection Files" tab.

Implementation

Scour POAs are required to be implemented by FHWA.

1. Is this POA being implemented? _____

Channel Section

Upstream

Custom Label	Location	Elevation
--------------	----------	-----------

Downstream

Custom Label	Location	Elevation
--------------	----------	-----------

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Comments:

Distance Measured From:

Elev. of Ref. Pt:

Depth to Water Surface:

WS Elev:

Vertical Datum:

Maintenance

Element	Source Code	Work Code	Description	P/R	Priority	Work Order #	Year Due	Last Viewed	Entered	Start Date	Completed
---------	-------------	-----------	-------------	-----	----------	--------------	----------	-------------	---------	------------	-----------



BRIDGE STRUCTURAL ASSESSMENT REPORT

PURPOSE:

This report is a structural assessment of the structure and its ability to carry loads based on conditions identified in the attached bridge inspection report. The assessment is only a cursory review intended to provide guidance as to the relative hazards for structural conditions and deficiencies identified. This report is mandatory for all fracture critical bridges and is completed by the MnDOT Bridge Office upon receipt of the 7 Day FC Report; however, it is an OPTIONAL tool for agencies to utilize at their discretion for all other inspection types.

BRIDGE NO.: 62563	BRIDGE OWNER: County Highway Agency
DATE INSPECTED: 09/16/2015	STRUCTURE TYPE: Concrete Slab
FACILITY CARRIED: CSAH 23(CR C)	FEATURES INTERSECTED: REC TRAIL
TYPE OF INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> FRACTURE CRITICAL <input type="checkbox"/> PINNED ASSEMBLY: <input type="checkbox"/> SPECIAL: <input type="checkbox"/> DAMAGE: <input type="checkbox"/> OTHER:	
<u>Check all that apply:</u>	
Redundancy: <input type="checkbox"/> Load Path <input type="checkbox"/> Structural <input type="checkbox"/> Internal	Connection Type: <input type="checkbox"/> Riveted <input type="checkbox"/> Bolted <input type="checkbox"/> Welded <input type="checkbox"/> Other:

1. Was a critical finding identified during this inspection or upon structural review? Yes No
 - a) If selected "Yes" above, state briefly the finding(s):

2. If a critical finding was identified, what is the current status? Pending
 Resolved
 N/A
 - a) Briefly state actions taken:

3. Does the condition of any bridge component indicate impaired function? Examples of bridge components with impaired function include elements that are: frozen or immovable, out-of-plumb or misaligned, distorted or structurally deformed, excessively deteriorated, cracked, broken, eroded or scoured. Yes No

a) If selected "Yes" above, state briefly the component(s) and condition(s):

4. Does the overall condition of the bridge, or any of its components mentioned in Question 3, suggest the need for detailed structural analysis and/or a revised load rating? Yes No

a) If selected "Yes", state the reason for this recommendation and indicate a proposed timeframe in accordance with State of Minnesota Rule 8810.9500 (Subpart 2):

5. Based on the structural assessment of these findings, recommendations include:

- Repair/Maintenance Monitoring Plan
 Other Increased Inspection Frequency

Explain recommended actions:

6. Other comments:

Bridge Office Reviewer