The 1991 published coordinates for 178E are in error, verify traverse in this area before using

See left