

MONUMENT 291

Fixed the Center of Section 32 by intersection and set monument, December 31, 1900.

Found 1 1/2 in. diameter iron, down 0.4 ft. in old concrete pavement; placed a cast iron cap and 3 in. bolt monument in concrete, flush, May 24, 1974. (Origin of iron monument is unknown).

Tied monument, August 13, 1975.

Retied monument, January, 1983.

Cast iron cap monument gone. Found 1.5 in. diameter iron down +/-0.3 ft. and tied, December 3, 1998.

Retied 1.5 in. diameter iron monument, August 29, 2006.

Retied 2 in. diameter solid iron monument, down 0.4 ft., September 7, 2011.