MONUMENT 293

CERTIFICATE OF LOCATION OF SECTION SUBDIVISION MONUMENT

Center of Section 33, Township 30 North, Range 22 West, County of Ramsey, State

of Minnesota.	
At the corner location shown on the sketch On September 30, 2011 found a cast iron monument, down 1.0 ft.	
On	
☐ raised/lowered	monument removed monument (explain)
□ On placed a	
SKETCH OF REFERENCE TIES	
LABORE WILLOW LAKE DRIVE	
Pameey Co. Surveyor	
$0 \longrightarrow X \longrightarrow $	
E. BERWOOD AVE. Link Fence 1.5 ft.	
Nail and Ramsey	
5/8 in. Re-bar with \ 16 in. Pine \ 28 in Poplar	
cap at back of curb	
77	6 in. spike in Co. disk in 12 in. Pine 1 10 in. Pine
RAMSEY COUNTY	up 1.5 ft. up 2 ft. S43*44'08"E
RAMSEY COUNTY NAD83 (1986)	47.51 — — — — — — — — — — — — — — — — — — —
MONUMENT 293	
X= 584553.471 (Easting) Y= 192046.352 (Northing)	ALL DISTANCES ARE SHOWN IN U.S. SURVEY FEET. BEARINGS ARE FOR TIE REFERENCE PURPOSES ONLY.
Statements of evidence relative to this corner are on the following page.	
I hereby certify that this document was prepared OFFICE OF COUNTY SURVEYOR	
by me or under my direct supervision and that I am	County of Ramsey
a duly Licensed Land Surveyor under the laws of the State of Minnesota.	I hereby certify that this document was filed in the
	County Surveyor's office this day of, 20
Daniel D. Baar Date	
Minnesota License No. 45816	
☐ County Surveyor☐ Land Surveyor	Craig W. Hinzman, L.S. Ramsey County Surveyor
2 - spass, stame, states, st	Rainsey County Surveyor

MONUMENT 293

Fixed the Center of Section 33 by intersection and set monument, November 20, 1900.

Granite okay, October, 1939.

Found a cast iron monument, tipped, April, 1974. (Research is unable to determine the origin of the cast iron monument).

Straightened monument, with information from M.W. Carley Eng. and Frank Kavidera (County Highway Department); tied, May 9, 1974.

Found a cast iron monument, top missing; replaced and tied, post 1 ft. north, November 5, 1981.

Found a cast iron monument using old ties; retied, June 26, 1991.

Set a sign and post +/-4 ft. north of monument, September 19, 1996.

Retied monument, October, 1999.

Monument in good stable condition. No additional ties taken; monument is approximately 70 ft. west of drainage ditch, August 29, 2006.

Retied a cast iron monument, down +/- 1 ft. in side slope, September 30, 2011.