

MONUMENT 435

The Center of Section 15 was fixed by intersection, set monument 1896.

Found railroad spike flush. Dug 2 ft. and found nothing. Placed a cast iron monument and tied, September 6, 1974.

Found all 3 reference monuments; Southeasterly and Southwesterly monuments broken off, September 16, 1974.

Construction destroyed monument and reference monuments; placed a P.K. nail and tied, November 21, 1983.

Set a 20 in. cast iron monument, 1984.

Tied monument, October 19, 2000.

Retied monument, August 2, 2006.

Retied cast iron monument, down +/-0.05 ft., June 9, 2011.