MONUMENT 507

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 26, Township 29 North, Range 22 West, County of Ramsey, State of Minnesota.

At th	ne corr	ner location shown on t	he sketch						
⊠ ()ո <u>J</u> ւ	une 8, 2011	found <u>a c</u>	ast iron	monument with t	he top broken off, v	within a cast iron wate	<u>r</u>	
,	valve a	assembly box.							
		☐ left monument as found	☐ raised/lowered monument ☐ removed monument (explain)						
	On		_ placed a _					_	
								_	
SKETCH OF RE					EFERENCE TIES				
4			IJ I	0					
			Sidewall	ROAD					
		NI 21	[3.1 I						
\wedge		Cou	and Ramsey	SHT					
			er pole, 2.0 ft.	McKNIGHT					
		Pun	ch mark top	N13.57.32"					
		nut	ch mark top of hydrant 19'24"W	5/3		Dun ah ya sa	ul. kan		
			19 24 W 15	\2", \X		Punch mai nut of hyd			
		Concrete Sidewalk		, <		N77·31'38"E	- X		
					AVENUE SSS Nail and Ramsey				
	MARYLAND								
			, (S)	$\langle \hat{\zeta}_{\hat{Q}} \rangle$	55,330 × N	ail and Ramsey			
			and Ramsey 267 ty disk in	Path	V, p	ounty disk in ower pole,			
RAIV	ISEY C		r/light pole,	minous	u	p 3.0 ft.			
	83 (19	986)	o 11.	Bitumi					
		MENT 507		-					
X= 597882.079 (Easting) Y= 168200.240 (Northing)					ALL DISTANCES ARE SHOWN IN U.S. SURVEY FEET. BEARINGS ARE FOR TIE REFERENCE PURPOSES ONLY.				
•	Statements of evidence relative to this corner are on the following page.								
П									
I hereby certify that this document was prepared by me or under my direct supervision and that I am					County of Ramsey				
a duly Licensed Land Surveyor under the laws of				I hereby certify that this document was filed in the					
the State of Minnesota.					County Surveyor's office this day of				
Daniel D. Baar Date									
Minnesota License No. 45816									
☐ County Surveyor☐ Land Surveyor					Craig W. Hinzman, L.S.				
☑ Deputy County Surveyor ☐ Land Surveyor					Ramsey County Surveyor				

MONUMENT 507

Set post Corner to Sections 23, 24, 25 and 26, Bur Oak 12 N15°E, 55, November 29, 1847.

Monument set by J.H. Armstrong, July 10, 1890 (City of St. Paul notes).

Tied granite monument, flush, February 2, 1934 (City of St. Paul notes).

Granite monument 0.3 ft. below bituminous surface, monument is in bad shape, April 4, 1972 (City of St. Paul notes).

Granite monument removed and cast iron monument set in concrete base to grade, April 21, 1972 (City of St. Paul notes).

Tied monument, down 0.27 ft., February 27, 1985.

Monument destroyed, Summer of 1987.

Re-established Corner position and set temporary P.K. nails; tied, December 28, 1987.

Set a 20 in. cast iron monument, October 27, 1988.

Tied monument, September 23, 1993.

Tied a cast iron monument at grade, March 8, 2001 (City of St. Paul).

Retied monument flush, April 14, 2003.

Retied monument, July 13, 2006.

Found broken cast iron monument, October 19, 2007 (City of St. Paul).

Placed casting over cast iron monument, January 28, 2008 (City of St. Paul).

Retied cast iron monument shaft; top is broken off, within a 8.5 in. diameter cast iron gate valve assembly box marked "WATER", June 8, 2011.