



2409.70

CROSBY ROAD

SANDY LAKE

18

2415.17

Mpls. ST. PAUL & S. STE. M.M. RY.

2627.92

ST

RICE

2631.40

2627.50

ST

MS. MENCHY

2643.60

BRICK SALOON

SHED

T.P. 88.95
4528
tel. p. T.P.

58.77 T.P.
45.11 T.P. pole

T.P. 52.00
T.P. 38.68
61.11 T.P. pole
1735 Stump

E.P. 46.87

66.30 E.P.

T.P. 13.80
706.40

40.74 T.P.

E.P. 78.72

tel. p. 32.14

Scrub Oak
51.06

18.67 03°

2410 E.P.

37' change

59.03 T.P.
25.78 Tal. Pole (6-1-22)
66.15 Poplar
6-1-22
Guy. Pole

1115.92

39.57 T.P.

85.87
48.0
E.P. 67.80 Stake.

102.58

1325.32

12.88
55.57
75.42

2632.46

Re. Est. 12/1/22

2626.37

17.30 E.P.

72.78

1313.18

89.02 T.P. (6-1-22)

61.48

6-1-22
Guy. Pole

T.P. 51.05
35.70

Hyd. 58.95

44.75
45.00

58.12

T.P. 57.92
53.05
Iron Sp. 15 up.

Guy. Pole

The South West Corner of Section 18 Fixed by City Engineer. No Monument

The South East Corner of Section 18 Fixed by City Engineer. No Monument

The North West Corner of Section 18 was fixed from old stake found on Rice St. and
Crosley Road and Monument set Apr 1895

The $\frac{1}{4}$ Corner between Sections 7 and 18 was fixed by Gates A. Johnson Jr in Nov. 1885
Set Monument 1895

The North East Corner of Section 18 was fixed by G. A. J. Jr. 1885 from Government witness
stump. No Set Monument 1895

The $\frac{1}{4}$ Corner between Section 18 T29 R22 and Section 13 T29 R23 was fixed from
old Lot and Block corners found in Wagner's Add Government witness. trees gone
Fixed corner tied it and set Monument March 1895

In Establishing the $\frac{1}{4}$ Corner between Sections 17 and 18 found some old ties and stake
Government witness trees gone Dec. 12 - 1898
Set Mont. Nov. 1899

Fixed the Centre of Section 18 by Intersection Sept 1 - 1900
Set Mont. Sept 1900