

N. 39° W.
B.T. 80.5"
40.92

45.54 Br. 0.8" B.T. N. 30° E.

10" Tam
6" W. 73.00
4.168

60.60 4' Scrub

18" W.O. 93.95

1/27/23
PRB.

Nail in P.P.

160.5

No ties

2653.08

Mon. 2' below
ground surface
with c. Jan 1914

2630.05

2634.53

30.6"
57.36

Jan 6" 118.92

Jan 4" 27.20

Jan 3"

Jan stump 10"

Jan 8"

2656.55

FP 34.91

FR 17.9

FR 27.81
FP 39.9

1/27/23
PRB.

100
61.03

Jan 6" 74.79

Jan 6"

100, 30 12"

2630.05

2634.53

BLACK
LAKE

TAMARACK
LAKE

fence post
4.410

Willow 18.54

FP 22.23

FP 26.4

1/27/23
PRB.

2656.5

2650.85

Gov tree
No. 55.45

52.98 270.

2830 Gov tree

44.59

111.90

Fence post

The South East corner of Section 9 was fixed from two Government witness trees
also found Iron stake at Section corner Retied it November 23 - 1897
Set monument June 30 1898.

The $\frac{1}{4}$ corner between Section 9 and 16 was fixed from old Government witness stump
also found old stake at $\frac{1}{4}$ corner Retied it November 22 1897
Set Monument June 30 1898

The South West corner of Section 9 was fixed by measuring West from $\frac{1}{4}$ corner between
Sections 9 & 16 the Government distance. no Government trees
fixed corner and tied it December 8 - 1897 Set monument June 30 - 98

In Establishing the N.E. corner of Section 9 found old stake at Section corner
no Government trees Feb 11 - 1902 Set Mont. Dec. 12 - 1902.

In Establishing the $\frac{1}{4}$ corner between Sections 9 and 10 Ran straight line from corner to corner
and fixed $\frac{1}{4}$ corner half way no Government trees Feb 13 - 1902
Set Mont. 500 ft. South Dec. 16 - 1902.

The $\frac{1}{2}$ Cor betw Sec 4 & 9 was fixed by measuring West from N.E. Cor Sec 9. Found old stake at $\frac{1}{2}$ Cor. no Gov
trees standing. Retied it Jan 26th 1910

The $\frac{1}{4}$ Cor. line of Sec 9 was fixed by running the N.E. $\frac{1}{4}$ line and the E & W $\frac{1}{4}$ line.
Retied it Jan 29th 1910