

For North West corner of Section 35 - see Section 34

For South West corner of Section 35 - see Section 34

For $\frac{1}{4}$ corner between Sections 34 and 35 see Sec. 34

The $\frac{1}{4}$ corner between Section 35 T 30 R 23 and Sec. 2 T 29 R 30 was fixed by J. H. Armstrong in Dec. - 1896 Set Monument Aug 6 - 1897

Meander corner No. 1 was fixed by J. H. Armstrong in Dec. 1896 Set Monument Aug 6 '97

The $\frac{1}{4}$ corner between Sections 26 and 35 was fixed by running a straight line which point comes 52.03 South of the South Rail of Rail Road track. No Government trees. July 26 - 1897 corner in Lake

The North East corner of Section 35 was fixed July 29 - 1897 Set Monument

In Establishing the $\frac{1}{4}$ corner between Sections 35 and 36 Found old stake. Government witness trees gone Fixed corner and tied it Aug 2 - 1897 - Set Monument

Fixed Meander corner No. 2. No Government trees. Aug 3 - 1897 - Set Monument

The South East corner of Section 35 was fixed Jan. 11 - 1898 in Lake Owasso

Fixed the centre of Sec. 35 by Intersection and set Monument: Nov. 24 - 1900.