

NORTH 1/4 COR. SEC. 17-30-22
 MONU. NO. 116

Found iron cemented in 4" iron pipe
 up 0.7 ft. Iron placed by Milner
 W. Carley & Assoc.. Tied to
 trav. point. 4-7-88

Found 4" iron pipe up 0.7 ft. Top
 rolled over, no iron or cement
 found, 4" pipe loose. Checked
 pipe location. Remove 4" pipe
 and set 20" C.I. flush. Set sign
 & post (0.4' W). 11-8-01

Tied monu. 11-15-01

RETIED MONT 2-23-05

Retied monu. 8-17-10

116

