

S.E. COR. SEC. 18, T30, R23
MONU. NO. 153

Found MH. at corner. Old ties
mostly gone. See "Survey Book
No. 1," pages 60 & 61 for location
determination.

Place two cast iron W.C. at 33
ft. W. & S. of true corner and
on line. Oct. 30, 1975.

Re-tied monu.'s Jan. 28, 1975.

Removed cast irons for construction. 4-89

Replaced both corners with 20" Cast Irons 7-3-90

Retied monu. 7-5-90

Retied. 12-2-98

RETIED S.O. WITNESS CORNER 11-10-04

FOUND W. WITNESS CORNER TIPPED

SET 6" SPK FOR TAMP LOCATION

RESET WEST WITNESS AFTER BEING FOUND

TIPPED, 11-15-04

RETICD BOTH WITNESS MONTS 4-26-07

Checked condition of both C.I.M's and ties 5-25-12

PLET
2080

