

NORTH 1/4 CORNER SEC. 5-30-22  
MONU. NO. 16 SP  
(16 SC)

Found R.R. spike over granite  
monu., down 0.7'. Drill hole  
larger in top and placed Cast  
Iron cap and bolt on top.

May 16, 1974 in concrete.

Retied July 3, 1974.

Found cap missing; monu.  
down 0.3 ft. 7-13-87

Replaced cap.

Tied monu. for const. removal. April 1990.

Removed C.I. cap. 5-7-90

Found broken granite down 18"!. Sept 5, 1990

Placed short C.I. (4<sup>5/8</sup>" ) in quick-set  
cement and rock. 10-30-90

Placed sign & post 5. 26'±. 10-16-91

Retied monu. 1-27-93

Placed 8" C.I. marked "3rd COR. LINE"  
in cement 0.31 ft. N. of closing  
corner (granite loc). 7-26-95

Tied 16 SP. 10-8-98

Tied June 25, 2004 \* RETIED loc, 9-23-09

