

5 1/4 COR. SECTION 14, T30, R22
MONU. No. 172

Found nothing. Placed cast
iron monu. as per Survey
Book No. 1, pages 56 & 57. Obtain-
ed ties from State Hwy Dept.
which checked. June 24, 1975.

Tied monu. 6-15-90
Retied monu.. 9-28-99
Cement added about monu. 5-24-00
RETIED 12-14-04

TIED OUT MONUMENT FOR REMOVAL
DURING SEWER/WATER AND SIDEWALK
RE CONSTRUCTION 6-28-07

RESET A SHORT (4 5/8") CAST IRON
FLUSH IN THE CONCRETE GUTTER
9-28-07

Tied monu 8-4-10

172

