

5 1/4 Cor. SEC. 19-30-22  
MONU. NO. 214

Found R.R. spike down 0.1 ft. 1975.  
Granite under spike, placed short  
cast iron. 1976.†

Tied monu. Aug. 3, 1981. Down 0.1 ft.  
Removed C.I. for maintenance to  
grind up road. 7-12-89

Reset pos. using ties 8-29-89  
Dug thru new asphalt, found  
granite app. .8' down.

set 4 1/2" C.I. mon. over granite  
in conc. 8-30-89

Retied monu. 5-1-90

Retied monu. & recemented. 6-10-98

RETICO MONT 3-14-05

Retied monu. 6-17-10

Look in back of book  
for 214N.

214

