

SOUTH 1/4 COR. SEC. 33-30-23  
MONU. NO. 306

Found cast iron monu. flush and  
re-tied Sept. 24, 1974.

Retied monu. Aug. 14, 1990

Retied monu. 7-16-02

Retied monu. 08-02-07

Top of monument broken, checked ties, set P.K.  
nail offsets. Removed broken cast iron. Found 6 in.  
spike down  $\frac{1}{2}$ -2 ft; spike was 0.07 ft S.S.W. of  
top of broken cast iron. Dig down  $\frac{1}{2}$ -4 ft, found  
nothing. 7-25-11

Set a 20 in. cast iron monument within a cast  
iron manhole assembly at position of center  
of broken cast iron shaft; tied 7-26-11

306

