

CENTER SECTION 5, T29, R23
MONU. No. 327

Found manhole at location; no ties
left. 1975

Placed 20" cast iron monu. 33.00
ft. East on line to E $\frac{1}{4}$ cor.
Sec. 5.

Tied monu. 5-16-90

Monu. down $1\frac{1}{2}$ " 9-28-94

Re-tied Monu. JBC SB DV 7/16/02

Re-tied monu. 08-02-07

Checked condition of C.I.M. down 0.2 ft
in bit. road, and it's fine. 6-7-12

