

5 1/4 COR. SEC. 5, T29, R23
 Monu. No. 350

Found nothing; re-established
 position from survey by Ray
 Wolfgram. Set C.I. monu. 8-15-75
 Destroyed by construction in 1979.
 Ties in section folder.

Replaced C.I. monu. and tied. 1981±
 Retied monu. 8-6-02
 Retied monument 7-1-09

