

SE COR. SECTION 12, T29, R23

MONU. No. 405

Found brass plug; dug 3', found nothing; set C.I. monu. 7-9-76.

Retied monu. 6-7-90

After const. by Minn DOT, found monu. with top missing. Set P.K. 9-29-92

Placed short 4 5/8" cast iron in conc. over broken C.I. 4-27-93.

Retied monu. 7-19-02

RETIED MONT 8-08-07

Tied out monument for removal during road reconstruction 5-24-10

Monument loose, removed 2-17-11

Set a 20 in. cast iron monument within a cast iron manhole assembly using construction ties; tied. 9-14-11

405

checked:
7-29-77

