

NORTH 1/4 COR. SEC. 17-29-22  
MONU. NO. 408

Found granite monu. down 0.3 ft.  
and re-tied. Sept. 10, 1974  
Placed cast iron cap and bolt in  
concrete. Sept. 11, 1974.

Removed cast iron cap. 6-15-90

Placed 4 5/8" (short) cast iron in Quick-set  
45 cement & re-tied. 10-26-90

Re-tied monu. 12-30-02

RETICED MONU. 8-09-07

Tied monument for removal during road reconstr.  
then removed short C.I.M.; found 6 in. x 6 in granite  
monument down ± 0.6 ft. 6-27-12

Placed C.I.M.H assembly over granite  
and tied. 8-23-12

408

179738.42  
579434.62  
MNDOT BM 6212K

