

WEST 1/4 COR. SEC. 18-29-22

MONU. NO. 428

Used old ties. Dug through top  
2" blacktop and found 3/4"  
dia. brass plug. Sept. 23, 1974.

Set Cast Iron cap & bolt. 6-1-76

Tied monu. 7-16-90

Found cast iron down 0.08'± after overlay  
and storm sewer by Minn DOT. 9-29-92

Retied monu. 7-19-02

monument CONC 8-07-07

DUG OUT HOLE WHERE MONUMENT WAS

FOUND GRANITE MONUMENT DOWN 4 INCHES.

CHECKED TIES AND 1/2 MILE DISTANCE TO  
THE SW CORNER OF SECTION 18, 29, 22.

FOUND SOME TIES THE SAME AND THE

1/2 MILE DISTANCE WITHIN 0.03 FT.

SET A CAST IRON CAP AND BOLT MONT

OVER GRANITE AND IN CONCRETE,

FLUSH WITH ROAD SURFACE. 8-16-07

Retied monu 8-22-07

Checked condition of monument and ties, found  
A.C.I.M. flush in bit lead stamped "QUARTER  
CORNER"  
7-31-12

Checked:  
7-29-77

