

S.E. COR. SECTION 17, T29, R23
 Monu. No. 443

Found iron flush. 6-22-76
 Const. Dept destroyed monu. in 4-97?
 Set 20" C.I.M. 14" ± below new conc.
 pavement. Contractor to place
 12" MH & pipe. 7-30-97
 Retied monu. 3-23-01
 RETIED MONU 9-05-07
 Found "Ramsay County" L.I.M. in L.I.M.H.
 assembly, checked condition of ties 10-3-12

