

SOUTH 1/4 COR. SEC. 13, T29, R23

Monu. No. 450

Found cast iron monu. 1976

Monu. down. 0.2'±; tied. 6-7-90

Retied monu. 7-19-02

RETIED MONU 8-06-07

Monument loose due to road milling; removed  
a 6 in. "ST PAUL CITY SURVEYOR" cast iron  
monument. Found a 2 in. diameter iron pipe  
under cast iron monument; tied. 7-22-11

Installed a cast iron manhole assembly  
over 2 in pipe (2 in pipe down 4.9 ft.) 7-25-11

Checked:  
8-12-77