

SOUTH 1/4 COR. SECTION 17, T29, R22
 Monu. No. 454

Found cast iron monu. 1974
 Cast iron down 0.15'±. Tied 5-10-90.
 Retied monu. 7-8-02
 RETIBO MONT 8-22-07

Checked condition of monument and ties;
 tied C.I.M., down 0.25ft, for removal
 during watermain reconstruction, 6-27-02

Checked:
 8-12-77

