

S.E. COR. SECTION 17, T29, R22

Monu. No. 455

Found granite monu. 1974.
Granite not at top after Minn DOT
repaired S.T.H. 61 in 1988. Found
granite chopped off $0.8 \pm$ down;
relocated position from traverse
work and cemented in a $4 \frac{5}{8}$ "
short cast iron monu. 9-22-89

Tied mon. 6-8-90

Tied monument ^{top broken off} DOWN 0.3 ft. 06-16-09

See 455 E btwn 459 & 460

455

Checked:
8-12-77

