

N 1/4 CORNER SEC. 25, T29, R22  
MONU. No. 508

Found granite monu. 1975  
Destroyed by construction; replaced  
with cast iron.

Re-tied monu. Feb. 1985.

Retied monu. flush. 9-24-93

Retied monu. flush. 4-14-03

lowered castiron down and placed  
Manhole casting and Tube Assembly  
over castiron for Milling project. Needs

Retied monument. 6-11-09

