

WEST 1/4 COR. SEC. 36, T29, R22

MONU. No. 576

Found cast iron monu. flush. 5-8-75.

Tied monu. 6-8-90

Monu. destroyed by const. storm sewer.

Relocated point & set PK's. & tied.

Placed 4 5/8" cast iron monu. and placed
Quickset 45 cement. Nov. 20, 1991.

Retied. (flush). 4-15-03

Retied Monument 05-21-08

Found "Ramsay County" C.I.M. flush in
bit. road; checked condition of ties 5-13-13

