

SOUTH 1/4 COR. SEC. 4-30-22
 MONU. NO. 68

Found 1/4" bolt with nut 2' long
 down 0.3'. Found 8" R.R. spike
 down 1.0'. Found possible
 granite tipped at 45° angle down
 1.5'. Did not try to upright.
 Placed Cast Iron monu. in same
 place as 1/4" bolt. flush with
 pavement.

May 17, 1974

Retied

July 3, 1974

Monu. removed for Const Dept. 1989

Reset 20" C.I. flush, 11-24-92

Retied monu., 1-25-93

Retied monu., 11-15-99

RETIED MONT 7-12-04

RETIED MONUMENT 7-27-09

