

Replacement of SW Corner of
Section 13, T29, R23.

R.M. July 20, 1981
M.K.
K.R.


43

Triple
V = 89-52-25
S = 2631.578
D = 2631.506

Triple
V = 90-11-52
S = 2611.042
D = 2610.959

W 1/4 Cor.
Sec. 13-29-23

W 1/4 Cor.
Sec. 24-29-23



W 1/4 Cor. Sec. 13-29-23

Point (See Page 2)

Punch mark

817.65

139-46-48