


# EDGCUMBE FARMS

Scale; 1" = 100'

o Indicates Iron.

Surveyed by  
T. Milton Fowble



Description: The S. 10 acres of the E. 30 acres of the S. 1/2 of the N.W. 1/4 Sec. 15 T.28 N. R. 23 W.

#  
1670