

MONUMENT 342

In establishing the 1/4 Corner between Sections 3 and 4, ran straight line from Corner to Corner and prorated fixed Corner and set monument, November, 1899.

Note in the tie book stated "cast iron monument over granite monument, April, 1971", 1975.

Replaced cast iron monument after road construction using Minnesota Highway Department survey information report to replace it, October 16, 1975.

Monument checked, September 12, 1977.

Monument checked, February 8, 1984.

Tied monument, February 23, 1984.

Retied monument, found down +/-0.1 ft., March 16, 1993.

Retied monument, January 17, 2003.

Tied monument out for removal by road construction, August 16, 2007.

Reset a 20 inch cast iron monument within a 12 inch cast iron manhole assembly, September 6, 2007.

Tied monument, May 23, 2011.