



# MONUMENT 761

Fixed the Center of Section 24 by intersection, March, 1899.

Set monument, April 19, 1899.

Re-established Center of Section, October 28, 1933.

Bolt over drill hole of granite monument down 0.4 ft., March, 1967.

Found a bolt in surface of road, August 6, 1974.

Found a granite monument down 0.75 ft., placed iron on surface and tied, May 29, 1979.

Short cast iron monument removed for road maintenance during the Spring of 1992.

Dug and found a granite monument under new road surface, October 20, 1992.

Placed a cast iron monument (+/-12 in.) in concrete, October 23, 1992.

Tied monument, April 18, 2001.

Retied monument, September 7, 2006.

Retied cast iron monument down 0.1 ft. in bituminous roadway, May 31, 2011.