

MONUMENT 784

The Quarter Corner between Sections 24 and 25 was fixed, July 12, 1897.
No Government trees.

Found 3/4 in. iron in concrete (old notes state a monument down 1 ft.), August 6, 1974.

Found 1/2 in. iron pipe in concrete flush on Sterling Avenue South. Tied out iron pipe and removed it. Found an approximate 8 in. by 8 in. granite monument with drill hole, down +/-0.5 ft. below iron pipe. Replaced iron pipe with a Washington County cast iron monument, March 26, 1982 (Washington County notes).

Tied Washington County cast iron monument, February 20, 1985.

Checked ties, monument down 0.2 ft., January 13, 1987.

Retied monument, down +/-0.2 ft., April 17, 2001.

Retied monument, September 7, 2006.

Retied a cast iron monument, down 0.35 ft. in bituminous road, May 27, 2011.