

From N.E.
Cor. Blk 37
E.P. 46.87

66.36 E.P.

Ties 428 77 of 1/4 1/4 Cor.

tree
53.42

tree
38.57

0.64
T.P.

26627.50

ST
MEMENTO

2643.60

53.70
0.05
T.P.

66.15
Poplar

99.60
4221.04
T.P.

50.14
947.0

75.67
0.8'

1280.82

1317.65

88.56
0.12'

2635.30
40.85
T.P.

1317.65

V.P. 22.38

32.32
T.P.

2633.45
2633.45

CROSLY ROAD

ROAD
CANADA

LITTLE

26638.77

ST
EDGEWATER

1313.4

1313.4

47.0

13010'
53.97
S 61° 15' W

92.80
B.C. 10'
S 29° E
239° 6'

44.29
T.P.
45.82
E.P.

T.P. 57.20

59.03
T.P.

1309.34

0.20" 2618.68 0.20"

41.91 45.18 38.27
0.6'

1309.34

39.92
0.4'

2619.62

67.77
0.16'
44.67
T.P. #30

Base stone gate post

26226.80

70.22
32.68
E.P.

WISCONSIN CENTRAL RY

43.53
0.41

63.10
0.8'
42.24
0.4'

26627.90

ST
ARCADE

2630.50

Elec. Lt. Pole
42.15

89.49
tree
42.15
35.47
T.P.

BRICK 2609.00

90° 29 1/2'
0.4' 43.58

152.90
0.06'
76.54
0.08'

The South West Corner of Section 17 Fixed by City Engineer Monument

The South East Corner of Section 17 Fixed by City Engineer Monument

The Center of Section 17 was fixed by D.L. Curtice May 13-1891 and tied by D.L. Curtice

Made Survey of Road through Section 17 December 11 - 1896 see page 71

The $\frac{1}{4}$ Corner between Sections 8 and 17 was fixed in 1885 by Gates A. Johnson
and Monument set Retied and Reset Monument Aug 1896

The North West Corner of Section 17 was fixed in 1885 by Gates A. Johnson
when old Government witness tree was standing and Monument set.

The North East Corner of Section 17 was fixed from some old notes and Monument set.
Aug 1896

In Establishing the $\frac{1}{4}$ Corner between Sections 17 and 18 fixed from some old notes found
stake Government witness trees gone Dec 12-1898
Set Mont. Nov. 1899

In Establishing the $\frac{1}{4}$ Corner between Sections 16 and 17 fixed from some old notes
found old stake Government trees gone Dec 14 1898
Set Mont. Nov. 1899

Fixed the Center of Section 17 by Intersection Sept 6-1900
Set Mont Sept. 1900