

PLEASANT
LAKE

8

BLACK
LAKE

11.90
Fencepost

The South East corner of Section 8 was fixed by measuring West from $\frac{1}{4}$ corner between
Sections 9 and 16 the Government distance no Government trees
fixed corner and tied it December 8-1897 Set monument June 30-1898